

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS / 2016 / *School/w2/832*

Dated: *20* / 05 / 2016

FIRE SAFETY CERTIFICATE

Certified that the Virendra Public School located at 70, Timarpur Road, Delhi-110054 comprised of lower ground, ground and two upper floors and 01 store room at 2nd floor terrace owned/ occupied by the Virendra Public School Management, have complied with the fire prevention and safety requirements in accordance with requirements of circular issued by Director of Education letter no 3298-3398 dated 01.03.2011 and verified by the officer concerned of Fire Service on 27.04.2016 in the presence of Sh. Rakesh Kumar (Manager) and that the building/premises is fit for occupancy Group B Educational with effect from *20/05/16*..... for a period of three years, subject to compliance of the conditions mentioned below:

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

Issued on *20/05/16*..... at New Delhi

[Signature]
19/5
(Dr. G.C. Misra)

Director

Ph:-011-23414000
[Signature]

Copy to :-

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 54.
2. The Manager, Virendra Public School, 70, Timarpur Road, Delhi-110054.

N/6

INSPECTION REPORT

1. Name & address of the building : Virendera Public School, 70, Timarpur Road, Delhi-110054.
2. Type of Occupancy : Educational
3. Type of Case : New case (lower ground, Ground plus 03 upper floors)
4. Details of previous NOC : nil
5. Fire Safety directives letter No : Director of Education Circular dated 01.03.2011
6. Date of inspection : 27/04/2016 Lower ground, Ground and 02 upper Floors----School
7. Name of the Inspecting Officers : ADO (RN) 2nd floor terrace--- Mumty and 01 temp store room
8. Name and designation of officers from the building side : Mr Rakesh Kumar (Manager)
9. Year of Construction : 1977/1986
10. Applicant's letter No. : VPS/2016/238 dated 26.03.2016

Plot Area-4060 sqm Covered Area:2436 sq.m, class rooms -32 nos students---1060 nos

	Minimum Standards on fire prevention and fire safety U/R 33	Director of Education letter dated 01.03.2011	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	6m	9m	MR ✓
	• Gate width	4.5m	Directly accessible	MR ✓
	• Width of internal road	NA	NA	NA
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	• Upper Floors	02	G to U F—03 LG to G F--2	MR ✓
	• Basements	NA	NA	NA
	b. Width of staircases			
	• Upper Floors	1.50m	G to UF—1.60m, 1.40m & 1.20m LG to GF—1.60m & 1.20m	MR ✓
	• Basements	NA	NA	NA
	c. Protection of exits			
	• Fire check door	NA	NA	NA
	• Pressurization	NA	NA	NA
	d. No. of continuous staircases to terrace	NA	02	NA
	e. Width of Corridor	NA	NA	NA
	f. Door Size	1 m	1.0m	MR ✓

Rk

N/7

3	Compartmentation.			
	• Fire check door	NA	NA	NA
	• Sealing of electrical shafts	NA	NA	NA
	• Fire Rating of shaft door	NA	NA	NA
	• Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	NA
4	Smoke Management System.			
	• Basements	30 a/c per hour	NA	NA
	• Upper floors	12 a/c per hour	Natural Ventilated	MR ✓
5	Fire Extinguishers			
	• Total numbers	10 nos	p	MR ✓
	• Types	ABC/Co2	ABC—10nos	MR ✓
	• ISI marking	ISI Marked	Yes	MR ✓
6	First-Aid Hose Reels.			
	• Total numbers on each floor	01	PF	MR ✓
	• Length of hose reel hose	30m	P	MR ✓
	• Nozzle diameter	5mm	P	MR ✓
7	Automatic fire detection and alarming system.			
	• Type of detectors	NA	NA	NA
	• Location of Main Panel	NA	NA	NA
	• Location of Repeater Panel	NA	NA	NA
	• Alternate source of power	NA	NA	NA
	• Hooters' Location	NA	NA	NA
8	MOEFA			
9	Public Address System.			
10	Automatic Sprinkler System.			
	• Basement	NA	NA	NA
	• Upper Floor	NA	Provided at LG Floor	NA
	• Sprinkler above false ceiling	NA	NA	NA
11	Internal Hydrants			
	• Size of riser/down-comer	NA	NA	NA
	• Number of hydrants per floor	NA	NA	NA
	• Hose Box	NA	NA	NA

ML

2/8

12	Yard Hydrants.			
	<ul style="list-style-type: none"> Total number of hydrants Hose Box 	NA	NA	NA
13	Pumping Arrangements.			
	<ul style="list-style-type: none"> Ground Level <ul style="list-style-type: none"> Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/ Manual stopping Pump House Access 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	<ul style="list-style-type: none"> Terrace level <ul style="list-style-type: none"> Discharge of pump Head of the pump Power Supply Auto Starting of pump 	450lpm	450lpm	MR ✓
		40m	40m	MR
		R	P	MR
R		P	MR	
14	Captive Water Storage for fire fighting.			
	<ul style="list-style-type: none"> Underground tank capacity Draw-off connection Fire service inlet Access to tank 	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
	<ul style="list-style-type: none"> Overhead Tank capacity 	10,000 ltrs	P	MR ✓
15	Exit Signage.	R	P	MR ✓
16	Provision of Lifts.			
	<ul style="list-style-type: none"> Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.			
	<ul style="list-style-type: none"> Total Area Location 	N/A	N/A	N/A
		N/A	N/A	N/A


M


N/A

19	Fire Control Room			
	• Detector System Panel	N/A	N/A	N/A
	• Flow Switch Panel	N/A	N/A	N/A
	• PA System Panel	N/A	N/A	N/A
	• Batter backup	N/A	N/A	N/A
	• Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. 215 dated 21.01.2016.

Keeping in view the satisfactory compliance of the minimum standard on fire prevention and fire safety requirements as stipulated under the circular issued by Director of Education dated 01.03.2016, it is recommended to issue Fire Safety Certificate.


Signature of the Inspecting Officer
Name :- Rajesh Kumar
Designation:- ADO/RN




13/5/16

137/DCFO (2016)