## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001.

No. FE 10FS/NJ 2016/NO2/953

Dated: 8/6//6

## **FIRE SAFETY CERTIFICATE**

Issued on 8/6/20/6 at New Delhi by

(Vipin Kental) Chief Fire Officer New Delhi Zone

To,

The Manager, G.S Public School C-2 Janta Flat Kondli, Mayur Vihar Phase-III, Delhi -92.

Copy:-

The Dy. Director of Education, Govt.of Nct of Delhi, Anand Vihar, Delhi.

## **CONDITIONS:**

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 6. "The owner /occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form'J'[sub rule(1) of rule 37] along with a copy of this certificate,six months prior to its expiry"
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

1. Name & address of the building : G.S Public School at C-2Janta Flat Kondli, Mayur

Vihar Phase-III, Delhi -92.

2. Building is comprised of : Ground+one upper floor

3. Type of Occupancy : Educational

4. Type of Case : New

5. Details of Previous NOC letter: Nil

6. Fire Safety Circular No. : F16/Estate/CC/Fire Safety/2011/3298 to3398 dt

01/03/11

7. Date of Inspection : 02/06/2016

8. Name of the Inspecting officers: ADO R.K. Yadav

9. Name and designation of

Officer from the building side : Mr. Gyan Sagar (Manager)

10. Year of Construction : 2005

11. Applicant's letter No : Dated 26/05/2016

N	Minimum Standards on fire	Requirement	Provided at Site	Remarks		
Ο.	prevention and fire safety U/R33					
1	<u> </u>					
	Road width	06 Mtrs.	10 Mtrs.	MR		
	Gate width	N/A	N/A	N/A		
	Width of internal road	N/A	N/A	N/A		
2	Number, Width, Type and Arrangement of Exits					
	a. Number of Staircases					
	Upper Floor	01 Nos.	02 Nos.	MR		
	Basement	N/A	N/A	N/A		
	B. Width of Staircases					
	Upper Floor	1.5 M	1.20 m &1.0 m	MR		
	Basement	N/A	N/A	N/A		
	c. Protection of exits					
	Fire check door	N/A	N/A	N/A		
	<ul> <li>Pressurization</li> </ul>	N/A	N/A	N/A		
	e. No. of continuous staircases to	1 No.	1 No.	MR		
	terrace g. Width of Corridor	1.5 Mtrs	1.5 Mtrs	MR		
	h. Door Size	1.0 Mtrs	1.0 Mtrs	MR		
	Compartmentation.					
	Fire check door	N/A	N/A	N/A		
2	<ul> <li>Sealing of electrical shafts</li> </ul>	N/A	N/A	N/A		
	Fire rating of shaft door	N/A	N/A	N/A		
	Water curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
4	Smoke Management System.					
	Basement	N/A	N/A	N/A		
	Upper floor	N/A	N/A	N/A		
5.	Fire Extinguishers					
T.	Total numbers	4 Nos.	4 Nos.	MR		
	• types	ABC & Co2	ABC & Co2	MR		
	IS marking	ISI marked	ISI marked	MR		

6	First-aid-Hose Reels.					
	Total numbers of each floor  Length of hose reel hose  Nozzle diameter	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
7	Automatic fire detection and alarming system.					
	Type of detectors	N/A	N/A	N/A		
	Location of main panel	N/A	N/A	N/A		
	Location of repeater panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooter's location	N/A	N/A	N/A		
3	MOEFA	N/A	N/A	N/A		
9	Public address System.	N/A	N/A	N/A		
10	Automatic Sprinkler System.	N/A	N/A	N/A		
	Basement	N/A	N/A	N/A		
	upper floor	N/A	N/A	N/A		
	sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants	N/A	N/A	N/A		
	size of riser/down-comer	N/A	N/A	N/A		
	Number of hydrants per floor	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
12	Yard Hydrants.	N/A	N/A	N/A		
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13	Pumping Arrangements.	N/A	N/A	N/A		
	Ground Level	N/A	N/A	N/A		
	Discharge of main Pump	N/A	N/A	N/A		
	Head of Main Pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	Jockey pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	Standby pump out put	N/A	N/A	N/A		
	> Standby pump Head	N/A	N/A	N/A		
	<ul><li>Auto Starting /Manual stopping</li></ul>	N/A	N/A	N/A		
	> Pump House Access	N/A	N/A	N/A		
	Terrace Level	N/A	N/A	N/A		
	Discharge of pump	N/A	N/A	N/A		
	Head of the Pump	N/A	N/A	N/A		
	> Power supply	N/A	N/A	N/A		
	> Auto Starting of pump	N/A	N/A	N/A		
14	Captive Water Storage for Fire Fighting.	N/A	N/A	N/A		
	Underground tank capacity	N/A	N/A	N/A		
	Draw-off connection	N/A	N/A	N/A		
	> Fire service inlet	N/A	N/A	N/A		
	> Access to tank	N/A	N/A	N/A		
	Overhead Tank capacity	N/A	N/A	N/A		
15	Exit Signage.	N/A	N/A	N/A		

16	Provision of Lifts.	N/A	N/A	N/A
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication in lift car	N/A	N/A	N/A
3.57	Firemen's grounding switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.	- N/A	N/A	N/A
	Total area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
19	Fire Control Room	N/A	N/A	N/A
	Detector system panel	N/A	N/A	N/A
	Flow switch panel	N/A	N/A	N/A
	PA system panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
N. I	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A

The fire extinguishers provided in the building were tested/ checked and found functional at the time of inspection.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Signature of the Inspecting Officer

Name: R. K. Yadav Designation: ADO(LN)

Dy.CFO(Virender Singh)
Submitted for approval please.

Wrugh
3/61/16