GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

No. F.6/DFS/MS/GH/2016/956 ·

Dated:

7/6/16

FIRE SAFETY CERTIFICATE

Certified that the Hotel Intercity located at 17A/42, WEA, Karol Bagh, New Delhi-110005. Comprises of Basement, Ground floor + Four Upper floors, using basement as hall, Ground floor as reception and three guest rooms, first, second and third floor having seven, six and seven guest rooms respectively (Total 23 guest rooms), a pantry for staff and one staff room in temporary tin shed on terrace was granted NOC by this department vide letter No.F.6/DFS/MS/GH/2011/1522 dated 08-07-2011 in the name of Guest House Delhi Heart. Now the owner changed the name of guest house Delhi Heart to Hotel Intercity. The premises was re- inspected by the officer concerned of this department on 01-06-2016 in the presence of Sh. Rajkumar (G.M) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued on Holls at New Delhi by.

(Rajesh Panwar) Dy. Chief Fire Officer Ph. 011-23412025

Copy to:-

1. Sh. Rajkumar (G.M.), Hotel Intercity 17A/42, WEA, Karol Bagh, New Delhi-110005.

Condition for the validity of fire safety certificate

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all time. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.

2. Any loss of life or property due to non-functional fire safety measures shall be at the

responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

5. This fire safety certificate may not be treated in any case for regularization of unauthorized

construction, if any

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

	INSPECTION REPORT							
	INSPECTION REPORT Name & address of the building : Dethi Heart Guest House 17A/42, WEA , Tutue 1							
	Karol Bagn , New Delin - 110003							
	Type of Occupancy : Residential (G.H.) B+G+4 upper Floors total guest room. Type of Case : Renewal							
	4. Details of Previous NOC							
	5. Fire Safety directives letter No							
	Date of inspection : 01/06/2016							
	R. Name and designation of officers							
	From the building side : Sh. Rajkumar (General Manager)							
	9. Year of Construction : Before 2010							
	10. Applicant's letter No.		: Nil dated 31.05.2016					
No.	Minimum Standards on fire pr	evention	NBC/BBL	Provided at site	Remarks			
110.	and fire safety U/R 33		Requirement		MR/NMR			
	Access to building							
	Road width		Accessible	6 mtr	MR			
	Gate width		NA	NA	NA			
*	Width of internal road		NA	NA	NA			
- 44	Number, Width, Type & Arrai	ogement o	of Exits					
	a. Number of staircases	igement o	LAILS					
			One	One	MR, Old Case			
	Upper Floors			and the second second				
	Basements		Two	Two	MR Old Case			
	b. Width of staircases			11				
	II. Elan		125 cms	130 cms	MR			
	Upper Floor		125 cms	115 cms,135cm	MR, Old Case			
	Basements							
	c. Protection of exits		NA	NA	NA			
			NA NA		NA			
		Fire check door		NA	INA			
	 Pressurization d. No. of continuous staircases to 							
			One	One	MR			
	e. Width of Corridor		1.0 Mtr	1.30 Mtr	MR			
	c. Width of Corridor							
	f. Door Size		1.0.14	90cms X 230 cm	MR, Old Case			
	1. Door Size		1.0 Mtr.	9001118 A 230 CII	is IVIK, Old Case			
	Compartmentation			1	" E			
			NA	NA	NA			
		Co						
	Sealing of electrical share		NA	Sealed	MR			
	Fire Rating of shaft door		NA	NA	NA			
	Water Curtain		NA	NA	NA			
	Fire Dampers		NA	NA	NA			
ļ.	Smoke Management System		1 11 1	7				
ł.			20 A CDII	Exhaust fans are	MR			
	 Basements 		30 ACPH	provided	IVIIX			
			12 A CDI I	Natural	MR			
	 Upper floors 		12 ACPH	Ventilation				
5.	Fire Extinguishers				N. C.			
	 Total numbers 		02 at each floor	Provided	MR			
	 Types 		ABC, WCO2	Provided	MR			
	IS marking		ISI marked	ISI marked	MR			
(First-Aid Hose Reels		151 marked					
5.		floor	One	Provided	MR			
	Total numbers on each		30 m	Provided	MR			
	Length of hose reel hose		5 mm		MR			
	Nozzle diameter		Jillii	Provided	IVIK			

•	Automatic fire detection and alarming sys	NA	NA		NA	
	Type of detectors	NA NA	NA		NA	
	Location of Main Panel Advantage Panel	NA -			NA	
	Location of Repeater PanelAlternate source of power		NA NA		NA	
	Alternate source of power	NA	NA NA		NA	
	Hooters' Location	NA				
	MOEFA	Required	Provided		MR	
	Public Address System	Required	· Provided		MR	
0.	Automatic Sprinkler System	Dagwined	Provided		MR	
	Basement	Required NA	NA		NA	
	Ground Floor	NA	NA		NA	
	 Ground Floor Sprinkler above false ceiling 	IVA	1111			
1.	Internal Hydrants					
1.	Size of riser/down-comer	NA	NA		NA	
	Number of hydrants per floor	NA	NA	1	NA	
	Hose Box	NA	NA		NA	
2.	Yard Hydrants				La La	
	Total number of hydrants	NA	NA		NA	
	Hose Box	NA	NA		NA	
3.	Pumping Arrangements		-		_	
	Ground Level				274	
	Discharge of main Pump	NA	NA		NA	
	> Head of Main pump	NA	NA		NA	
	Number of main pumps	NA	NA		NA	
	Jockey Pump out putJockey pump head	NA	NA		NA	
	Standby Pump out put	NA	NA		NA	
	> Standby Pump Head	NA	NA		NA	
	> Auto Starting/Manual	NA	NA		NA	
	Stopping	NA	NA		NA	
	Pump House Access		-			
	Terrace level	450 LPM	450 LPM	MR	,Old Case	
	Discharge of pump	30 M	30 M		, Old Case	
	> Head of the pump	Required	Provided	17110	MR	
	Power SupplyAuto Starting of pump		NA		NA	
	Auto starting or pump	NA	INA		147.1	
14.	 Captive Water Storage for fire fighting Underground tank capacity 	NA	NA		NA	
	 Underground tank capacity Draw-off connection 	NA	NA		NA	
	> Fire service inlet	NA	NA		NA	
	> Access to tank	NA .	NA		NA	
	Overhead Tank capacity	5000 Ltr	5000 Ltr	MF	,Old Case	
		Required	Provided	1411	MR.	
15.	Exit Signage.	1			<u> </u>	
16.	Provision of Lifts.					
	Pressurization of Lift Shaft	NA	NA		NA	
	Pressurization of Lift lobby	NA	NA	3 3 5	NA	
	Communication In lift Car	Required	Provided		MR	
	 Fireman's Grounding Switch 	Required	Provided		MR	
	Lift Signage	Required	Provided		MR	
		Required	110,1000			

17.	Standby power supply	Required	Provided	MR
18.	Refuge Area.			
	> Total Area	NA	NA	NA
	> Location	NA	. NA	NA
19.	 Fire Control Room Detector System Panel Flow Switch Panel PA System Panel 	NA NA	NA NA	NA NA
	Batter backup	NA	NA	NA
	Success Suchap	NA	NA	NA
	Building Floor Plans	NA	NA	NA
20.	Special Fire Protection System for Protection of special Risks, if any:	NA	NA	NA

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection. The Guest House Building was issued NOC by this department vide Letter No F6/DFS/MS/GH/2011/1522 dated 08/07/2011 in the name of Guest House Delhi Heart. Now the owner of the Guest House changed the name of the Guest House Delhi Heart to Hotel Intercity

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS/GH/2011/1522 dated 08.07.2011 renewal under rule 35 of Delhi Fire Service Rules 2010, is recommended please.

Signature of Inspecting Off

Signature of Inspecting Officer

Name:- Rajesh Panwar

Name

Designation: - Dy. C.F.O (NDZ)

Designation

Minter Chi