GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

Fax: 011-23412593, Email: gargatul@hotmail.com, Ph.(011-26189168)

No. F.6/DFS/MS/EH/2016/ SZ/ 9 43

Dated: 07/06/16

FIRE SAFETY CERTIFICATE

Chief Fire Officer

Copy to: -

- 1. The DHO(South Zone), Office of Deputy Health Officer, M.C.D. Health Department South Zone, Green Park, New Delhi,
- 2. The Director, The Big Chill Café Pvt. Ltd. F-38, East of Kailash, New Delhi-110065.

Conditions for the validity of Fire Safety Certificate

- 1. All the Fire Safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
- 2. Building Sanctioning Authority may verify any deviation with regard to the construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- 3. The staff shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- 4. The Basement shall be used strictly as per the provisions of Building Bye Laws.
- 5. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

	1		INSPECTION RE	PORT		
		tame a address of the building	The Big Chill Café Restaurant at short no 100, 070, 070			
		1 Building Correction Late	, ==	TOW DONIII.		
		Building Comprised of	(3 B+G+ 7 uppe	er floors), (Restaurant is running	at ground 9	
		Turner of O				
		Typo of open	Assembly Building "D" Restaurant			
	4		Renewal			
		Details of previous NOC	F6/DFS/MS/EH/2013/308 dt 15.5.2013			
	6	Fire safety directives letter No	Nil			
	7	Date of inspection	30.5.2016	30.5.2016		
	8	Name of the inspecting Officers :	specting Officers : DCFO D.P. Bhardwaj & ADO D.B. Mukherjee			
	9	Name and designation of all	Mr. Irono (M			
	9	from the building side	Mr. Imran (Mana	ager),		
	NI THE	Year of construction				
	10					
		Applicant's letter No.	Nil dated 4.05.20	Nil dated 4.05.2016 (Old Case)		
-	11					
	S. N	O. Minimum Standards on fire prevention an fire safety U/R 33	d NBC Requireme	ent Provided at site		
+	1	0		1 Tovided at site	Remarks MR / NMR	
1		Access to building 1) Road width			INITA / INIVITA	
		2) Gate width	Required	10 Mtr Provided	MR	
		3) Width of internal road	N/A	N/A	N/A	
-	2		N/A	N/A	N/A	
		Number, width Type & arrangement of exit a. Number of staircases	ts		1.477	
		1. Upper floors				
		2. basements	2 Nos	Provided nearest by Rest. (Mal	I) MR	
1		b. Width of staircase	N/A	N/A	N/A	
		1. Upper floors	1.5 Mtrs	Provided	MR	
		2. basements	N/A	NIA		
		c. Protection of exits	13/7 (N/A	N/A	
		1. Fire check door				
		2. Pressurization	N/A	N/A	N/A	
		d. No. of continuous staircase to terrac	N/A	N/A	N/A	
		e. Width of corridor	N/A	N/A	N/A	
		£ D	IN/A	N/A Ground floor 1 00 0 1 100 10	N/A	
		f. Door size	2 Exit (Old Case)	Ground floor - 1.09 & 1.12 Mtr & 1st floor- 1.12 Mtr each Provided	IMP	
	3	Compartmentation.				
		1. Fire check door	Provided & Maintain by Mall			
		2 Sealing of electrical at at	Required	Provided	MR	
		3 Fire Bating of short de	Required N/A	Provided	MR	
		4 water curtoin	N/A	N/A	N/A	
		15 Fire demand	N/A	N/A	N/A	
_	4	Smoke Management system.	14/7 (N/A	N/A	
			30 a/c per hour	ALIA		
			12 a/c per hour	N/A	N/A	
		upper floors		Exhust Fans provided		
		Fire Extinguishers		Silv provided	MR	
		total numbers		0. N		
		Types		ADOGG	MR	
-		ISI marking	0.	V	MR	
				165	MR	

6	First-Aid Hose Reels.		Provided & Maintain	by Mall	
	total numbers on each floor	Required	Provided	MR	
	Length of Hose reel hose	30 Mtr	Provided	MR	
	Nozzle Diameter	5 MM	Provided	MR	
7	Automatic fire detection and alarming system:- Provided & Maintain by Mall				
	Type of detectors	Required	Provided	MR	
	location of Main Panel	Required	Mall Cantrol Room		
	location of Repeater panel	Required	Provided	MR	
	Alternate source of power	Required	Provided	MR	
	hooter's location	Requied	Provided	MR	
8	MOEFA		Provided & Maintain		
9	Public Address System.	Provided & Maintain by Mall			
10	Automatic Sprinkler System.	Provided & Maintain by Mall			
	basement	Required	Provided	MR	
	upper floors	Required	Provided	MR	
	sprinkler above false ceiling	Required	Provided	MR	
11	Internal Hydrants		Provided & Maintain		
	Size of riser/down-corner	150 mm	Provided	MR	
	Number of Hydrants per floor	1-15 Nos.	Provided	MR	
	hose Box	1-15 Nos.	Provided	MR	
12	Yard Hydrants.		Provided & Maintain		
	total number of hydrants	16 Nos	Provided	MR	
	hose box	16 Nos.	Provided	MR	
13	Pumping arrangements		Provided & Maintain		
	1. Ground level			by Man	
	a. Discharge of main Pump	4500 LPM	Provided	MR	
	b.Head of main pump	70 Mtr	Provided	MR	
	c.Number of main pumps	Two	Two	MR	
	d.jockey pump out put	180 LPM (2 Nos)	Provided	MR	
	e.jockey pump head	70 Mtr	Provided	MR	
	f. Standby Pump output	4500 LPM	Provided	MR	
	g.Stanby Pump head	70 Mtr	Provided	MR	
	h.Auto Starting/Manual stopping	Required	Provided	MR	
	pump house access	Required	Provided	MR	
	2.Terrace level	ricquired	1 Tovided	IVIN	
	a. Discharge of pump	N/A	N/A	N/A	
	b. head of the pump	N/A	N/A	N/A N/A	
	c. Power supply	N/A	N/A	N/A N/A	
	от опред	I V/ / \	IN/A	IN/A	
	d. Auto starting of pump	N/A	N/A	N/A	
14	Captive water storage for fire fighting	Provided & Maintain by Mall			
	1. Underground tank capacity	2,00,000 ltr	Provided	MR	
	a. Draw-off connection	Required	Provided	MR	
	b. fire service inlet	Required	Provided	MR	
	c.Access to tank	Required	Provided	MR	
	Over head tank Capacity	30,000 Ltr	Provided	MR	
15	Exit Signage.	Required	Provided	MR	
16	Provision of lifts.	Provided & Maintain by Mall			
	a. Pressurization of lift shaft	Required	Provided	MR	
	b. pressurization of lift lobby	Required	Provided	MR	
	c. communication in lift car	Required	Provided	MR	
	d. Fireman's grounding switch	Required	Provided	MR	
	e. Lift signage	Required	Provided	MR	

	Standby power supply	Provided & Maintain by Mall Provided & Maintain by Mall			
10	Refuge Area.				
	total area	N/A	N/A	N/A	
	location	N/A	N/A	N/A	
19	Fire control room	Provided & Maintain by Mall			
	a. detector system Panel	Required	Provided	MR	
	b. Flow switch Panel	Required	Provided	MR	
	c. PA system Panel	Required	Provided	MR	
	d. Batter backup	Required	Provided	MR	
	e. Building floor plans	Required	Provided	MR	
	Special Fire Protection systems for	Required	Provided	MR	
20	protection of special risks, if any:				

This department has issued fire safety certificate vide letter no. F6/DFS/MS/Mall/ 2015/SZ/1954

dated 30.10.2015 for mall.

The fire protection systems provided in the building were checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules of NOC issued vide letter no.**F6/DFS/MS/EH/2013/308 dt 15.5.2013** renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Accordingly DFA is put up for your approval and signature please.

Signature of the Inspecting Officer

Name D.P. BHARDWAJ Designation:- DY. CFO

Signature of the Inspecting Officer

Name

D.B. Mukherjee

1/6/2016

Designation:- A.D.O. (BCP)

Cfo. Afal Gorg

DIRECTOR OF