GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

E-mail: gargatul@hotmail.com, Tel:- 011-26189168

No. F.6/DFS/MS/School/2016/ 9 75

Dated: 08/06/16

FIRE SAFETY CERTIFICATE

Certified that M/s. Institution for the Blind Andh Vidyalaya located at Amar Colony, Lajpat Nagar-IV, New Delhi-110024 comprised of ground plus one upper floor was granted Fire Safety Certificate by this department vide F.6/DFS/MS/School/2012/2002 dated 31/05/2012. The school building was re-inspected by the officer concerned of this department on 31/05/2016 in presence of Mr. Sohan Singh, office incharge and found that the said School building have deemed complied with the fire prevention and fire safety requirements in accordance with the Directorate of Education circular No. F.6/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011 and that the school building is fit for occupancy class "Educational" with effect from the date of issue of this certificate for a period of three years, subject to compliance of the under mentioned conditions.

Issued on ___68/06/16__ at New Delhi by.

CHIEF FIRE OFFICER

Copy to: -

1. The Office Incharge, M/s. Institution for the Blind Andh Vidyalaya, Amar Colony, Lajpat Nagar-IV, New Delhi-110024.

2. The Director, Education, G.N.C.T. Delhi, Old Secretariat, Delhi.

Conditions for the Validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 5. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building : M/s. Institution for the Blind Andh Vidyalaya, Amar

Colony, Lajpat Nagar-IV, New Delhi-110024.

1. Type of Occupancy : Educational

2. Type of Case : Renewal

3. Details of previous NOC : F.6/DFS/MS/School/2012/2002 dated 31/05/2012

4. Fire Safety directives letter No : F.6/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011

5. Date of inspection : 31.05.2016

6. Name of the Inspecting Officers : M.K.Chattopadhyay, ADO (M.Rd)

7. Name and designation of officers

from the building side : Mr. Sohan Singh, Office Incharge

9. Year of Construction : 1986

10. Applicant's letter No. : nil dated 25.05.2016.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Directorate of Education circular		Provided at s	ite Remarks MR/NMR	
1	Access to building					
	Road widthGate width	06 mts Old case	Pro	ovided ovided	MR MR	
	Width of internal road	N/A	N/A	A	N/A	
2	Number, Width, Type & Arrangement	of Exits		in the state of th		
*	a. Number of staircases					
	Upper Floors	03 Nos.		Provided	MR	
	Basements	N/A		N/A	N/A	
	b. Width of staircases					
	Upper Floors	1.5 mts or less & 0.75 mt		1.50, 1.04, 1.0 mts	MR	
	Basements	N/A		N/A	N/A	
	c. Protection of exits				× 1	
	Fire check door	N/A		N/A	N/A	
	 Pressurization 	N/A		N/A	N/A	
	e. No. of continuous staircases to terrace	01		Provided (01)	MR	
Y	g. Width of Corridor	N/A		N/A	N/A	
	h. Door Size	1.0 mts		Provided (1.0 mt)	MR	
	Compartmentation.			- 12 L- 2		
	Fire check door	N/A		N/A	N/A	
	Sealing of electrical shafts	N/A N/A N/A		N/A	N/A	
	Fire Rating of shaft door			N/A	N/A	
	Water Curtain			N/A	N/A	
	• Fire Dampers	N/A	10	N/A	N/A	
	Smoke Management System.		MATE			

	Upper floors	12 a/c per hour	Natural Ventilation	MR		
5	Fire Extinguishers					
	Total numbers	10 nos.	Provided	MR		
	• Types	ABC & CO ₂ type	Provided	MR		
	IS marking	ISI marked	Provided	MR		
6	First-Aid Hose Reels.					
1116	 Total numbers on each floor 		N/A	N/A		
	 Length of hose reel hose 	30 m	N/A	N/A		
	Nozzle diameter	5 mm	N/A	N/A		
7	Automatic fire detection and alarming	system Not	required			
	Type of detectors	N/A	N/A	N/A		
	Location of Main Panel	N/A	N/A	N/A		
	Location of Repeater Panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooters' Location	N/A	N/A	N/A		
8	MOEFA	N/A	N/A	N/A		
9	Public Address System.	Required Provided		MR		
10	Automatic Sprinkler System	Not require				
	Basement	N/A	N/A	N/A		
	Upper Floor	N/A	N/A	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants Not re	quired				
	Size of riser/down-comer	N/A	N/A	N/A		
	Number of hydrants per floor	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
12	Yard Hydrants. Not required					
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13	Pumping Arrangements Not required					
	Ground Level					
	Discharge of main Pump	N/A	N/A	N/A		
	➤ Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
225 To T	Jockey Pump out put	N/A	N/A	N/A		
	> Jockey pump head	N/A	N/A	N/A		
	> Standby Pump out put	27/4	DT/A	27/4		

	Auto Starting/ Manual stopping	N/A	N/A	N/A
	Pump House Access	N/A	N/A	N/A
	Terrace level			
	Discharge of pump	N/A	N/A	N/A
	Head of the pumpPower SupplyAuto Starting of pump	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
14	Captive Water Storage for firefighting		Not required	
	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	> Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	Not Applica	able	
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.		2	-1
	> Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
19	Fire Control Room			
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Batter backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	01 ABC type fire extinguisher is provided near elect. Panel.	MR

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

dated 31/05/2012, renewal under the Directorate of Education circular No. F.6/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011 is recommended.

DFA is put up for approval & signature please

DCFO (D.P. Bhardwaj)

/ 2/ 6/16

cfo. Atul Gar

DIRECTORIOR

Name (M.K. CHATTOPADHYAY)
Assistant Divisional Officer (MRD)

or A square of the filette