## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001 Fax: 23412593, Email:gargatul@hotmail.com, Tel:- 011-26189168

No. F6/MS/DFS/EH/SZ/2016/ 1017

Dated: 10/6 /16

## FIRE SAFETY CERTIFICATE

Certified that the Nandos's (Unit of Janpath Restaurant India Pvt. Ltd.), located at 315 & 316, Plot no.3, Promenade Mall, Vasant Kunj New Delhi. comprised of 2 tier basement, ground & 02 upper floors but the restaurant is running at second floor was granted FSC by this department vide letter no. F6/DFS/MS/EH/2012/4261 Dated: 14/11/2012. The premises were re-inspected by the officer concerned of this department on 03/06/2016 in the presence of Mr. and observed that the said restaurant have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Group-D (Restaurant) with effect from. [C. [. A. ]]. Solution. For a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

(ATUL GARG) CHIEF FIRE OFFICER

ore try ADO(BLD)

Copy to:

- 1) The Dy. Health Officer South Zone, SDMC, Green Park, New Delhi
- Nandos's (Unit of Janpath Restaurant India Pvt. Ltd.),
   315 & 316, Plot no.3, Promenade Mall,
   Vasant Kunj New Delhi

## Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. The basement shall be used as per the provisions of BBL.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

## **INSPECTION REPORT**

- 1. Name & address of the building:- Nandos's (Unit of Janpath Restaurant India Pvt. Ltd.),315 & 316, Plot no.3, Promenade Mall, Vasant Kunj, New Delhi.
- 2. Type of occupancy:- Assembly, Group D, Restaurant
- 3. Type of case:-Renewal
- Details of previous NOC:-F6/DFS/MS/EH/2012/4261 dated 14/11/2012
- 5. Fire safety directives No.- Nil
- 6. Date of inspection: 02/06/2016
- 7. Name of the inspecting officer: D.B.Mukherjee, A.D.O.(BCP)
- 8. Name & designation of officer From the building side:- Mr. Sharma
- 9. Year of construction:- Not known
- 10. Applicant's letter no:- DHO/SZ/2016/D/362 dated: 12/05/2016
- 11. Composition of the Building: 2 tier basement, Lower Ground, Upper Ground, First Floor and Projection Room. floors.

Restaurant is running at 2nd floor (1st Floor as per Fire NOC)

(OLD CASE)

SI.	Minimum Standards on fire Prevention and fire safety U/R 33	BBL/NBC Requirement	Provided at site	Remarks MR/NMR		
1.	Access to Building					
1.	1) Road width	10 mtr	Provided 16 m	MR		
	2) Gate width	N/A	N/A	N/A		
	3)Width of internal road	N/A	N/A	N/A		
	Number, Width Type & Arrangement of Exits					
•	A Number of staircases					
	1. Upper floors	Required	Provided by Mall	MR		
	2. Basements	N/A	N/A	N/A		
	B. Width of staircase					
	1. Upper floors	1.5m	1.5m	MR		
	2. Basements	N/A	N/A	N/A		
	C. Protection of exits					
	1. Fire check door	N/A	N/A	N/A		
	2. Pressurization	N/A	N/A	N/A		
	D. No. of continuous staircase to terrace	N/A	N/A	N/A		
	E. Width of corridor	N/A	N/A	N/A		
	F. Door size	2m	2nos. of door	MR		
3.	Compartmentation					
).	1) Fire check door	N/A	N/A	N/A		
	2) Sealing of electrical shafts	N/A	N/A	N/A		
	2) Sealing of electrical sharts	N/A	N/A	N/A		
	3) Fire rating of shaft door	N/A	N/A	N/A		
	4) Water curtain	N/A	N/A	N/A		
	5) Fire Dampers N/A N/A N/A  Smoke Management System :Provided and maintained by mall					
4	1) Basements	30 a/c per hour	N/A	N/A		
_		12 a/c per hour	Exhaust Fan	MR		
	2) Upper floors 12 a/c per nour Exhaust Fair  Fire Extinguishers					
5.	1) Total numbers	ISI Marked	04 nos.	MR		
			ABC, Co2	MR		
	2) Types 3) ISI marking		Yes	MR		
	First-Aid Hose Reel	Provided and maintained by mall				
6.	1) Total number of each floor	01	Provided	MR		
	2) Length of hose reel hose	30 m	Provided	MR		
	3) Nozzle diameter	5 mm	Provided	MR		

7.	Automatic Fire Detection & Alarming System		Provided and maintained by mall			
	1) Type of detectors	Required	Provided Smoke	MR		
	2) Location of main panel	Required	1 <sup>st</sup> basement	MR		
	3) Location of repeater panel	Required	Basement	MR		
	4) Alternate source of power	Required	DG Set	MR		
	5) Hooter's Location	Every Floor	Provided	MR		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	Provided and	maintained by mall	and processors		
10.	Automatic Sprinkler System Provided and maintained by mall					
	1) Basement	N/A	N/A	N/A		
	2) Upper floors	Required	Provided	MR		
	3) Sprinkler above false ceiling	N/A	N/A	N/A		
11.	Internal Hydrants Provided and maintained by mall					
	1) Size of riser/down-comer	150 mm.	Provided	MR		
	2) Number of hydrants per floor	03	Provided	MR		
	3) Hose box	03	Provided	MR		
12.	Yard Hydrants		maintained by mall	IVIIC		
	1) Total number of hydrants	07	Provided	MR		
	2) Hose box	07	Provided	MR		
13.	Pumping Arrangement Provided and maintained by mall					
100000	1) Ground level		J RANGE	T		
	a) Discharge of main pump	4500 lpm	Provided	MR		
	b) Head of main pump	70m	70m	MR		
	c) Number of main pump	02	Provided	MR		
	d) Jockey pump out put	180 lpm	Provided	MR		
	e) Jockey pump head	70m	70m	MR		
	f) Stand by pump output	4500 lpm	Provided Diesel Engine	MR		
	g) Stand by pump head	70m	70m	MR		
	h) Auto starting/Manual stopping	Required	Provided	MR		
	2) Terrace level	The Control of the Co		1,11		
	a) Discharge of pump	N/A	N/A	N/A		
	b) Head of pump	N/A	N/A	N/A		
	c) Power supply	N/A	N/A	N/A		
	d) Auto starting of pump	N/A	N/A	N/A		
14.	Captive Water Storage for Fire Fighting		d maintained by mall	- 1/4 A		
	Underground tank capacity	460KL	Provided.	MR		
	a) Draw-off connection	Required	Provided	MR		
	b) Fire service inlet	Required	Provided	MR		
	c) Access to tank	Required	Provided	MR		
	d) Over head tank capacity	30000 ltrs.	Provided	MR		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts. Provided and maintained by mall					
	a) Pressurization of lift shaft	Required	Provided	MR		
	b) Pressurization of lift lobby	Required	Provided	MR		
	c) Communication in lift car	Required	Provided	MR		
	d) Fireman's switch	Required	Provided	MR		
	e) Lift signage	Required	Provided	MR		
17.	Standby Power Supply	Required	Provided D.G. Sets			
	111	required	Trovided D.O. Sets	IVIIV		
18.	Refuge Area	27/4	127/1	T		
-	Total area	N/A	N/A	N/A		

	location	N/A	N/A	N/A		
19.	Fire Control Room	Provided and n	Provided and maintained by Mall			
	a) Detector system panel	Required	Provided	MR		
	b) Flow switch panel	Required	Provided	MR		
	c) PA system panel	Required	Provided	MR		
	d) Battery backup	Required	Provided	MR		
	e) Building floor plan	Required	Provided	MR		
20.		Protection System for Protection of special Risk, if any:				

The fire protection system provided in the building were checked and found functional at the time of inspection. The mall has been issued FSC vide letter no. F6/DFS/MS/SZ/2014/SZ/881, dated: 17/07/2014.

In view of the compliance of the minimum standards on fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F6/DFS/MS/EH/2012/4261 Dated: 14/11/2012, renewal under rules 35 of the Delhi Fire Service Rules 2010 is recommended.

Accordingly DFA is put up please.

Signature of the inspecting officer

Name: D.B. Mukherjee.

1616

Designation: - Assistant Divisional Officer(BCP)

cfo.

Puty fi

A/V/ 1/6/10