GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6/DFS/MS/2016/School/w2/1120

Dated: 9 /7 /2016

FIRE SAFETY CERTIFICATE

Certified that the Ryan International School located at plot no. G-2, Sec-11, Rohini, Delhi-110085 comprised of ground and two upper floors owned/ occupied by the Ryan International School have complied with the fire prevention and safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on 29.06.2016 in the presence of Sh. Robert Gill (Principal) and that the building/premises is fit for occupancy Class Group B Educational with effect from 2/2/16 for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety-arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry'.

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

Issued on Shift at New Delhi

Chief Fire Officer Ph:-011-23414250

Copy to:-

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 54.

2. The Principal, Ryan International School located at plot no. G-2, Sec-11, Rohini, Delhi-110085.

4/10

		SPECT	ION REPORT		
1 2	,	(G +02 Floors)			
3	Type of Case	: New (Case		
4	Details of previous NOC	:Nil			
5	Fire Safety directives letter No	: NBC	: NBC Part 4/ Director of Education letter dated 01.03.2011		
6.	Date of inspection	: 29/06/2016			
7.	Name of the Inspecting Officers	: Rajesh Kumar, ADO (RN)			
8.	Name and designation of officers				
	from the building side	: Sh. Re	obert Gill		
9.	Year of Construction	: 2004			
10	. Applicant's letter No.	: Nil da	nted 23.06.2016		ac a
			qm, No of student-	—960 nos, Total c	lass room24nos
	Minimum Standards on fire prevention fire safety U/R 33		NBC Requirement	Provided at site	Remarks MR/NMR
1	Access to building			a .	
	Road width		6m	9m (approx)	MR
	Gate width		4.5m	4.5m	MR
	 Width of internal road 		NA	NA	NA
2	Number, Width, Type & Arrangement	of Exits	1474		,,,,
	a. Number of staircases				
	Upper Floors		02	02	MR
	Basements				
	b. Width of staircases		NA	NA	NA NA
	Upper Floors		1.50 m	1.55cm & 160 cm	MR
	• Basements		NA	NA	NA
	c. Protection of exits		NA	NA	NA
	Fire check door		NA	NA	NA
	 Pressurization 		NA	Olno	NA
	d. No. of continuous staircases to terrace		NA	NA	NA
	e. Width of Corridor f. Door Size		1.0m	1.0m	MR
3	Compartmentation.			<u> </u>	
,			NA	NA	NA
	Fire check doorSealing of electrical shafts		NA	NA	NA
	Searing of electrical sharts				



	Fire Rating of shaft door	NA	NA	NA	
	Water Curtain	NA	NA	NA	
	• Fire Dampers	NA	NA	NA	
4	Smoke Management System.		*		
	Basements	30 a/c per hour	No basement	NA	
	Upper floors	12 a/c per hour	Natural Ventilated	MR	
5	Fire Extinguishers	Ewi	I Technology		
	Total numbers	8nos	13 nos (6 -2 kg & 07-	MR	
	• Types	ABC/Co2	5 kg) ABC13	MR	
	ISI marking	Yes	Yes	MR	
6	First-Aid Hose Reels.				
	Total numbers on each floor	01	P & F	MR	
	• Length of hose reel hose	30 m	Р	MR	
	Nozzle diameter	5mm	- P	MR	
7	Automatic fire detection and alarming system	m	-		
	Type of detectors	NA	NA	NA	
	Location of Main Panel	NA	NA	NA	
	Location of Repeater Panel	NA	NA	NA	
	Alternate source of power	NA	NA	NA	
	Hooters' Location	NA	NA	NA	
8	MOEFA	NA	NA	NA	
9	Public Address System.	NA	NA	· NA	
10	Automatic Sprinkler System.				
	Basement	NA	NA	NA	
	Upper Floor	NA	NA	NA	
	Sprinkler above false ceiling	NA	NA	NA	
11	Internal Hydrants	NIA	01 DC system	NA	
	Size of riser/down-comer	NA	01 DC system	NA NA	
	Number of hydrants per floorHose Box	NA NA	01	NA NA	
12	Yard Hydrants.	1871	V1		
12		NA	NA NA	NA	
	Total number of hydrants	NA	NA	NA	
	Hose Box	IVA	14/4		
13	Pumping Arrangements.				
	Ground Level				

HILL

fle

	Discharge of main Pump	N/A	N/A	N/A
	➤ Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	N/Λ	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head Auto Starting/ Manual stopping	N/A	N/A	N/A
	Auto Starting/ Manual stoppingPump House Access	N/A	N/A	N/A
	Terrace level			
	Discharge of pump	450 lpm	450 lpm	MR
	Head of the pump	40m	Provided	MR
	Power Supply	Required	Provided	MR
	Auto Starting of pump	Required	Provided	MR
14	Captive Water Storage for fire fighting.	1		
	Underground tank capacity	NA	NA	NA
	> Draw-off connection	NA	NA	NA
	Fire service inlet	NA	NA	NA
	Access to tank	NA	NA	, NA
	Overhead Tank capacity	10,000 ltr	10,000 ltr	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage .	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.		*	
	> Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
19	Fire Control Room	2		
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Batter backup	N/A	N/A	N7A



Building Floor Plans	N/A	N/A	N/A
Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. 1129 dated 04.05.2016.

Keeping in view the satisfactory compliance of the minimum standard on fire prevention and fire safety requirements as stipulated under the circular issued by Director of Education dated 01.03.2016/ NBC Part 4, it is recommended to issue Fire Safety Certificate.

41716

Signature of the Inspecting Officer Name: - Rajesh Kumar Designation: - ADO/RN

25.6.1

DYCEO (WZ)

FT PIS