## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS / 2016 / 1148

Dated: 15 /07/2016

## FIRE SAFETY CERTIFICATE

Certified that the Glorious Public School. Sec-9, Rohini, Delhi-110085 comprised of two blocks i.e. Ground plus two upper floors and Ground plus one floor owned/ occupied by Glorious Public School was granted NOC by this department vide letter No F 6 / DFS /MS /2010/2415 dated 18.08.2010. The premise was re-inspected by the officer concerned of this department on 01.07.2016 in the presence of Smt. Unmukta Aggarwal, Principal and observed that all the fire prevention and fire safety arrangements as provided in the premise found in good working condition and there is no additional construction. The premise have therefore deemed complied with the requirements under rule 33 of the Delhi Fire Service Rules, 2010 and the building premise is fit for occupancy under Educational "Group B" with effect from ..1 \$1.67.1.16... for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40, subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010,

## Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.Delhigovt.nic.in">www.dfs.Delhigovt.nic.in</a>

Chief Fire Officer Ph:-011-23414250

Copy to: -

- 1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi 110054.
- 2. The Principal, Glorious Public School, Sec-9, Rohini, Delhi-110085.

INSPECTION REPORT

1. Name & address of the building : Glorious Public School, Sec-9, Rohini, Delhi-110085.

(Ground +02 Floors & ground and first floor)

2. Type of Occupancy : Educational

3. Type of Case : Renewal

4. Details of previous NOC :F6/DFS/MS/2010/2415 dated 18.08.10

5. Fire Safety directives letter No : Director of Education Letter dated 17.01.2005

6. Date of inspection : 01/07/2016

7. Name of the Inspecting Officers : ADO (RN)

8. Name and designation of officers

from the building side : Ms. Unmukta Aggarwal/ Principal

9. Year of Construction : 2010

10. Applicant's letter No. : GPS/MISC-23-2016 dated 14.06.2016

	Minim	um Standards on fire prevention and fire safety U/R 33	Dir. Of Education circular dated 17.01.2005	Provided at site	Remarks MR/NMR		
	Access to building						
		Road width	6m	6m	MR ,		
	•	Gate width	4.5m	4.5m	MR		
	•	Width of internal road	NA	NA	NΛ		
	Number, Width, Type & Arrangement of Exits						
	a. Numb	er of staircases					
	•	Upper Floors	02 in each block	02 in each block	MR		
	•	Basements	NA	NA	NA		
	b. Width	of staircases					
	•	Upper Floors	1.50m	1.0m x02 0.85mx1, 0.90.x1	MR(Old case		
	•	Basements	NA	NΛ	NΛ		
is .	c. Protec	tion of exits					
	•	Fire check door	NA	NA	NA NA		
	•	Pressurization	NA	NA	NA		
	d. No. c	of continuous staircases to terrace	NA	NA	NA		
	e. Width	of Corridor .	NA	NA	NA		
	f. Door	Size	1.0m	1.0m	MR		

		11/11			
3	Compartmentation.				
	• Fire check door				
	<ul> <li>Sealing of electrical shafts</li> </ul>		NA	NA	
	Fire Rating of shaft door		NA	NA	N/
	Water Curtain		NA	NA	NA.
	• Fire Dampers		NA		NA
			NA	NA	NA
4 Sn	oke Management System.		1 1/-1	NA	NA
	Basements				
	• Upper floors	30 a/c p	per hour	No basement	
5		12 a/c p	er hour	Natural Ventilat	NA
	Fire Extinguishers			- Additar Ventilat	ed MR
	Total numbers	. 08	Bnos		
	Types	ABC/Co2		08 nos	MR
6 First	ISI marking			ABC8	MR
FIFSI-	Aid Hose Reels.	Y	es	Yes	MR
•	Total numbers on each floor	01			
•	<ul> <li>Length of hose reel hose</li> </ul>			Provided	MR
•	Nozzle diameter	30 m		Provided	1311
Autom	atic five dotage	5mm			MR
•	atic fire detection and alarming sys	tem		Provided	MR
		NA		NA	
	Location of Main Panel	NA		NA	NA
•	Location of Repeater Panel	NA		NA	NA
	Alternate source of power	NA			NA
	Tooters' Location	NA		NA	NA .
MOEFA		NA NA		NA	NA
Automasi	dress System.	NA NA		NA	NA
	Sprinkler System.			NA	NA
	asement	NA		N. I.	
	pper Floor	NA		NA	NA
• Sp	rinkler above false ceiling .	NA		NA	NA
Internal Hy		INA		NA	NA
• Siz	e of riser/down-comer	Required	D		
• Hos	nber of hydrants per floor	01		rovided ovided	MR
		Required		ovided	MR
				ovided	MR

2/12

12	Yard Hydrants.							
	Total number of hydrants	NA	NA	NA				
	Hose Box	NA	NA	NA				
3	Pumping Arrangements.							
	Ground Level							
	Discharge of main Pump	N/A	N/A	N/A				
	Head of Main pump	N/A	N/A					
	Number of main pumps			N/A				
	Jockey Pump out put	N/A	N/A	N/A				
	Jockey pump head	N/A	N/A	N/A				
	Standby Pump out put	N/A	N/A	N/A				
	Standby Pump Head	N/A	N/A	N/A				
	Auto Starting/ Manual stopping	». N/A	N/A	N/A				
	Pump House Access	N/A	N/A	N/A				
	Terrace level	4501pm	450 lpm	MR				
	Discharge of pump	40m	40m	MR				
	Head of the pump	Required	Provided	MR				
	Power Supply	Required	Provided	MR				
	Auto Starting of pump							
14	Captive Water Storage for fire fighting.							
	Underground tank capacity	NA	NA NA	NA				
	> Draw-off connection	NA	NA	NA				
	Fire service inlet	NA	NA	NA				
	Access to tank	NA	NΛ	NΛ				
	Overhead Tank capacity	10,000 ltr	10,000 ltr	MR				
15	Exit Signage.	Required	Provided	MR				
16	Provision of Lifts.		-					
	Pressurization of Lift Shaft	N/A	N/A	N/A				
	Pressurization of Lift lobby	N/A	N/A	N/A				
	Communication In lift Car	N/A	N/A	N/A				
	Fireman's Grounding Switch	N/A	N/A	N/A				
	Lift Signage		N/A	N/Λ				
		N/A		N/A				
17	Standby power supply	N/A	N/A	1N/FV				

M

> Total Area	N/A	N/A	N/A
► Location .	N/A	N/A	N/A
Fire Control Room			
Detector System Panel	N/A	N/A	N/A
Flow Switch Panel	N/A	N/A	N/A
PA System Panel	N/A	N/A	N/A
Batter backup	N/A	N/A	N/A
Building Floor Plans	N/A	N/A	. N/A
Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. 1432 dated 02.06.2016.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in director of education Circular dated 01.03.2011, it is recommended to renewal of fire safety certificate issued vide this department letter of even no. 2415 dated 18.08.2010 ground + two floors. Media

Signature of the Inspecting Officer Name: - Rajesh Kumar

Designation: - ADO/RN

J.7. 16 Ly cco (WZ) Cfo. west