GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS / 2016 / 11 0 0

Dated: 22/7/2016

FIRE SAFETY CERTIFICATE

Certified that the Tagore International Public School, Gali No. 6, Sangam Vihar, Wazirabad, Delhi-84 is comprised of ground and first floor owned/ occupied by the Tagore International Public School was granted FSC by this department vide letter No F 6 / DFS / MS /2008/2959 dated 27.10.2008. The premises was re-inspected by the officer concerned of this department on 11.07.2016 in the presence of Sh. M.P.Sharma, Manager and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy Group B Educational with effect from .22./.7.//6.... for a period of three years, subject to compliance of the conditions mentioned below:

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on

WWW.dfs.Delhigovt.nic.in

Issued on ... 2. 2. at New Delhi

Chief Fire Officer Ph:-011-23414250 OUN

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 54.

2. The Manager, Tagore International Public School, Gali No. 6, Sangam Vihar, Wazirabad, Delhi-84.

	-		INSPEC	CTION REPORT			
1.	1. Name & address of the building			: Tagore International Public School, Gali No. 6, Sangam Vihar,			
			Wazira	bad, Delhi-84(Groun	d+01 Floor)		
2.	Туре	of Occupancy	: Educational				
3.	Туре	of Case	: Renewal				
4.	Deta	ils of previous NOC	:F6/DFS/MS/2008/2959 dated 27.10.08				
5.	Fire	Safety directives letter No					
6.		of inspection	: 11/07/2016				
7.		e of the Inspecting Officers					
8.		e and designation of officers					
0.		the building side		1.P.Sharma, Manag	or.		
()		of Construction		i.i .siiaima, wamag			
				116060016			
	2.2	cant's letter No.		ated 16.06.2016			
Ple		400 Sqm Covered area400 rum Standards on fire preventi		No of student—200 nos Dir. Of Education	, Total class room -1 Provided at site	Remarks	
		fire safety U/R 33	on and	Dir. Of Education	Trovided at site	MR/NMR	
	Access	o building					
		Road width		6m	5m(old case)	MR	
		Gate width		4.5m	2m(old case)	MR	
		Width of internal road					
	NI.		. C.E! 60	NA	NA	- NA	
	Number, Width, Type & Arrangement of Exits						
	a. Numb	per of staircases					
	•	Upper Floors		01	02	MR	
	•	Basements		NA	NA	NA	
	b. Width	of staircases	3				
	•	Upper Floors		1.50 m	1.20m & 75 cm(old case)	MR	
	•	Basements		NA	NA	NA	
	c. Protec	ction of exits					
	٠	Fire check door		NA	NA	NA	
	•	Pressurization		NA	NA	NA	
		of continuous staircases to terrace		NA	NA	NA	
		of Corridor		NA	NA	NA	
	f. Door	Size		1.0m	1.0m	MR	

3	Compartmentation.						
	• Fire check door	NA	NA	XXX			
	 Sealing of electrical shafts 	NA	NA NA	NA			
	 Fire Rating of shaft door 	NA		NA			
	Water Curtain		NA	NA			
	Fire Dampers	NA	NA	NA			
	, , , ,	NA	NA	NA			
	Smoke Management System.						
	Basements	30 a/c per hour	No basement	NA			
	Upper floors	12 a/c per hour	Natural Ventilated	MR			
	Fire Extinguishers		racarar ventrated	IVIIX			
	Total numbers	4nos	4 nos				
	• Types	ABC/Co2	ABC4	MR			
	ISI marking			MR			
	First-Aid Hose Reels.	Yes	Yes	MR			
	Total numbers on each floor	01	Provided	MR			
	• Length of hose reel hose	30 m	30m	MR			
	 Nozzle diameter 	5mm	- 5mm	MR			
	Automatic fire detection and alarming system						
	Type of detectors	NA	NA .	NA			
	 Location of Main Panel 	NA	NA	NA			
	 Location of Repeater Panel 	NA	NA	NA			
	 Alternate source of power 	NA	NA	NA			
	 Hooters' Location 	NA	NA	NA			
	MOEFA	NA	NA	NA			
	Public Address System.	NA	NA NA	NA			
	Automatic Sprinkler System.						
	• Basement	NA	NA	NA			
	Upper Floor	NA	NA	NA			
	 Sprinkler above false ceiling 	NA	NA	NA			
	Internal Hydrants						
	Size of riser/down-comer	. NA	NA	NA			
	Number of hydrants per floorHose Box	NA	NA	NΛ			
	- HOSE DUX	NA	. NA	NΛ			

2	Yard H	ydrants.			NI A	
	•	Total number of hydrants	NA	NA	NA	
		Hose Box	NA	NA	NA	
13	Pumpii	ng Arrangements.				
	•	Ground Level				
		Discharge of main Pump	N/A	N/A	N/A	
		➢ Head of Main pump	N/A	N/A	N/A	
		Number of main pumps	N/A	N/A	· N/A	
		Jockey Pump out put			N/A	
		Jockey pump head	N/A	N/A	N/A	
		> Standby Pump out put	N/A	N/A		
		Standby Pump Head	N/A	N/A	N/A	
		Auto Starting/ Manual stopping	N/A	N/A	N/A N/A	
		> Pump House Access	N/A	N/A	N/A	
	,	Terrace level	Required	2201pm	MR	
		Discharge of pump	NA	NΛ	NA	
		Head of the pump	NA	NA	NA	
		Power Supply	NA NA	NA	NA	
		Auto Starting of pump				
14	Captive Water Storage for fire fighting.					
	•	Underground tank capacity	NA	NA	NA	
	1	Draw-off connection	NA	NA	NA	
	1	Fire service inlet	NA	NA	NA	
	>	Access to tank	NA	NA	NA	
		Overhead Tank capacity	Required	2500ltr	MR	
15	Exit S	ignage.	Required	Provided	MR	
16		ion of Lifts.				
10	•	Pressurization of Lift Shaft	N/A	N/A	N/A	
		Pressurization of Lift lobby	N/A	N/A	N/A	
	•	Communication In lift Car	N/A	N/A	N/A	
		Fireman's Grounding Switch	N/A	N/Λ	N/A	
		Lift Signage	N/A	N/A	N/A	
				N/A	N/A	
17	Stand	by power supply	N/A	1 8/7 3		

N/11

	Total Area	N/A	N/A	N/A	
	> Location	N/A	N/A	N/A	
19	Fire Control Room	<u> </u>			
	• _ Detector System Panel	N/A	N/A	N/A	
	• Flow Switch Panel	· N/A	N/A	N/A	
	PA System PanelBatter backup	N/A	N/A	N/A	
•	Building Floor Plans	N/A	N/A	N/A	
		N/A	N/A	N/A	
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A	
	8				

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. 1444 dated 03.06.2016.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in director of education Circular dated 01.03.2011, it is recommended to renewal of fire safety certificate issued vide this department letter of even no. 2959 dated 27.10.2008.

Signature of the Inspecting Officer Name: - Rajesh Kumar Designation: - ADO/RN

DOLNED - On leave

Dy CFofw 2

b wext hold o