FORM 'H'

FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI

HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

No: 6 | Ofs | ans | Hospital/2016/652 | 1198 FIRE SAFETY CERTIFICATE

Dated: 27/07/16

Certified that the building of Deep Chand Bandhu Hospital (Nurse Hostel) located at Kokiwala Bagh, Ashok Vihar, Phase - IV, New Delhi comprised of Basement, Ground plus Seven Upper Floors owned/ occupied by Delhi Administration have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010 and verified by the officers concerned of Fire Service on 29-06-2016 in the presence of Sh. S K Gupta (Assistant Engineer) PWD and that the building / premises is fit for the occupancy class "Residential" Group A Sub Division A-3 with effect from .2.7./57./1.6... for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on2.7./.6.7./.16... at New Delhi.

Chief Fire Officer Delhi Fire Service

Copy to:-

1. Sh. NS Khurana, Medical Superintendent, Deep Chand Bandhu Hospital, Kokiwala Bagh, Ashok Vihar - IV, New Delhi.

2. Executive Engineer (E), BPD (E), B – 241, 2nd Floor, MSO Building, New Delhi.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. The basement shall be used as per building bye laws.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

1. Name & address of the building: Deep Chand Bandhu Hospital located at Kokiwala Bagh, Ashok Vihar, New Delhi. (Hostel Block, B-1+B-2+G+7 upper floors)

2. Type of Occupancy

: Residential Cass A Sub DivisionA-3

3. Type of Case

: New

4. Details of previous NOC

: New

5. Fire Safety directives Letter No.: F6/DFS/MS/BP/Hospital/2007/2352 dated 24-08-2007

6. Date of inspection

: 29/06/2016

7. Name of the Inspecting Officer: Udaivir Singh, ADO (WP)

8. Name and designation of Officer

from the building side : Mr. S.K.Gupta (A.E.PWD)

9. Year of Construction

: 2012

10. Applicant's letter No. :32/11(3)/DCBH/2015/4035-39 dated-06/06/2016

S No	Minimum standards on fire prevention and fire safety U/R	NBC Requirements	Provided at site	Remarks MR/NMR
1.	Access of building Road width Gate width Width of internal road	9 m 6 m 6 m	Provided Provided Provided	MR MR MR
2.	 Number, width, Type & Arrange a. Number of staircases Upper floors Basements b. Width of staircases Upper floors Basements 	Hostel – 3stairs Total no-14 stairs 3 ramps Hostel-3x1.3 mtr 9 X2 m,5 X1.5 n Total no-14 stair Ramps- 2.3 mtr	Provided Provided	MR MR MR MR
	 c. Protection of exits Fire check door Pressurization d. No of continuous staircase to terrace e. Width Of Corridor f. Door Size 	NA Required 3 2 mtr 1 mtr	NA Provided Provided Provided Provided	NA MR MR MR MR



			P			
•	Compartmentation					
	Fire check door	Required	Provided	MR		
	Sealing of electrical shafts	Required	Provided	MR		
	Fire Rating of shaft door	Required	Provided	MR		
	Water Curtain	Required	Provided	MR		
	to the same countries assessment	Required	Provided	MR		
4	• Fire Dampers Smoke managements System	Teoquita				
4.	Basements	Required	Provided	MR		
		NA	NA	NA		
_	Upper floors Fire Fretin swighors	11/11	1112			
5.	Fire Extinguishers	28 nos.	Provided	MR		
	• Total numbers	ABC, WCO_2 ,	Provided	MR		
	• Types	CO_2	11011404	groot Selfer Still		
	IS marking	ISI marked	Provided	MR		
6.	First – Aid Hose Reels	0.2	D	MR		
	 Total numbers on each floor 	02	Provided			
	 Length of hose reel 	30 m	Provided	MR		
	hose	5 mm	Provided	MR		
	Nozzle diameter					
7.	Automatic fire detection and alarming system					
	Type of detectors	Smoke & Heat	Provided	MR		
	 Location of Main Panel 	Ground floor	Provided	MR		
	Location of Repeater Panel	Ground floor	Provided	MR		
	Alternate source of power	Required	Provided	MR		
	Hooters' Location	Required	Provided at strategic location	MR		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	Required	Provided	MR		
10.	Tubile Madress System					
	Basements	Required	Provided	MR		
	• Upper Floor	NA	NA	NA		
	Sprinkler above false ceiling	NA	NA	NA		
11.						
	Size of riser/down- comer	100 mm	Provided	MR		
	 Number of hydrants per floor 	02	Provided	MR		
		Required	Provided	MR		
10	Hose Box Vard Hydrants					
12.		14	Provided	MR		
	Total number of hydrantsHose Box	Hose Box	Provided	MR		



		TANK TE MAN			
Pum	ping Arrangements: Commo	n with Hospita			
	Ground Level	2220 1	Provided	MR	
	 Discharge of main 	2280 lpm	110 1100		
	pump	5 0	Provided	MR	
	> Head of main pump	70 mtrs	Provided	MR	
	Number of main pumps	2	Provided	MR	
	> Jockey pump out put	2x180 lpm	Provided	MR	
	> Tockey pump head	70 mtr	Provided	MR	
	Standby Pump out put	2280 lpm	Provided	MR	
	Standby Pump Head	70 mtrs		MR	
	> Auto Staring/Manual	Required	Provided	1,111	
	stopping		- 111	MR	
	> Pump House Access	Required	Provided	IVIIC	
	• Terrace level			MR	
	Discharge of pump	900 LPM	Provided	MR	
	> Head of the pump	40 mtr	Provided		
	> Power supply	Required	Provided	MR	
	> Auto starting of pump	Required	Provided	MR	
	Auto starting = 1		***		
4. C	aptive water Storage for fire f	lighting.		1 - 473	
	1	1,50,000 litro	Provided	MR	
	 Under ground tank 	1,50,000			
	capacity	Required	Provided	MR	
	> Draw off connection	Required	Provided	MR	
	> Fire service inlet	Required	Provided	MR	
	> Access to tank		1	MR	
	 Overhead Tank 	Nursing Ho	Ster		
	capacity	25,000 ltrs	Provided	MR	
15 J	Exit Signage	Required	Tiovided		
	Provision of Lifts			15	
10.			Provided	MR	
	Pressurization of Lift	Required	Provided		
	Shaft		Provided	MR	
	> Pressurization of lift	Required	Provided	1111	
	lobby		7 111	MR	7
	Communication in lit	Required	Provided	IVIIC	*
	Car		- 111	MR	
	> Fireman's Grounding	g Required	Provided	IVIIX	
	Switch			MR	
	Lift Signage	Required	Provided	IVIIX	
	Lift biging	- 1	Provided	MR	
17.	Standby power supply	Required	TTOVICE		
18.	Refuge Area		NA ·	NA	
10.	> Total area	NA		NA	
	> Location	NA	NA	1112	
10	1		7 11	MR	
19.	> Detector system par	nel Required	Provided	4	
	> Flow Switch Panel		Provided		
	> PA System Panel	Required	Provided	- (7)	
	1 1 1	Required	Provide	' (T)	
	Battery backupBuilding Floor Plan	+	- 1	d MR	



	1 MD
20.	Special Fire Protection Systems for Protection of special Risks, if any; Transformer/ HT & LT Panel Provided Automatic & MR moderar Grippiere Provided
	The fire protection systems provided in the building were test checked and found functional at the time of inspection. Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/issue shortcomings as noted at serial numbers
	Signature of the Inspecting Officer Officer Name Designation Signature of the Inspecting Name Designation Designation
	D9/100 /mular 4/7/16
	Mr. (40 (WZ) Being H. R. Budding unifert The promises along weith to M.N. 5/7/16
	The premises visited by undersigned on 8/7/16 alongwith ADO WP? F5L is necommended.
	Jusmi Hea please. Januar 8/7/16 Januar 8/7/16
	CK) W2 11/6

-