GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. P6/D68/ans/Sehool/2016/MD2/122/Dated: 01/08/16

FIRE SAFETY CERTIFICATE

Certified that the R C S Convent Secondary School at R S T Enclave Main Road Joharipur, Delhi -110094, comprised of ground plus two upper floors owned/occupied by R C S Convent Secondary School was issued FSC vide letter No.-F6/DFS/MS/2010/1918 dated-29/06/2010. The school building was re-inspected by the officer concerned of this department on 06/07/2016 in the presence of Mr. Yatender Sharma (Manager) of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with Circular Letter No.262-362 Dated-17/01/05 issued by Director of Education and the school building is fit for occupancy class "B" Educational Building' for ground plus two upper floors with effect from . C.I. . Se I.G. for a period of three years, subject to conditions, printed overleaf.

(Vipin Kental) Chief Fire Officer Delhi Fire Service Ph: - 011-23412225

To,

The Principal, R C S Convent Secondary School, R S T Enclave, Main Road, Joharipur, Delhi -110094

Copy:-

The Dy. Director of Education B–Block, Yamuna Vihar, North-East, Delhi-110053

CONDITIONS

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry

1. Name & address of the building

: R C S Convent Secondary School, R S T Enclave Main Road Johripur,

Delhi-110094.

2. Building is comprised of

: Ground plus two upper floors

3. Type of Occupancy

: Educational

4. Type of Case

: Renewal

5. Details of Previous NOC letter

: F6/DFS/MS/2010/1918 Dated-29/06/2010

6. Fire Safety direction letter No

: Dir. of Edu. Circular Letter No.262-362 Dated-17/01/05

7. Date of Inspection

: 06/07/2016

8. Name of the Inspecting officers

: ADO Vijay Bahadur

9. Name and designation of Officer from the building side

: Mr. Yatender Sharma (Manager)

10. Year of Construction

: 2004

11. Applicant's letter No

: No.-RCS/L/16, Dated- 15/06/2016

Sr.	Minimum Standards on Fire	Circular	Provided at Site	Remarks				
No.	Prevention and Fire Safety U/R33	Requirement		MR/NMR				
01	Access to Building.							
	Road width	06 mtr.	18 mtr.	MR				
	 Gate width 	N/A	N/A	N/A				
	 Width of internal road 	N/A	N/A	N/A				
02	Number, Width, Type and Arrangement of Exits.							
***************************************	a. Number of Staircases			/				
	Upper floor	02 nos.	02 nos.	MR				
	Basement	N/A	N/A.	N/A				
	b. Width of Staircases			1				
	Upper floor	1.50 mtr.	1.35 mtr. & 0.76 mtr.	MR (old accepted)				
	 Basement 	N/A	N/A	N/A				
	c. Protection of exits		'0					
	 Fire check door 	N/A	N/A	N/A				
	 Pressurization 	N/A	N/A	N/A				
	d. No. of Continuous Staircases to Terrace	01 nos.	02 nos.	MR /				
	e. Width of Corridor	1.50 mtr.	1.60 mtr.	MR				
	f. Door Size	01 mtr.	01 mtr.	MR				
03	Compartmentation.							
	Fire check door	N/A	N/A	N/A				
	 Sealing of electrical shafts 	N/A	N/A	N/A				
	 Fire rating of shaft door 	N/A	N/A	N/A				
	Water curtain	N/A	N/A	N/A				
	Fire dampers	N/A	N/A	N/A				
04	Smoke Management System.							
	Basement	N/A	N/A	N/A				
	Upper floor	N/A	N/A	N/A				
05.	Fire Extinguishers.							
	Total numbers	07 nos.	10 nos.	MR				
	Types	ABC /CO ₂	ABC /CO₂	MR				
	IS marking	ISI marked	ISI marked	MR				

06	First-Aid-Hose Reels.						
	Total numbers on each floor	01 no.	01 no.	MR			
	 Length of hose reel hose 	30 mtr.	30 mtr.	MR			
	Nozzle diameter	6.5 mm	6.5 mm	MR			
07	Automatic Fire Detection and Alarming System.						
	Type of detectors	N/A	N/A	N/A			
	Location of main panel	N/A	N/A	N/A			
	Location of repeater panel	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooter's location	N/A	N/A	N/A			
08	MOEFA	N/A	N/A	N/A			
09	Public Address System.	N/A	N/A	N/A			
10	Automatic Sprinkler System.						
************	Basement	N/A	N/A	N/A			
	upper floor	N/A	N/A				
		N/A	N/A	N/A			
11	sprinkler above false ceiling Internal Hydrants	IVA	IVA	N/A			
	size of riser/down-comer	100 mm	100 mm	MR			
	Number of hydrants per floor	01 no.	01 no.	MR			
	Hose box	01 no.	01 no.	MR			
12	Yard Hydrants.	01110.	01110.	IVIIX			
	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13	Pumping Arrangements.	14/7	IVA	111//			
	➢ Ground Level						
	Discharge of main pump	N/A	N/A	N/A			
	Head of Main pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
		N/A	N/A	N/A			
	out parties	N/A	N/A	N/A			
	Jockey pump headStandby pump out put	N/A	N/A	N/A			
	Standby pump dut put Standby pump head	N/A	N/A	· N/A			
	Auto Starting /Manual stopping	N/A	N/A	N/A			
	Pump house access	N/A	N/A	N/A			
	> Terrace Level	1977	1071	1877			
	Discharge of pump	450 Lpm.	450 Lpm.	MR			
	Head of the pump	40 M	40 M	MR			
	Power supply	Required	Provided	MR			
	Auto Starting of pump	Required	Provided	MR			
14	Captive Water Storage for Fire Fighting.						
	Underground tank capacity	N/A	N/A	N/A			
	Draw-off connection	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	Access to tank	N/A	N/A	N/A			
	Overhead tank capacity	5,000 Ltr.	5,000 Ltr.	MR			
15	Exit Signage.	Required	Provided	MR			
16	Provision of Lifts.						
	Pressurization of lift shaft	N/A	N/A	N/A			
	Pressurization of lift lobby	N/A	N/A	N/A			
		1 41 / /	14/7	14//			
The state of the s		N/Δ	ΛΙ/Δ	NIA			
	Communication in lift car Firemen's grounding switch	N/A N/A	N/A N/A	N/A N/A			

17	Standby Power Supply	N/A	N/A	N/A	
18	Refuge Area.		1		
	Total area	N/A	N/A	N/A	
	Location	N/A	N/A	N/A	
19	Fire Control Room				
	Detector system panel	N/A	N/A	N/A	
	Flow switch panel	N/A	N/A	N/A	
	PA system panel	N/A	N/A	N/A	
	Battery backup	N/A	N/A	N/A	
	Building floor plans	N/A	N/A	N/A	
20	Special Fire Protection Systems for Protection of Special Risks, if any:	N/A	N/A	N/A	

The fire protection systems provided in the building were tested/checked at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No.-F6/DFS/MS/2010/1918 Dated-29/06/2010, renewal under the Director of Education Circular Letter No.262-362 Dated-17/01/05, is recommended.

Signature of the Inspecting Officer Name- Vijay Bahadur

Designation- A.D.O

DO(ED)

212/7

DeFO(NBZ)