GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No. F.6/DFS/MS/2016/SZ | 1232

Dated: 4/8/16

FIRE SAFETY CERTIFICATE

Certified that the **Satya Service Station** at L-Block, Hari Nagar, Jail Road, New Delhi-110064 comprised of ground floor in double storied building was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/2013/695 dated 13.08.2013 owned/occupied by Major Jai Gopal Srivastava. The premises was reinspected by the officer concerned of this department on 19.7.2016 in the presence of Sh. M.K. Sahib (Works Manager) and found that the said service station have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Group J "Hazardous Building" w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed below.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to:-

 Sh. Major Jai Gopal Srivastava, Satya Service Station, L-Block, Hari Nagar, Jail Road, New Delhi-110064.

Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT 1. Name & address of the building: Satya Service Station, located at, Hari Nagar, Jail Road, New Delhi-64 2. Type of Occupancy Group J (Hazardous Building) 3. Type of Case Renewal 4. Details of Previous NOC F6/DFS/MS/2013/695 dated 13.8.2013 5. Fire Safety directives letter No : N/A 6. Date of inspection : 19.7.2016 7. Name of Inspecting Officer : A.D.O. Sandeep Duggal 8. Name and designation of officers From the building side : Sh. M.K. Sahib (Works Manager) 9. Year of Construction

10. Applicant's letter No. : Letter No. Form "J" dated 01.7.2016

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC/ BBL Requirement	Provided at site	Remarks MR/NMR			
i.	Access to building	Street A. Street Street Street Street	Site	TVIIIVITIII			
W							
	Road width	Accessible (09 mtrs) 4.5 mtrs.	12 mtrs	MR			
	Gate width	N/A	Directly accessible from road	MR			
	 Width of internal road 	19/74	N/A	N/A			
2.	Number, Width, Type & Arrangement of Exit	s					
	a. Number of staircases						
	Upper Floors	N/A	N/A	N/A			
	Basements	N/A	N/A	N/A			
	b. Width of staircases	14/11	14/11	1771			
	Upper Floor	DT/A		DT/A			
	Basements	N/A	N/A	N/A			
		N/A	N/A	N/A			
	c. Protection of exits						
	Fire check door	N/A	N/A	N/A			
	Pressurization	N/A	N/A	N/A			
	d. No. of continuous staircases to	N/A	N/A	N/A			
	terrace	N/A	N/A	N/A			
	e. Width of Corridor						
	f. Door Size	100 cms	Provided	MR			
3.	Compartmentation			an A			
			•	V 18 0 18			
	Fire check door	N/A	N/A	N/A			
	 Sealing of electrical shafts 	N/A	N/A	N/A			
÷	Fire Rating of shaft door	N/A	N/A	N/A			
	Water Curtain	100 100 100					
	• Fire Dampers	N/A	N/A	N/A			
		N/A	N/A	N/A			
4.	Smoke Management System		•	•			
	Basement	N/A	N/A	N/A			
	Upper floors	N/A	N/A	N/A			
		The second of th					
5.	Fire Extinguishers						
	Table with the second	12 == 2	Duovi de d	MD			
	Total numbers	12 no's	Provided	MR			
	• Types	DCP/ABC/CO ₂ type	Provided	MR			
	IS marking	ISI marked	Provided	MR			
6.	First-Aid Hose Reels						
210	Total numbers on each floor	N/A	N/A	N/A			
	Length of hose reel hose	N/A	N/A	N/A			

7.	Automatic fire detection and alarming system		8 44	v
1.	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
		N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	 Alternate source of power 		N/A ·	N/A
·	Hooters' Location	N/A		
	MOEFA	N/A	N/A	N/A
	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System	DI/A	N/A	N/A
	Basement	N/A N/A	N/A N/A	N/A
	Ground Floor			
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants	N/A	N/A	N/A
	Size of riser/down-comer		N/A N/A	N/A
	Number of hydrants per floor	N/A N/A	N/A N/A	N/A
	Hose Box	IN/A	IN/A	IN/A
2.	Yard Hydrants	3.T/A	DT/A	NT/A
v **	 Total number of hydrants 	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			
	Ground Level	27/4	27/4	NT/A
	Discharge of main Pump	N/A	N/A	N/A
2	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put	N/A	N/A	N/A
2 1	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
25	Standby Pump Head	N/A	N/A	N/A
4 5	Auto Starting/Manual Stopping			
	Auto Starting/Manual Stopping	N/A	N/A	N/A
	Pump House Access	N/A	N/A	N/A
	Terrace level			
	Discharge of pump	N/A	N/A	N/A
	> Head of the pump	N/A	N/A	N/A
	> Power Supply	N/A	N/A	N/A
	Auto Starting of pump	N/A	N/A	N/A
·		1 1/1 1		1 2 2 8
14.	Captive Water Storage for fire fighting			* 5
	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	> Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
- V	Overhead Tank capacity			N/A
	,	N/A	N/A N/A	N/A N/A
15	Evit Signage	N/A	IN/A	IN/A
	Exit Signage. Provision of Lifts.			(No Lift)
10.	I IOVISION OF LINES.			(1.0 1111)
W	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch			
	Lift Signage	N/A	N/A .	N/A
	■ LIII SIKIIAKE	N/A	N/A	N/A
17.	Standby power supply	Required	Provided 62.5	MR
			KVA DG set	
18.	Refuge Area			
	> Total Area	N/A	N/A	N/A

Fire Central Room			×
	N/A	N/A	N/A
	N/A	N/A	N/A
	N/A	N/A	N/A
Battery backup	N/A	N/A	Ņ/A
Building Floor Plans	N/A	N/A	N/A
Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A
	 PA System Panel Battery backup Building Floor Plans 	Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans N/A Special Fire Protection System for Protection N/A	Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans N/A N/A N/A N/A N/A N/A N/A N/

The fire protection systems provided in the building were tested, checked and found

functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the Fire Safety Certificate issued vide letter number F6/DFS/MS/2013/695 dated 13.8.2013 renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Note:- 1. There are three rooms (at the rear side of petrol pump office building) on first floor served by a single staircase of one mtr. width, having store & offices.

2. There are facilities of wheel balancing, wheel alignment, servicing of cars, Air compressor, pollution control centre Kisok, Puncture Kisok, spare parts sale Kisok etc. at the rear office of petrol pump.

3. No smoking boards were found displayed in Hindi & English. Fire buckets filled with sand

placed near retail points.

Signature of Inspecting Officer

Name:- Sandeep Duggal

Designation:- Asstt. Divisional Officer

D.O. (South West)

DCFO(SZ)

26/2