FORM 'H'
FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

NEW DELHI.

No. F6/DF5/M5/2016/Cinena/w2/1334

Dated: 01/09/16

FIRE SAFETY CERTIFICATE

Chief Fire Officer Delhi Fire Service

Copy to:

1. Sh. Abhishek Kapoor (Manager)
M/s Movie Times Cineplex Pvt Ltd (Audi 1-6) at 4th Floor, West Gate Mall, Plot No. 4, 5, 6, Shivaji Palace, Raja Garden, New Delhi

2. Sh. Ravindra Singh (SDM) Patel Nagar GNCT of Delhi, Old Middle School Complex, Rampura, Delhi – 110035

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per building bye laws.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

1. Name & address of the building: M/s Movie Times Cineplex Pvt Ltd (Audi 1-6) at 4th Floor, West Gate Mall, Plot No. 4, 5, 6, Shivaji Palace, Raja Garden, New Delhi

2. Type of Occupancy

: Assembly

3. Type of Case

: Renewal

4. Details of previous NOC

: Letter No. F6/DFS/MS/Cinema/2015/289 dated 09/02/15

5. Fire Safety directives Letter No.: Letter No. F6/DFS/MS/BP/2005/1876 dated 13-09-05

6. Date of inspection

: 26-07-2016

7. Name of the Inspecting Officer: Mukesh Verma, DO (MN)

8. Name and designation of Officer

from the building side

: Sh. Abhishek Kapoor (Manager)

9. Year of Construction

: 2006

10. Applicant's letter No.

: F.84/DDMA)W)LCT/Movie Timer(RG)/2015/ dated nil

S No	Minimum standards on fire prevention and fire safety U/R 33	BBL Requirements	Provided at site	Remarks MR/NMR	
1.	Access of building	Common with the Mall			
	Road width	6 m	Provided	MR	
	• Gate width	6 m	Provided	MR	
	Width of internal road	6 m	Provided	MR (Being old case)	
2.	Number, width, Type & Arrangem	ents of exits Common with the Mall			
	a. Number of staircases				
	• Upper floors	10	Provided	MR	
	 Basements 	12	Provided	MR	
	b. Width of staircases	11			
	• Upper floors	Old Case	Old Case	Old Case	
	 Basements 	Old Case	Old Case	Old Case	
	c. Protection of exits				
	Fire check door	Required	Provided	MR	
	 Pressurization 	Required	Provided	MR	
	d. No of continuous staircase	Required	Provided	MR	
	to terrace				
	e. Width Of Corridor	NA	NA	NA	
	f. Door Size	3 exits	3 exits provid in each Audi	led NA	
3.	Compartmentation		Common with t	1 74 11	
	Fire check door	Required	Provided	MR	
	 Sealing of electrical shafts 	Required	Provided	MR	
	 Fire Rating of shaft door 				
	Water Curtain	Required	Provided	MR	
	• Fire Dampers	Required	Provided	NR	
	The Dampers	Required	Provided	MR	
4.	Smoke managements System	Common with the Mall			
	Basements	30 a/c per hour	Provided	NR	
	Upper floors	12 a/c per hour	Provided	MR	
5.	Fire Extinguishers	Common with the Mall			
	Total numbers	04 in each Audi	04 Provided	MR	
		o i mi cucii / tudi	UTITUVIUCU	IVIIV	

6.	First – Aid Hose Reels	* 1	THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER.						
	Total numbers on each	02 nos in each	02 Provided	MF	3				
	floor	Audi	7	3.61	D.				
	 Length of hose reel hose 	30 m	Provided	MI					
	Nozzle diameter	5 mm	Provided	MI	K.	17			
7.	Automatic fire detection and alarming system								
	Type of detectors	Beam detector	Provided	MR					
	 Location of Main Panel 	Required	Provided	MR					
	 Location of Repeater 	Required	Provided	MR					
	Panel								
	 Alternate source of power 	Required	22012000	MR					
	 Hooters' Location 	Required	Provided	MR		20			
8.	MOEFA	Required	Provided	MR					
9.	Public Address System	Required	Provided	MR					
10.	Automatic Sprinkler System	Comm	on with the Mall						
	Basements	Required	Provided	NR					
	 Upper Floor 	Required	Provided	MR					
	 Sprinkler above false 	Required	Provided	MR					
	ceiling								
11.	Internal Hydrants								
	Size of riser/down- comer	150 mm	Provided Provided	MR	-				
	 Number of hydrants per 	02 in each Audi	02 Provided	MR					
	floor	Required	Provided	MR					
	Hose Box	Required	Trovided	IVIIC					
12.	Yard Hydrants	NA	NA	NA					
	Total number of hydrants	NA NA	NA NA	NA					
	Hose Box	Common wi		11/1					
13.	Pumping Arrangements	Common wi	ith the Man		-				
	Ground Level	4500 lpm	4500 lpm Provided MR		MR				
	Discharge of main pump	70 m	70 m Provided		MR	1.5			
	Head of main pumpNumber of main pumps	2	2 Provided		MR				
		180 lpm	180 lpm Provide		MR				
	Jockey pump out putJockey pump head	75 m	75 m Provided		MR				
	> Standby Pump out put	4500 lpm	4500 lpm Provi	ded	MR	· ·			
	> Standby Pump Head	70 m	70 m Provided		MR				
	> Auto Staring/Manual	Required	Provided &		MR				
	stopping	1	Functional		*	1 1			
	> Pump House Access	Required	Provided		MR				
	Terrace level								
	Discharge of pump	Not Required	NR	NR		-			
	> Head of the pump	Not Required	NR	NR		N 12			
	> Power supply	Not Required	NR	NR					
	> Auto starting of pump	Not Required	NR	NR					
14.	Captive water Storage for fire figh		ommon with the	T					
	Under ground tank	2,50,000 litres	Provided	MR		9			
	capacity	Required	Provided	MR					
	> Draw of connection	Required	Provided	MR	7				
	Fire service inletAccess to tank	Required	Provided	MR					
	Overhead Tank capacity	30, 000 litres	Provided	MR					
15	Exit Signage	Required	Provided	MR					
16.		Common wit							
10.	> Pressurization of Lift Shaft		Provided	NR					
	Pressurization of lift lobby	A	Provided	NR					
	Communication in lift Car		Provided	MR					
	Fireman's Grounding	Required	Provided	MR					
	Switch		111111111111111111111111111111111111111			MA AND			

	standby po	wer supply	Required	Provided	MR		
67	Refuge Are	1 1 1					
-	> Tota	al area	NA	NA	NA		
	> Loc	ation	NA	NA	NA		
19.	Fire control room Common with the Mall						
	> Det	ector system panel	Required	Provided	MR		
	> Flo	w Switch Panel	Required	Provided	MR		
	> PA	System Panel	Required	Provided	MR		
	> Bat	tery backup	Required	Provided	MR		
	Bui	lding Floor Plans	Required	Provided	MR		
20.	Special Fire	e Protection Systems	NR	NR	NR		
		on of special Risks, if					
	any;	-		7			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide letter no. F6/DFS/MS/Cinema/2015/289 dated 09/02/15renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Officer

Name Mukesh Verma

Designation DO (MN)

Steel seg widle of Haircas