GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2016/SZ / 1397

Dated: 09/09/16

FIRE SAFETY CERTIFICATE

Certified that the **The Happy Child Model School,** RZ-24, Jain Colony Part-III, Uttam Nagar, New Delhi-110059, comprised of ground floor plus one upper floor of a three storied building owned/occupied by The Happy Child Model School was inspected by the officer concerned of this department on 24.8.2016 in the presence of Sh. Vivek Sharma (Manager) and found that The Happy Child Model School have complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises (Ground plus one upper floor) is fit for occupancy class "Educational" for a period of three years, subject to compliance of the conditions printed as under.

Issued on ... O.S. / ... at New Delhi.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to:-

- 1. The Manager, The Happy Child Model School, RZ-24, Jain Colony Part-III, Uttam Nagar, New Delhi-110059.
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

School building is comprised of ground plus one upper floor in a three storied building. INSPECTION REPORT The Happy Child Model School, RZ-24, Jain Colony Part-III, Uttam 1. Name & address of the building: Nagar, New Delhi-110059. Educational 2. Type of Occupancy Type of Case New **Details of Previous NOC** N/A Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated Fire Safety directives letter No : 01.03.2011 issued by the Director of Education Date of inspection 24.8.2016 A.D.O. Sandeep Duggal Name of Inspecting Officer Name and designation of officers From the building side Sh. Vivek Sharma (Manager) : 2005-2006 9. Year of Construction : Nil dated 08.8.2016 10. Applicant's letter No. Remarks Dt. of edu. Provided at S. No. Minimum Standards on fire prevention and Requirement MR/NMR site fire safety U/R 33 Access to building 1. Accessible (06 mtrs) 6.5 mtrs MR Road width 4.5 mtrs Directly accessible MR Gate width from road N/A N/A N/A Width of internal road Number, Width, Type & Arrangement of Exits 2. a. Number of staircases 02 No.'s 01 No. **Upper Floors** MR Basements N/A N/A N/A b. Width of staircases Upper Floor 150 cms & 89 150 cms MR **Basements** cms c. Protection of exits N/A N/A N/A Fire check door Pressurization N/A N/A N/A N/A N/A N/A d. No. of continuous staircases to terrace N/A N/A N/A Width of Corridor N/A N/A N/A Door Size MR 100 cms 100 cms Compartmentation 3. N/A N/A N/A Fire check door N/A N/A Sealing of electrical shafts N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A 4. Smoke Management System N/A N/A N/A Basements Natural ventilation MR Required Upper floors provided Fire Extinguishers 5. Provided MR 04 no's Total numbers ABC/CO₂ type Provided MR Types MR IS marking Provided ISI marked First-Aid Hose Reels 6. N/A N/A N/A Total numbers on each floor N/A N/A N/A Length of hose reel hose N/A

7.	Automatic fire detection and alarming system			
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	 Location of Repeater Panel 	N/A N/A	N/A	N/A
	 Alternate source of power 	N/A	N/A	N/A
	 Hooters' Location 	IV/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			•
	Basement	N/A	N/A	N/A
		N/A	N/A	N/A
	Ground Floor Gravin Hay a baye false sailing	N/A	N/A	N/A
11	Sprinkler above false ceiling Internal Hydrants	IVA	14/11	11/12
11.	Size of riser/down-comer	N/A	N/A	N/A
		N/A	N/A	N/A
	Number of hydrants per floorHose Box	N/A	N/A	N/A
12		1111		
12.	Yard Hydrants	N/A	N/A	N/A
	Total number of hydrants Head Boy	N/A	N/A	N/A
12	Hose Box Provide A managements	11/71	11/11	1771
13.	Pumping Arrangements	I		
	Ground Level Discharge of main Rumn	N/A	N/A	N/A
	Discharge of main Pump			N/A
	Head of Main pumpNumber of main pumps	N/A	N/A	
	Jockey Pump out put	N/A	N/A	N/A
	> Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	> Standby Pump Head	N/A	N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A	N/A
	, , , , , , , , , , , , , , , , , , , ,	N/A	N/A	N/A
		N/A	N/A	N/A
	Pump House Access	14/71	11/11	177.2
	Terrace level	DI/A	NI/A	N/A
	Discharge of pump	N/A	N/A N/A	N/A N/A
	> Head of the pump	N/A N/A	N/A N/A	N/A N/A
	> Power Supply		N/A N/A	N/A
	Auto Starting of pump	N/A	IN/A	IN/A
14.	Captive Water Storage for fire fighting	1		
- N	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	> Fire service inlet	N/A	N/A	N/A
	> Access to tank	N/A	N/A	N/A
	Overhead Tank capacity		N/A	N/A
4 10		N/A N/A	N/A N/A	N/A N/A
15.	Exit Signage.	IN/A	IN/A	IV/A
16.	Provision of Lifts.			No Lift
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	· N/A
	 Fireman's Grounding Switch 	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	Ņ/A
18.	Refuge Area.			
	Refuge Area. > Total Area	N/A	N/A	N/A

19.	Fire Control Room			
× v	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were checked, found functional at the time of inspection and shortcomings issued vide letter no.F.6/DFS/MS/School/2016/SZ/1924 dated 09.8.2016 has been complied.

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation: - Asstt. Divisional Officer

D.O. (South West)

Jor 18/2016 shout earl at SAR 2) 165 have been bulon bed as can