GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2016/SZ / 1 4 0 2

Dated: 12/08/16

FIRE SAFETY CERTIFICATE

Certified that the **Govt. Girls Sr. Sec. School**, Ujwa, New Delhi-110073, owned/occupied by Govt. of NCT of Delhi was issued FSC for Ground floor only by this department vide letter no. F.6/DFS/MS/School/2012/3986 dated 25.10.2012. The School was re-inspected by the officer from this department on 23.08.2016 in the presence of Smt. Damyanti (Principal) and found a new block comprised of ground plus one upper floor is added in the premise. The Govt. Girls Sr. Sec. School have complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the school building/ premises is fit for occupancy class "Educational" for a period of three years, subject to compliance of the conditions printed as under.

(VIPIN KENTAL)
CHIEF FIRE OFFICER

Copy to:-

- 1. The Principal, Govt. Girls Sr. Sec. School, Ujwa, New Delhi-110073.
- Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

and Block-B is having Ground Plus One Upper Floor INSPECTION REPORT Govt. Girls Sr. Sec. School, Ujwa, New Delhi-110073. 1. Name & address of the building Educational Type of Occupancy New/Renewal for A moch 3. Type of Case F.6/DFS/MS/School/2012/3986 dated 25.10.2012 (Only for Block-A). 4. Details of Previous NOC 5. Fire Safety directives letter No Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 6. Date of inspection 23.08.2016 A.D.O. Sandeep Duggal 7. Name of Inspecting Officer Name and designation of officers From the building side Smt. Damyanti (Principal) Before 2010 (Block-A) & 2015 (Block-B) 9. Year of Construction 10. Applicant's letter No. GGSSS/Ujwa/26.7.16/672 dated 26.7.16 Dir. Of Edu. Provided at Remarks S. No. Minimum Standards on fire prevention and MR/NMR site fire safety U/R 33 Circular dt. 01.03.2011 Access to building Accessible 06 mtrs MR 6.5 mtrs Road width Old Case MR, being old case 2.44 mtrs. Gate width N/A · N/A N/A Width of internal road Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors MR 02 No.'s 02 No.'s **Basements** N/A No Basement N/A b. Width of staircases Upper Floor 150 & 150 cms MR 150 cms Basements in Blk-B c. Protection of exits N/A N/A No Basement Fire check door Pressurization N/A N/A N/A N/A N/A N/A d. No. of continuous staircases to terrace N/A N/A One e. Width of Corridor 200 cms in Blk-A & MR 150 cms f. Door Size 177 cms in Blk-B 93 & 110 cms in Blk-Old case MR, being old A & 111cms Double case door in Blk-B Compartmentation N/A N/A N/A Fire check door Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A Smoke Management System N/A N/A No Basement Basements Natural Ventilation MR Required Upper floors provided 5. Fire Extinguishers 09 No's Provided MR Total numbers Provided MR **Types** ABC/CO₂ type

ISI marked

N/A

N/A

ISI marked

N/A

N/A

MR

N/A

N/A

1.

2.

3.

4.

6.

IS marking

Total numbers on each floor

Length of hose reel hose

First-Aid Hose Reels

7.	Automatic fire detection and afarming system	112 1 54 4 11 17 17 18		
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10				* 3
10.	Automatic Sprinkler System Basement	N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants	IN/A	IN/A	IN/A
11.	Size of riser/down-comer	N/A	N/A	N/A
	 Number of hydrants per floor 	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants	9000 955333 900	20° 200 mm/m²	
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements	A 11/A A	- "	
	Ground Level	T		
	Discharge of main Pump	N/A	N/A	N/A
	➤ Head of Main pump	N/A	N/A	N/A
	Number of main pumps			N/A
	Jockey Pump out put	N/A	N/A	
	Jockey pump head	N/A	N/A	N/A
	> Standby Pump out put	N/A	N/A	. N/A
	Standby Pump HeadAuto Starting/Manual Stopping	N/A	N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
	D II	N/A	N/A	N/A
	> Pump House Access			
	Terrace levelDischarge of pump	N/A	N/A	N/A
	Head of the pump	N/A	N/A	N/A
	> Power Supply	N/A	N/A	N/A
	> Auto Starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for fire fighting			***
	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	> Access to tank	55 540 15		N/A
	Overhead Tank capacity	N/A	N/A	
4 2	T '4 C'	N/A	N/A N/A	N/A N/A
15.	Exit Signage.	N/A		
16.	Provision of Lifts.	21/4		(No Lift)
	Pressurization of Lift Shaft Pressurization of Lift Shaft Pressurization of Lift Shaft Pressurization of Lift Shaft	N/A	N/A	N/A
	 Pressurization of Lift lobby Communication In lift Car 	N/A	N/A	N/A
	Communication in lift Car Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
	- Litt Signage	N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
18.	Refuge Area.			
	> Total Area	N/A	N/A	. N/A
AW	location	IN/A	IV/A	. 11/11

19.	Fire Control Room			
	Detector System Panel	N/A	N/A	· N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Note:- Earlier Fire Safety Certificate was issued vide letter no. F.6/DFS/MS/School/2012/3986 dated 25.10.2012 only for Block-A having ground floor only.

Sauce 8 6

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation: - Asstt. Divisional Officer

Divisional Officer (South West)

29/8