GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/DFS/ans/sehool/2016/MD2/1421

Dated: 20/9/16

FIRE SAFETY CERTIFICATE

Certified that the Nursery School at D-Block Anand Vihar, behind Over Head Tank Delhi for Adhunik Education Society, comprised of basement, ground plus one upper floor was issued NOC vide letter No.- F6/MS/DFS/School/2004/847 dated 16/04/04. The school building was inspected by the officer concerned of this department on 05/09/2016 in the presence of secretary of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with Circular F16/Estate/CC/FireSafety/2011/3298 to 3398 dated 01/03/11 issued by Director of Education and the school building is fit for occupancy class "B' Educational Building for basement, ground plus one upper floor only with effect from.....for a period of three years, subject to conditions, printed overleaf.

Issued on 20/9//6...a New Delhi by

(Vipin Kental)
Chief Fire Officer

9/4/

To,

The Secretaryl,

Nursery School at D-Block Anand Vihar, behind Over

Head Tank Delhi for Adhunik Education Society.

Copy to:-

The Director of Education, EDMC, Udyog Sadan, Plot No. 419, FIE, Patpargani Industrial Area, Delhi-92.

CONDITIONS

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry

1. Name & address of the building: Nursery School at D-Block Anand Vihar, behind Over

Head Tank Delhi for Adhunik Education Society.

2. Building is comprised of : B+G+1

3. Type of Occupancy : Educational

4. Type of Case : Renewal

5. Details of Previous FSC letter : F6/MS/DFS/School/2004/847 dated 16/04/04

6. Fire Safety Circular No. : F.16/Estate/CC/FS/2011/3298 to 3398 dated 1.3.11

7. Date of Inspection : 05/09/2016

8. Name of the Inspecting officers: ADO R.K. Yadav

9. Name and designation of

Officer from the building side : Secretary

10. Year of Construction : 2004

11. Applicant's letter No : Dated 11/08/16

N O.	Minimum Standards on fire prevention and fire safety U/R33	Circular Requirement	Provided at Site	Remarks		
1	Access to building					
	Road width	06 M	18 Mrs.	MR		
	Gate width	N/A	N/A	N/A		
	 Width of internal road 	N/A	N/A	N/A		
2	Number, Width, Type and Arrangement of Exits					
	a. Number of Staircases					
	Upper Floor	02 Nos.	02 Nos.	MR		
	Basement	02 Nos.	02 Nos.	MR		
	B. Width of Staircases					
	Upper Floor	1.5 M	1.25 Meach	MR*		
	Basement	1.25 M	1.25 M each	MR		
	c. Protection of exits					
	Fire check door	Required	Provided	MR		
	Pressurization	N/A	N/A	N/A		
	e. No. of continuous staircases to	1 No.	1 No.	MR		
	terrace	1.5 M	1.5 M	MR		
	g. Width of Corridor	1.0 M	1.0 M	MR		
	h. Door Size					
3	Compartmentation.					
	Fire check door	N/A	N/A	N/A		
	 Sealing of electrical shafts 	N/A	N/A	N/A		
	Fire rating of shaft door	N/A	N/A	N/A		
	Water curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
4	Smoke Management System.					
	Basement	N/A	N/A	N/A		
	Upper floor	N/A	N/A	N/A		
5.	Fire Extinguishers					
	Total numbers	06 Nos.	10 Nos.	MR		
	types	ABC & Co2	ABC & Co2	MR		
	IS marking	ISI marked	ISI marked	MR		

Earlier NOC was issued date 16/04/2004 same width 1.25 m of staircases

6	First-aid-Hose Reels. Total numbers of each floor	1 no.	Provided	MR			
	Length of hose reel hose	30 m	Provided	MR			
	Nozzle diameter	5 mm	Provided	MR			
7	Automatic fire detection and alarming system.						
	Type of detectors	N/A	N/A	N/A			
	Location of main panel	N/A	N/A	N/A			
	Location of repeater panel	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooter's location	N/A	N/A	N/A			
8	MOEFA	Required	Provided	MR			
9	Public address System.	N/A	N/A	N/A			
10	Automatic Sprinkler System.	N/A	N/A	N/A			
	Basement	N/A	Provided	MR			
***************************************	upper floor	N/A	N/A	N/A			
	sprinkler above false ceiling	N/A	N/A	N/A			
11	Internal Hydrants						
	size of riser/down-comer	100 mm	Provided	MR			
	Number of hydrants per floor	1 no.	Provided	MR			
	Hose Box	1 no.	Provided	MR			
12	Yard Hydrants.	N/A	N/A	N/A			
	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13	Pumping Arrangements.	N/A	N/A	N/A			
-	Ground Level	N/A	N/A	N/A			
	Discharge of main Pump	N/A	N/A	N/A			
	➢ Head of Main Pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	Jockey pump out put	N/A	N/A	N/A			
	> Jockey pump head	N/A	N/A	N/A			
-	Standby pump out put	N/A	N/A	N/A			
	> Standby pump Head	N/A	N/A	N/A			
	 Auto Starting /Manual stopping 	N/A	N/A	N/A			
	Pump House Access	N/A	N/A	N/A			
	Terrace Level	N/A	N/A	N/A			
	Discharge of pump	450 Lpm	450 Lpm	MR			
	> Head of the Pump	40M	40M	MR			
	Power supply	Required	Provided	MR			
	> Auto Starting of pump	Required	Provided	MR			
14	Captive Water Storage for Fire Fighting.	N/A	N/A	N/A			
	Underground tank capacity	N/A	N/A	N/A			
	> Draw-off connection	N/A	N/A	N/A			
	> Fire service inlet	N/A	N/A	N/A			
	> Access to tank	N/A	N/A	N/A			
	Overhead Tank capacity	10,000 Ltrs.	Provided	MR.			
15	Exit Signage.	Required	Provided	MR			

16	Provision of Lifts.	N/A	N/A	N/A
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication in lift car	N/A	N/A	N/A
	Firemen's grounding switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.	N/A	N/A	N/A
	Total area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
19	Fire Control Room	N/A	N/A	N/A
~~~~~	Detector system panel	N/A	N/A	N/A
	Flow switch panel	N/A	N/A	N/A
	PA system panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules. The NOC issued vide letter no. F6/MS/DFS/School/2004/847 dated 16/04/04 renewal under the circular no. F.16/Estate/CC/FS/2011/3298 to 3398 dated 1.3.11 is recommended Fire Safety Certificate.

Signature of the Inspecting Officer

Name: R. K. Yadav Designation: ADO(LN)

DO(ED) Submitted for approval please.