GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS / 2016 / W 2 / 1477

Dated: 05/10/16

FIRE SAFETY CERTIFICATE

Certified that the Aggarwal City Plaza located at Plot No- 17, Mangalam Palace District Center, Sec-03 Rohini, Delhi-110085 comprised of basement, ground and 03 upper floors owned/occupied by Aggarwal City Plaza was issued fire safety certificate vide letter no. F6/MS/DFS/2006/430 dated 20/02/2006. The premises was re-inspected by the officer concerned of Fire Service and observed that all the fire prevention & fire safety arrangements as provided in the premises found in good working condition. The premises have therefore deemed complied with the fire prevention and fire safety accordance with rule 33 of the Delhi Fire Service rule 2010 and verified by the officer concerned of Delhi Fire Service on 08.08.2016 in the presence of Mr. Jai Chand and that the premises is fit for occupancy Class-G Mercantile with effect from $\partial \mathcal{N}/\partial \mathcal{N}$ /2016 for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi fire service Rules, 2010.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on **www.dfs.Delhigovt.nic.in**
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

Chief Fire Officer Ph:-011-23414250

Copy to: -

1. M/s Unity Projects (Pvt.) Ltd., Plot no. 17, Mangalam Place, Sec-03, Rohini, New Delhi.

INSPECTION REPORT

1. Name & address of the building

: Aggarwal City Plaza Plot No- 17, Manglam Palace District Center, Sec- 03 .

Rohini, Delhi-110085.

2. Type of Occupancy

:Mercantile (B+G+03upper floors)

3. Type of Case

:Renewal

4. Details of previous NOC

:F.6/DFS/MS/GH/2006/430 Dated: 20/02/2006

5. Fire Safety directives letter No

:F.6/MS/DFS/BP/2003/3056 Dated: 16/12/2003

6. Date of inspection

:08/08/2016

7. Name of the Inspecting Officers

:Suresh Singh, DO/NWD, Rajesh Kumar, ADO (RN)

8. Name and designation of officers

from the building side

: Mr. Jai Chand (Maintenance)

9. Year of Construction

: 2003

10. Applicant's letter No.

: UPL/AS/ACM/DFS/2K16/0172 Dated: 01/07/2016

	Minim	num Standards on fire prevention and fire safety U/R 33	BBL 1983	Provided at site	Remarks MR/NMR	
1	Access t	o building			12	
	•	Road width	09m	12m	MR	
	•	Gate width	06m	06m	MR	
	•	Width of internal road	NA	NA	NA	
2	Number, Width, Type & Arrangement of Exits					
	a. Numb	er of staircases				
	•	Upper Floors	09	08nos	MR (Old case	
	•	Basements	07+01 ramp	07+01 ramp	MR	
	b. Width	of staircases				
	•	Upper Floors	1.25m each	1.25m each	MR	
	•	Basements	1.25m each	1.25m each	MR	
	c. Protec	tion of exits				
		Fire check door	Required	Provided	MR	
		Pressurization	Required	Provided	MR	
	d. No. o	f continuous staircases to terrace	05	05	MR	
	e. Width	of Corridor	1.25m	1.25m	MR	
	f. Door S	i <mark>ze</mark>	1.0m	1.0m	MR	
	Compar	tmentation.				



C

	Fire check door	Required	Provided	MR		
	Sealing of electrical shafts	Required	Provided	MR		
	Fire Rating of shaft door	Required	Provided	MR		
	Water Curtain	NA	NA	NA		
	Fire Dampers	NA	NA	NA		
4	Smoke Management System.					
	Basements	30 a/c per hour	Exhaust Fan	MR		
	• Upper floors	12 a/c per hour	Natural Ventilated	MR		
5	Fire Extinguishers					
	Total numbers	35nos	35 nos	MR		
	• Types	ABC & Co2	W. Co-10, ABC— 20, Co2 - 05	MR		
	ISI marking	Yes	Yes	MR		
6	First-Aid Hose Reels.	•				
	Total numbers on each floor	03 at each floor	03 no's	MR		
	Length of hose reel hose	30mm	Provided	NA		
	Nozzle diameter	05mm	Provided	NA		
7	Automatic fire detection and alarming system.					
	Type of detectors	Required	Provided .	MR		
	Location of Main Panel	GF	Provided	MR		
	Location of Repeater Panel	Each floor	Provided	MR		
	Alternate source of power	Required	Provided	MR		
	Hooters' Location	At strategic location	Provided	MR		
8	MOEFA	Required	Provided	MR		
9	Public Address System.	Required	Provided	MR		
10	Automatic Sprinkler System.	6				
	Basement	Required	Provided	MR		
	Upper Floor	Required	Provided	MR		
	Sprinkler above false ceiling	Where applicable	Provided	MR		
11	Internal Hydrants					
	Size of riser/down-comer	100mm	100mm	MR		
	Washington and American	03	03	MR		
	 Number of hydrants per floor 	03				



Total number of hydrants	06 nos	06 Provided	MR		
	Required	Provided	MR		
Hose Box	Required	11011444			
Pumping Arrangements.					
Ground Level	D. C. D. C.	Provided	MR		
Discharge of main Pump	4500LPM		MR		
Head of Main pump	60 M	Provided	MR		
Number of main pumps	01	Provided	MR		
Jockey Pump out put	180 LPM	Provided	MR		
> Jockey pump head	60 M	Provided			
Standby Pump out put	Required	Provided	MR		
Standby Pump Head	Required	Provided	MR		
Auto Starting/ Manual stoppingPump House Access	Required	Provided	MR		
Terrace level					
Discharge of pump	NA	NA	NA		
> Head of the pump	NA	NA	NA		
> Power Supply	NA	NA	NA		
> Auto Starting of pump	NA	NA	NA		
Captive Water Storage for fire fighting.					
	2,00,000 ltrs	Provided	MR		
Underground tank capacity		Provided	MR		
> Draw-off connection	Required		MR		
Fire service inlet	Required	Provided	MR		
> Access to tank	Required	Provided			
Overhead Tank capacity	30,000 ltr	Provided	MR		
Exit Signage.	Required	Provided	MR		
Provision of Lifts.					
Pressurization of Lift Shaft	Required	Provided	MR		
Pressurization of Lift lobby	Required	Provided	MR		
Pressurization of Lift loody Communication In lift Car	Required	Provided	MR		
Communication in Int Car Fireman's Grounding Switch	•	Provided	MR		
	Required				
Lift Signage	Required	Provided	MR		
Standby power supply	Required	Provided	MR		

-	
. 1	10
N	1)4
1	V

		N/A	N/A	N/A	
	> Total Area	IN/A			
	> Location	N/A	N/A	N/A	
19	Fire Control Room				
	Detector System Panel	N/A	N/A	N/A	
	Flow Switch Panel	N/A	N/A	N/A	
	PA System Panel	N/A	N/A	N/A	
	Batter backup	NA	NA	NA	
	Building Floor Plans	N/A	N/A	N/A	
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA	

The fire protection systems provided in the building were tested/ checked and found some in working order at the time of inspection. As per approved plans 09 nos of staircases were proposed whereas only 08 nos of staircase were constructed which are meeting the travel distance requirement as prescribed in BBL 1983. The fire safety certificate was issued vide letter of even no 430 dated 20.02.2006. The management has complied all the observations made earlier issued by this department letter of even no. 2249 dated 01.10.2015.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules the NOC issued vide letter no. F.6 /MS/DFS/2006/ 430 dated 20.02.2006 Renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Officer

Name: - Rajesh Kumar

Designation: - ADO/RN

Do/Ny20)

Al speak

Spoken.