GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001**

No. F.6/DFS/MS/GH/2016/SZ/ 1547

Dated: 20/10/16

FIRE SAFETY CERTIFICATE

Certified that the Ameya Guest House, (A unit of Purwanchal Social Welfare Society) located at Plot No. 6, FC-33 Jasola, New Delhi-110025, comprised of Basement, Ground plus three upper floors but guest house is at 1st 2nd & 3rd floor having 40 guest rooms. The Guest House was inspected by the officer concerned of this department on 14/10/16 in the presence of Mr. Trilochan Singh Khurana & found to have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010and that the building is fit for occupancy Group A "Residential & Lodging" with effect -2-1-2016 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued on. 20. (a.). (at New Delhi by.

Chief Fire Officer Ph:-011-23412235

Copy to:-

1. Mr. Trilochan Singh Khurana, M/s Ameya Guest House, (A unit of Purwanchal Social Welfare Society), Plot No. 6, 1st, 2nd and 3rd Floor, FC-33 Jasola, New Delhi-110025

2. Joint Commissioner of Police (Lic), 1st Floor, Police Station, Defence Colony, New Delhi

Conditions for the validity of fire safety certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of firefighting system.

4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first of Delhi Fire Service Rules 2010. The form is www.dfs.delhigovt.nic.in.

5. This fire safety certificate may not in any way be treated as regularization of unauthorized construction, if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

	e of Occupancy : Class-A "Residentia possession), Rece	6, 1 st , 2 nd and 3 rd F al & Lodging" [Tot ption+ Lobby + of	loor, FC-33 Jasola, Ne tal 40 Guest Rooms {I fice + Dining + One v	W Delhi-110025 Basement (others cacant hall at			
 Detail Fire S Date Name Name From 	e of Case : New ils of Previous NOC : Nil Safety directives letter No : F6/DFS/MS/2008/7 of inspection : 14/10/2016 e of Inspecting Officer : A. K. Malik e and designation of officers in the building side : Mr. Trilochan Sin	1 dated 11/01/2008 gh Khurana					
	of Construction : 2014 / : Nil, dated Nil recei		[Basement + $GF + 1^{st}$] or diary no. 9053 dated				
	Minimum Standards on fire prevention and fire safety U/R 33	BBL/NBC Requirement	Provided at site	Remarks MR/NMR			
1.	Access to building						
	Road widthGate widthWidth of internal road	9m 5m -NA-	12m 4.5m -NA-	MR NMR			
2.	• Width of internal road -NANA- Number, Width, Type & Arrangement of Exits						
	a. Number of staircases						
	• Upper Floors	2No's	Two	MR			
	• Basements	-NA-	-NA-	-NA-			
	b. Width of staircases						
	• Upper Floor	1.25m	1.25 & 1.28m	MR			
	Basements Basements	-NA-	-NA-	-NA-			
	c. Protection of exitsFire check door						
	Pressurization	Required	Provided	MR			
	d. No. of continuous staircases to terrace	-NA-	-NA-	-NA-			
	W	2 Nos.	Provided	MR			
-	e. Width of Corridor f. Door Size	1.5m 1m	Provided 1m (final exit)	MR MR			
3.	Comment of the control of the contro	1111	Till (Tillal exit)	IVIK			
3.	Compartmentation						
	Fire check doorSealing of electrical shafts	Required	Provided	MR			
	 Fire Rating of shaft door 	Required	Provided	MR			
	Water Curtain	Required	Provided	MR			
	• Fire Dampers	-NA-	-NA-	-NA-			
4.	Smoke Management System	-NA-	-NA-	-NA-			
7.		20 -/- 1	374	27.4			
	Basements Unant floorer	30 a/c per hour	-NA-	-NA-			
-	Upper floors 12 a/c per hour Exhaust Fan MR						
5.	Fire Extinguishers • Total numbers 24 No's MR						
	Total numbersTypes		24 No's	MR			
	Types	20 No's	ABC-12 No's CO ₂ - 12 No's	MR			
	IS marking	201103	Yes	MR			
6.	First-Aid Hose Reels		1 03	IVIIX			
	Total numbers on each floor	Two	Provided	MR			
	 Length of hose reel hose 	30m	Provided	MR			
	Nozzle diameter	5mm	Provided	MR			
7.	Automatic fire detection and alarming system						
	Type of detectors	-NA-	-NA-	-NA-			
	Location of Main Panel	-NA-	-NA-	-NA-			
	***************************************	-NA-	-NA-	-NA-			

T	Hooters' Location	-NA-	Provided	MR
	MOEFA	Required Required	Provided	MR
	Public Address System	Required		
	Automatic Sprinkler System	Required	Provided	MR
	 Basement 	-NA-	Provided	-NA-
	Ground Floor	-NA-	-NA-	-NA-
	Sprinkler above false ceiling	-NA-		
	Internal Hydrants	-NA-	100mm	-NA-
	• Size of riser/down-comer	-NA-	2 Nos	-NA-
	Number of hydrants per floor	-NA-	2 Nos	-NA-
	Hose Box	-IVA-		
•	Yard Hydrants	-NA-	6 Nos	-NA-
	 Total number of hydrants 	-NA-	6 Nos	-NA-
	Hose Box	-INA-		
3.	Pumping Arrangements		S.	
	Ground Level	-NA-	2280 LPM	-NA-
	Discharge of main Pump		60m	-NA-
	Head of Main pump	-NA-	One	-NA-
	Number of main pumps	-NA-	180 LPM	-NA-
	Jockey Pump out put	-NA-	60m	-NA-
	Jockey pump head	-NA-	2280 LPM	-NA-
	> Standby Pump out put	-NA-		-NA-
	Standby Pump Head	-NA-	60m	-NA-
	> Auto Starting/Manual Stopping	-NA-	-NA-	-NA-
	Pump House Access	-NA-	Provided	-1471
	Terrace level		222 L DM	MR
	➤ Discharge of pump	900 LPM	900 LPM	MR
	> Head of the pump	40m	45m	MR
	> Power Supply	Required	Provided	MR
	> Auto Starting of pump	Required	Provided	IVIIX
	Captive Water Storage for fire fighting			-NA-
14.	Underground tank capacity	-NA-	75,000 Lts	-NA-
	> Draw-off connection	-NA-	Provided	-NA-
	Fire service inlet	-NA-	-NA-	-NA-
	> Access to tank	-NA-	-NA-	
	Overhead Tank capacity	10,000 Lts.	10,000 Lts.	MR
		Required	Provided	MR
15.	Exit Signage. Provision of Lifts.			NT A
16.	D intion of Lift Shaft	-NA-	-NA-	-NA-
	 Pressurization of Lift lobby 	-NA-	-NA-	-NA-
	Communication In lift Car	Required	Provided	MR
	Fireman's Grounding Switch	Required	Provided	MR
	Lift Signage	Required	Provided	MR
-		Required	Provided	MR
17				
18	Refuge Area.	-NA-	-NA-	-NA-
	> Total Area	-NA-	-NA-	-NA-
	> Location	-NA-	1111	
19	9. Fire Control Room	NIA	-NA-	-NA-
	Detector System Panel	-NA-	-NA-	-NA-
	 Flow Switch Panel 	-NA-		-NA-
	PA System Panel	-NA-	-NA-	-NA-
	Battery backup	-NA-	-NA-	-NA-
	Building Floor Plans	-NA-	-NA-	
	20. Special Fire Protection System for Pro		I. if any	-NA-

Ameya Guest House, Plot No. 6, 1st, 2nd and 3rd Floor, FC-33 Jasola, New Delhi-110025

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Accordingly reply letter in shape of DFA is put up.

Signature of Inspecting Officer

Name: A. K. Malik

Designation: Divisional Officer

DY. CFO (FPW)

This deport had already in formed the mind member is not covered under Act who composition is same so B+4+3 upper. I do composition is same so B+4+3 upper.