GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110 001

No. F6/DFS/MS/School/SZ/ 20/6/153/

Dated: / 3/10/16

FIRE SAFETY CERTIFICATE

Certified that M/s N. P. Co-ed Senior Secondary School, located at Bapu Dham, San Martin Road, Chankyapuri, New Delhi, comprised of ground plus one upper floor only, owned/occupied by New Delhi Municipal Council was granted Fire Safety Certificate by this department vide letter No. F6/DFS/MS/School/2013/SZ/1066, dated 11-10-2013. The premises was re-inspected by the officer concerned of this department on 22.09.2016 in the presence of Mrs. Asha Datt, Principal of the school & Mr. Sajjan Kumar, Fire Officer, NDMC and found that the said school building have deemed complied with the fire prevention and fire safety requirements in accordance with the circular issued by the Director of Education dated 17.01.2005 and that the premises is fit for occupancy class "B" educational building with effect from 1.9. 1.9. 2016 for period of three years.

Issued 1.9/10/... 2016 at New Delhi by.

(Vipin Kental)

Chief Fire Officer
T.No.011-23412225

- To:- 1. The Principal, N. P. Co-ed Secondary School, located at Bapu Dham, San Martin Road of Chankyapuri, New Delhi.
 - 2. Sh. Ajay Kumar, Fire Officer, NDMC, Palika Kendra, New Delhi-110001.
 - 3. The Director of Education, GNCTD, Old Secretariat, Delhi-110052.

Conditions for the validity of fire safety certificate are as under:-

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. The employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All fire fighting equipments shall be maintained in perfect working condition all time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate in form J. six month prior to its expiry.

		A the ballang	Martin F	Co-ed Seni	or Secondary School, located at Bapu apuri, New Delhi.	Dham, San		
	2	Type of Occupancy		onal Building				
	3	Type of case	Renewa					
	4	Details of previous NOC			ol/2013/SZ/1066, Dated 11.10.2013.			
	5	Fire safety directives letter No			- 17.01.2005.			
		Date of inspection			17.01.2005.			
	6	Name of the inspecting Officers	22.09.2016 A.D.O. Vedpal.					
	7	Name and designation of officers						
		from the building side	NDMC.	Mrs. Asha Datt, Principal of the school & Mr. Sajjan Kumar, Fire Officer, NDMC.				
	9	Building Comprised of	Ground r	olus one uppe	er floor			
	10	Year of construction	1971					
	11							
		Applicant's letter No.		Nil, Dated 02.09.2016.				
	S. NO.	Minimum Standards on fire prevention and fire safety U/R 33	Director Circular	ment as per r Education No. 262-362 2005.		Remarks MR / NMR		
-	1	Access to building						
		1) Road width	Accessib	le.	12m	MR		
		Gate width Width of internal road	N/A		4.25m	N/A		
-	2		N/A			N/A		
-		Number, width Type & arrangement of a. Number of staircases	exits					
		1. Upper floors	03nos		03nos.	MS		
		2. basements	· ·	1		MR		
		b. Width of staircase	N/A		N/A	N/A		
		The Control of Control	1.5m &yc	n 1.5m 8	1.38m, 1.07m & 1.11m			
		Upper floors basements	N/A	95 1 444	N/A	MR		
		c. Protection of exits	111//		N/A	N/A		
		1. Fire check door	N/A		N/A	NICO		
		2. Pressurization	N/A		N/A	N/A N/A		
		d. No. of continuous staircase to	01no.	-	01no.	MR		
		e. Width of corridor	N/A					
		f. Door size	1 Mtr	el l	N/A	N/A		
	3	Compartmentation.			1Mtr Provided	MR		
		1. Fire check door	N/A		N/A	N/A		
		2. Sealing of electrical shafts	N/A	N	N/A	N/A		
		3. Fire Rating of shaft door	N/A	N	N/A	N/A -		
200		4. water curtain5. Fire dampers	N/A		N/A	N/A		
	4	Smoke Management system.	N/A	N	N/A	N/A		
		basement system.	30 a/c per	hour In	J/A			
		Upper Floors	12 a/c per l	2011r	Vatural Ventilation	N/A MR		
		Fire Extinguishers				IVIIX		
		total numbers	08nos.	0	8nos.	MR		
			ABC & WC ISI Mark	A	BC & Water CO2	MR		
	6	ISI marking First-Aid Hose Reels.		15	SI Mark	MR		
		1-1-1	02nos.	10:	2nos.			
	-	Lacati Citi	30m			MR		
	TO 17500		6.5mm		0m 5mm	MR		
	7	Automatic fire detection and alarming sy				MR		
		Type of detectors	N/A	N	/A	N/A		
- N			N/A		1.0	N/A		
		A 14 1	1/A N			N/A		
					/A	N/A		
		MOSE.	N/A	N/		N/A		
		D. L.I.	N/A N/A	N/		N/A		
		Automatic Sprinkler System.	WA	Pr	ovided	N/A		
	ŀ	basement	N/A	N/.	A	NI/Å		
			N/A	N/		N/A N/A		
100						V//Y		

		1010	
al Hydrants			
riser/down-corner	N/A	N/A	IN/A
er of Hydrants per floor	N/A	N/A	N/A
OX	N/A	N/A	NIA

11	Internal Hydrants			
	Size of riser/down-corner	N/A	N/A	N/A
	Number of Hydrants per floor	N/A	N/A	N/A
	hose Box	N/A	N/A	N/A
12	Yard Hydrants.		•	
	total number of hydrants	. N/A	N/A	N/A
****	hose box	N/A	N/A	N/A
13	Pumping arrangements		1	
	1. Ground level	N/A	N/A	N/A
	a. Discharge of main Pump	N/A	N/A	N/A
	b. Head of main pump	N/A	N/A	N/A
	c.Number of main pumps	N/A	N/A	N/A
	d.jockey pump out put	N/A	N/A	N/A
	e jockey pump head	N/A	N/A	
	f. Standby Pump output	N/A	N/A	N/A
	g.Stanby Pump head	N/A	N/A	N/A
	h.Auto Starting/Manual stopping	N/A	N/A	N/A
	pump house access	N/A	N/A	N/A
	2.Terrace level	14// (IN/A	N/A
	a. Discharge of pump	220LPM	450LPM	IMR
	b. head of the pump	40m		
	c. Power supply		40m	MR
	d Auto starting of pump	Required	Provided	MR
4		Required	Provided	MR
	Captive water storage for fire fight	ng		
	1. Underground tank capacity	N/A	N/A	N/A
	a. Draw-off connection	N/A	N/A	N/A
	b. fire service inlet	N/A	N/A	N/A
	c.Access to tank	N/A	N/A	N/A
	Over head tank Capacity	2500 Liters	2500 Liters	MR
5	Exit Signage.	Required	Provided	MR
6	Provision of lifts.		-	17/2
	a. Pressurization of lift shaft	N/A	N/A	N/A
	b. pressurization of lift lobby	N/A	N/A	N/A
	c. communication in lift car	N/A	N/A	N/A
	d. Fireman's grounding switch	N/A	N/A	N/A
	e. Lift signage	N/A	N/A	N/A
7	Standby power supply	N/A	N/A	
8	Refuge Area.		Not Required	N/A
	total area	N/A	N/A	N/A
	location	N/A	N/A	
9	Fire control room		IN/A	N/A
	a. detector system Panel	N/A	N/A	
	b. Flow switch Panel	N/A		N/A
	c. PA system Panel	N/A	N/A	N/A
	d. Batter backup		N/A	N/A
	e. Building floor plans	N/A	N/A	N/A
	Special Fire Protection systems for	N/A	N/A	N/A

The fire protection systems provided in the building were test checked at random and found functional at the time of inspection. In view of the deemed compliance of the minimum standards on fire prevention and fire safety required under circular of Director of Education dated 17.01.2005, the FSC issued vide letter No: F6/DFS/MS/School/2013/SZ/1066, dated 11.10.2013, renewal under rule 37 of the Delhi Fire Service Rule 2010 is recommended.

Accordingly DFA is put up for your approval and signature please.

Signature of the inspecting officer

Name: Vedpal

Designation : ADO