GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS : DELHI FIRE SERVICE : NEW DLEHI - 110 001

No. F.6/DFS/MS/FH/2016/SZ/

Dated: 21/10/16

FIRE SAFETY CERTIFICATE

Certified that the The Destination Farm House, Kh. No. 662/1, 662/2, Village Chatterpur, Tehsil Mehrauli, New Delhi comprised of Sunken basement & ground floor. The Farm House was inspected by the officer concerned of this department on 19/10/16 in the presence of Mr. Varun & found to have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010and that the building is fit for occupancy class D "Assembly Building Farm House" with effect 21/10/20 2016 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued on. 2.1. ... at New Delhi by.

(Vipin Kental) Chief Fire Officer Ph:-011-23412235

Copy to:-

1. The Assistant Engineer (Bldg), SDMC, South Zone, Green Park, New Delhi.

2. Sh. Varun, The Destination Farm House, Kh. No. 662/1, 662/2, Village Chatterpur, Tehsil Mehrauli, New Delhi.

Conditions for the validity of fire safety certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of firefighting system.

- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 5. This fire safety certificate may not in any way be treated as regularization of unauthorized construction, if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

INSPECTION REPORT : The Destination Farm House, located at Kh. No. 662/1, 662/2, Name & address of the building Village Chatterpur, Tehsil Mehrauli, New Delhi : Assembly Building Group "D" (Farm House) Type of Occupancy 2. : New Type of Case 3. : NA 4. Details of Previous NOC : NIL 5. Fire Safety directives letter No : 19/10/16 6. Date of inspection : A.K. Malik 7. Name of Inspecting Officer 8. Name and designation of officers : Sh. Varun From the building side : 1993 [Sunken basement &ground floor (with standalone Toilet)] 9. Year of Construction : Nil Dated Nil, received in outdoor diary no. 9876 dated 27/09/16 10. Applicant's letter No. Remarks Provided at site Minimum Standards on fire prevention **NBC** S. MR/NMR Requirement and fire safety U/R 33 No. Access to building MR 30m 9 m Road width MR One of 10m& Two of 6m 5 m Gate width 15m MR 6m Width of internal road Number, Width, Type & Arrangement of Exits 2. a. Number of staircases -NA--NA--NA-Upper Floors -NA-One -NA- [Sunken Basements basement (open to ground)] b. Width of staircases Upper Floor -NA--NA--NA--NA-**Basements** 0.90m -NAc. Protection of exits -NA--NA--NA-Fire check door -NA--NA--NA-Pressurization MR -NA--NA- (Sloping d. No. of continuous staircases to terrace roof) e. Width of Corridor -NA--NA--NA-Door Size MR 1m (final exit) 1 m Compartmentation 3. -NA--NA--NA-Fire check door -NA--NA--NA-Sealing of electrical shafts -NA-Fire Rating of shaft door -NA--NA-Water Curtain -NA--NA--NA-Fire Dampers -NA--NA--NA-Smoke Management System 4. -NA-Natural Ventilation -NA-Basements -NA-Natural Ventilation -NA-Upper floors Fire Extinguishers 5. MR 20 No's Total numbers MR ABC-10 No's, 4 No's Types W.Co₂-10No's IS marking MR ISI Yes First-Aid Hose Reels 6. MR Provided One Total numbers on each floor MR Provided 30 m Length of hose reel hose MR Provided 5 mm Nozzle diameter Automatic fire detection and alarming system 7. -NA--NA--NA-Type of detectors -NA--NA-Location of Main Panel -NA--NA-Location of Repeater Panel -NA--NA--NA-Alternate source of power -NA--NA--NA-Hooters' Location -NA--NA-MR Provided Required **MOEFA** -NA-8. -NA-NA.

Chatterpur, Tehsil Mehrauli, New Delhi

T	The Destination Farm House, Kh. No. 662/1, Ground Floor	-NA-	1112	-NA-			
	Sprinkler above false ceiling	-NA-	-NA-				
Int	ternal Hydrants		Provided	MR			
1111	Size of riser/down-comer	100 mm	1	MR			
	Number of hydrants per floor	1	1	MR			
	Hose Box	1	, 1				
. Y:	ard Hydrants		6 No's provided	-NA-			
-	Total number of hydrants	-NA-	6 No's provided	-NA-			
	Hose Box	-NA-	6 No s provided				
. P	Pumping Arrangements						
. 1	Ground Level		-NA-	-NA-			
	Discharge of main Pump	-NA-	-NA-	-NA-			
	Head of Main pump	-NA-	-NA-	-NA-			
	Number of main pumps	-NA-		-NA-			
	Jockey Pump out put	-NA-	-NA-				
	Jockey pump head	-NA-	-NA-	-NA-			
	Standby Pump out put	-NA-	-NA-	-NA-			
	Standby Pump Head	-NA-	-NA-	-NA-			
	> Auto Starting/Manual	-NA-	-NA-	-NA-			
	Stopping	NIA	-NA-	-NA-			
	Pump House Access	-NA-	Standalone Toilet with 0.	75m (Iron) staircase]			
	Terrace level	450 LPM	Provided	IVIIC			
	Discharge of pump	430 El W	Provided	MR			
	> Head of the pump	Required	Provided	MR			
	> Power Supply	Required	Provided	MR			
	Auto Starting of pump	require					
14.	4. Captive Water Storage for fire fighting						
14.		-NA-	-NA-	-NA-			
	 Underground tank capacity Draw-off connection 	-NA-	-NA-	-NA-			
	Fire service inlet	-NA-	-NA-	-NA-			
	> Access to tank	-NA-	-NA-	-NA-			
	 Overhead Tank capacity 	10000 Ltr.	Provided	MR			
		Required	Provided	MR			
15.	5. Exit Signage.						
16.	Provision of Lifts.	-NA-	-NA-	-NA-			
	Pressurization of Lift Shaft CL: 0 labby		-NA-	-NA-			
	Pressurization of Lift lobby Continue In lift Car The state of the l	-NA-	-NA-	-NA-			
	Communication In lift Car Crounding Switch		-NA-	-NA-			
	• Fireman's Grounding Switch	-NA-		-NA-			
	Lift Signage	-NA-	-NA-				
15	Standby power supply	Required	Provided	MR			
17.	7. Standby power suppry						
18.	Refuge Area. > Total Area	-NA-	-NA-	-NA-			
	> Total Area > Location	-NA-	-NA-	-NA-			
19.							
19.	Detector System Panel	-NA-	-NA-	-NA-			
		-NA-	-NA-	-NA-			
	Flow Switch Panel		-NA-	-NA-			
	PA System Panel	-NA-		-NA-			
	Battery backup	-NA-	-NA-				
	 Building Floor Plans 	-NA-	-NA-	-NA-			
20	Special Fire Protection System for Protection of special Risks, if any:	-NA-	-NA-	-NA-			
	The fire protection systems provided in	n the building wer	e tested, checked and	found function			

	Building Floor Plans Special Fire Protection System for Protection of special Risks, if any:	-NA-	-NA-	-NA-	
20.		-NA-	-NA-	-NA-	
Tł	ne fire protection systems provided in the building were tested, checked and found functional at				

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

The Destination Farm House, Kh. No. 662/1, 662/2, Village Chatterpur, Tehsil Mehrauli, New Delhi

The Destination Farm House, Kh. No. 662/1, 662/2, Village Chatterpur, Tehsil Mehrauli, New Delhi Accordingly DFA is put up for approval and signature.

Signature of Inspecting Officer

Name: A. K. Malik Designation: DO (SD)

Dy. CFO (SZ)

20/2

m'scell

FT/01.

2.9/1/16

f.f. ufret uf

In chable

1600

miscey Will