GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

No. F.6/DFS/MS/FH/2016/SZ/ 16 2 2

Dated:

57-11-16

FIRE SAFETY CERTIFICATE

Certified that the Farm House at Kh. No. 242, 242(min), 235/2, 241 and 242/2 (min), Bhatti Village, Chatterpur Road, New Delhi comprised of ground floor only. The Farm House was inspected by the officer concerned of this department on 31/10/16 in the presence of Mr. Shivam Gupta & found to have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class D "Assembly Building Farm House" with effect ---- 0-3-14/1/2 2016 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued on . G. J. at New Delhi by.

(Vipin Kental) Chief Fire Officer Ph:-011-23412235

Copy to:-

1. The Assistant Engineer (Bldg)-II, SDMC, South Zone, Green Park, New Delhi.

2. Sh. Shivam Gupta, Kh. No. 242, 242(min), 235/2, 241 and 242/2 (min), Bhatti Village Chatterpur Road, New Delhi.

Conditions for the validity of fire safety certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of firefighting system.

4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.

5. This fire safety certificate may not in any way be treated as regularization of unauthorized

construction, if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

Farm House at Kh. No. 242, 242(min), 255/2, 241 and 242/2 (min), INSPECTION REPORT : Farm House at Kh. No. 242, 242(min), 235/2, 241 and 242/2 Name & address of the building (min), Bhatti Village Chatterpur Road, New Delhi : Assembly Building Group "D" (Farm House) Type of Occupancy 2. Type of Case : NA 4. Details of Previous NOC : NIL 5. Fire Safety directives letter No : 31/10/16 6. Date of inspection : A. K. Malik 7. Name of Inspecting Officer Name and designation of officers : Sh. Shivam Gupta [Ground floor only] From the building side : D-1349/AE(B)-II/SZ/2016 dated 14/10/16 from AE(Bldg.)-II, South Zone 9. Year of Construction Nil Dated Nil, received in outdoor diary no. 10586 dated 17/10/16 10. Applicant's letter No. Remarks Provided at site Minimum Standards on fire prevention **BBL 1976** MR/NMR S. Requirement and fire safety U/R 33 No. Access to building MR 30m 1. Accessible Road width MR 2 x 4.5m Accessible MR Gate width 6m Accessible Width of internal road Number, Width, Type & Arrangement of Exits 2. a. Number of staircases -NA--NA--NA-Upper Floors -NA--NA--NA-Basements b. Width of staircases -NA--NA--NA-Upper Floor -NA--NA--NA-Basements c. Protection of exits -NA--NA--NA-Fire check door -NA--NA--NA-Pressurization -NAd. No. of continuous staircases to terrace -NA--NA--NA--NA-Width of Corridor -NA-MR 2 feet 8 inch (final exit) Door Size 2 feet 8 inch Compartmentation 3. -NA--NA--NA-Fire check door -NA--NA-Sealing of electrical shafts -NA--NA-Fire Rating of shaft door -NA--NA--NA-Water Curtain -NA--NA--NA-Fire Dampers -NA--NA-Smoke Management System 4. -NA--NA--NA-Basements -NA--NA--NA-Upper floors Fire Extinguishers MR 5. 20 No's Total numbers MR ABC-10 No's, 4 No's Types W.Co₂-10No's IS marking MR ISI Yes First-Aid Hose Reels MR 6. Provided One Total numbers on each floor MR Provided 30 m Length of hose reel hose MR Provided 5 mm Nozzle diameter Automatic fire detection and alarming system -NA-7. -NA--NA-Type of detectors -NA--NA-Location of Main Panel -NA-

Location of Repeater Panel

Alternate source of power

Hooters' Location

MOEFA

-NA-

-NA-

-NA-

MR

-NA-

-NA-

-NA-

-NA-

Provided

-NA-

-NA-

-NA-

Required

	Farm House at Kh. No. 242, 242(min), 233/2, 27	-NA-	-NA-	-NA-
	Ground Floor	-NA-	-NA-	-NA-
	Sprinkler above false ceiling	-NA-		
Int	ernal Hydrants	100 mm	Provided	MR
	• Size of riser/down-comer	1	1	MR
	Number of hydrants per floor	1	1	MR
	Hose Box			
Ya	ard Hydrants	-NA-	6 No's provided	-NA-
	Total number of hydrants	-NA-	6 No's provided	-NA-
	Hose Box	-1471		
Pu	umping Arrangements			
	Ground Level	-NA-	-NA-	-NA-
	Discharge of main Pump	-NA-	-NA-	-NA-
	Head of Main pump	-NA-	-NA-	-NA-
	Number of main pumps		-NA-	-NA-
	Jockey Pump out put	-NA-	-NA-	-NA-
	Jockey pump head	-NA-	-NA-	-NA-
	Standby Pump out put	-NA-		-NA-
	Standby Pump Head	-NA-	-NA-	-NA-
	Auto Starting/Manual	-NA-	-NA-	-NA-
	Stopping	-NA-	-NA-	
	> Pump House Access		(On standalone platform	n)
	Terrace level	450 LPM	Provided	MR MR
	Discharge of pumpHead of the pump	40 mtr	Provided	MR
	2 1	Required	Provided	MR
9	Power SupplyAuto Starting of pump	Required	Provided	IVIIC
4.	Captive Water Storage for fire fighting		-NA-	-NA-
	 Underground tank capacity 	-NA-	-NA-	-NA-
	> Draw-off connection	-NA-		-NA-
	Fire service inlet	-NA-	-NA-	-NA-
	> Access to tank	-NA-	-NA- Provided	MR
	Overhead Tank capacity	10000 Ltr.	Provided	MR
15.	Exit Signage.	Required	Flovided	
16.	Provision of Lifts.			-NA-
10.	n intim of Lift Shaft	-NA-	-NA-	
	pigation of I ift lobby	-NA-	-NA-	-NA-
	Communication In lift Car	-NA-	-NA-	
	Fireman's Grounding Switch	-NA-	-NA-	-NA-
	• Lift Signage	-NA-	-NA-	-NA-
-			Provided	MR
17.	Standby power supply	Required	1101146	
18.		271	-NA-	-NA-
10.	> Total Area	-NA-	-NA-	-NA-
	Location	-NA-	1111	
19	. Fire Control Room		-NA-	-NA-
	Detector System Panel	-NA-		-NA-
	Flow Switch Panel	-NA-	-NA-	
	PA System Panel	-NA-	-NA-	-NA-
	D. u bookun	-NA-	-NA-	-NA-
	D '11' - Floor Plone	-NA-	-NA-	-NA-
			-NA-	-NA-
2	0. Special Fire Protection System for Protection of special Risks, if any:	-NA-	-INA-	

The fire protection systems provided in the building were tested, checked and found functional at

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Accordingly DFA is put up for approval and signature.

Signature of Inspecting Officer Name: A. K. Malik

Designation: DO (SD)

Dy. CFO (SZ) Jan Leave

Plopeak W.

DOSD. Spopen with cfo (52) an 2/21/16. There is
only one ream for bridal use.

dy co (SZ)/on leave