## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No. F.6/DFS/MS/GH/2016/ 1628

Dated: 04/11/16

## FIRE SAFETY CERTIFICATE

Certified that the **Orchid Garden Guest House** located at 51/1, Prabhat Road, D.B.G. Road, Karol Bagh, New Delhi-110005 is comprised of Basement, ground floor plus three upper floors, using basement as storage, ground floor as reception & commercial, first & second floor each having 09 guest rooms respectively, third floor having 06 guest rooms (Total 24 guest rooms) was issued FSC by this department vide letter No.F.6/MS/DFS/GH/2012/4235 dated 12.11.2012 owned/occupied by Sh. Paramjit Singh Hora. The guest house building was re- inspected by the officers concerned of this department on 03.11.2016 in the presence of Sh. Manoj Kumar and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Conditions for the validity of Fire Safety Certificate:

1. All fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc. shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

6. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

7. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.Delhigovt.nic.in.

Issued on all 11 11 c. at New Delhi by.

Chief Fire Officer
Delhi Fire Service

Copy to:-

1. The Joint Commissioner of Police (Lic.)

1<sup>st</sup> floor, P.S., Defence Colony, New Delhi.

(Re. No. 2629/Joint C.P./Lic.(H), Dated 19.09.2016)

2. Sh. Paramjit Singh Hora (Owner), Orchid Garden Guest House, 51/1, Prabhat Road, D.B.G. Road, Karol Bagh, New Delhi-110005.

**INSPECTION REPORT** G.H Orchid Garden, 51/1, Prabhat Road, D.B.G. Road, Karol 1. Name & address of the building Bagh, New Delhi-110005 Residential (Guest House) 2. Type of Occupancy Renewal 3. Type of Case F.6/MS/DFS/GH/2012/4235 dated 12.11.2012 4. Details of Previous NOC 5. Fire Safety directives letter No NA 03/11/2016 6. Date of inspection Dy.CFO Sunil Chaudhary 7. Name of Inspecting Officer 8. Name and designation of officers Sh. Manoj Kumar From the building side 2009 9. Year of Construction Nil dated 29.10.2016 10. Applicant's letter No. Remarks Provided at site NBC/BBL Minimum Standards on fire prevention S. No. MR/NMR Requirement and fire safety U/R 33 Access to building 1. MR Accessible 10 mtr Road width NA NA NA Gate width NA NA NA Width of internal road Number, Width, Type & Arrangement of Exits 2. a. Number of staircases MR, Old Case One One **Upper Floors** MR, Old Case One One Basements b. Width of staircases MR, Old Case Upper Floor 125 cms **Basements** MR, Old case 125 cms c. Protection of exits NA NA NA Fire check door NA NA Pressurization NA d. No. of continuous staircases to terrace MR One One MR 03 mtr 01 mtr e. Width of Corridor MR 01 mtr f. Door Size 01 mtr Compartmentation 3. NA NA NA Fire check door NA NA Sealing of electrical shafts NA Fire Rating of shaft door NA NA NA Water Curtain NA NA NA Fire Dampers NA NA NA Smoke Management System 4. MR Exhaust fans are 30 ACPH Basements provided MR Natural 12 ACPH Upper floors Ventilation Fire Extinguishers 5. MR Provided 08 Nos Total numbers ABC, Co2 MR Provided Types MR Provided IS marking ISI marked First-Aid Hose Reels 6. MR Provided One Total numbers on each floor MR Provided 30 m Length of hose reel hose 5 mm MR Provided Nozzle diameter

	Automatic fire detection and alarming sys	stem		DIA
	Type of detectors	NA	NA	NA
	<ul> <li>Location of Main Panel</li> </ul>	NA NA	NA	NA
	<ul> <li>Location of Repeater Panel</li> </ul>	NA –	NA	NA
	<ul> <li>Alternate source of power</li> </ul>	NA -	NA	NA
		NA NA	NA	NA
2.		Required	Provided	MR
8	MOEFA Public Address System	Required	Provided	MR
).	Automatic Sprinkler System		2	1.00
).	Basement	Required	Provided	MR
	Busement	NA	. NA	NA
	Ground Floor	NA	NA	NA
	Sprinkler above false ceiling			
1.	Internal Hydrants		271	NA
1.	Size of riser/down-comer	NA	NA	NA NA
	<ul> <li>Number of hydrants per floor</li> </ul>	NA	NA	NA
	Hose Box	NA	NA	INA
2.	Yard Hydrants			NT A
	Total number of hydrants	NA	NA	NA
	Hose Box	NA	NA	NA
3.	Pumping Arrangements			
J.	Ground Level			
	<ul><li>Discharge of main Pump</li></ul>	NA	NA	NA
	Head of Main pump	NA	NA	NA
	Number of main pumps	NA	NA	NA
	Jockey Pump out put	NA	NA	NA
	Jockey pump head	NO THE	NA	NA
	Standby Pump out put	NA		NA
	Standby Pump Head	NA	NA	
	Auto Starting/Manual	NA	NA	NA
	Stopping	NA	NA	, NA
	Pump House Access			
	Terrace level	450 LPM	450 LPM	MR
	Discharge of pump	30 M	30 M	MR
	> Head of the pump		Provided	MR
	> Power Supply	Required	NA	NA
	Auto Starting of pump	NA	INA 1	11/1
		:		
14.	Captive Water Storage for fire fighting	NA NA	NA	NA
	Underground tank capacity	NA	NA	NA
	> Draw-off connection		NA NA	NA
	Fire service inlet	NA	NA NA	NA
	> Access to tank	NA		MR
	Overhead Tank capacity	5000 ltr	10000 ltr.	MR
15.	Exit Signage.	Required	Provided	IVIIX
	Provision of Lifts.			ſ
16.	- ' Line of Lift Chaft	NA	NA	NA
,	a time of lift lobby	NA	NA	NA
	Pressurization of Lift lobby     Communication In lift Car	Required	Provided	MR
				MR
	<ul> <li>Fireman's Grounding Switch</li> </ul>	Required	Provided	IVIIV

-	Standby power supply	Required	Provided	MR
17.				
18.	Refuge Area.		*	
10.	> Total Area	NA	NA	NA
	> Location	NA	NA	NA
19.	Fire Control Room			
19.	Detector System Panel	NA	NA	NA
	Flow Switch Panel	NA	NA	NA
	<ul> <li>PA System Panel</li> </ul>	NA	NA	NA
	Batter backup	NA	NA	NA
	<ul> <li>Building Floor Plans</li> </ul>	NA	NA	NA

The hotel management has rectified all the shortcomings communicated by this department and the fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter No. F.6/MS/DFS/GH/2012/4235 dated 12.11.2012 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Signature of Inspecting Officer

Signature of Inspecting Officer

Name:- Sunil Chaudhary

Name

Designation:- Dy. Chief Fire Officer

Designation

M. Scell. bently