GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/2016/SZ/ 1797

Dated: 16/12/16

FIRE SAFETY CERTIFICATE

Certified that the Guest House Sri Nanak Continental, 2222 Hardhyan Singh Road, Karol Bagh, New Delhi- 110005 comprised of Basement, ground floor plus three upper floors, using basement as one office & hall running vacant, ground floor as reception and shops, first floor having nine guest rooms, one office & one store room, second floor having eight guest rooms & third floor having nine guest rooms, one office & one store room (Total Twenty six guest rooms), A staff kitchen with temporary shed on terrace owned/occupied by M/s Guest House Sri Nanak Continental was issued FSC by this department vide letter no. F.6/DFS/MS/GH/2013/SZ/482 dated 25.6.2013. The guest house building was re-inspected by the officers concerned of this department on 28.11.2016 in presence of Sh. Sandeep Khandelwal (Owner) and found that Guest House Sri Nanak Continental have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi fire service Rules 2010 and that the building/premises is fit for occupancy class "Residential" (Guest house) w.e.f the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on 16/12/16 at New Delhi.

(VIPIN KENTAL)
CHIEF FIRE OFFICER

Copy to: -

- The Joint C.P (Lic.), Police Station,
 Defence Colony, 1st floor, New Delhi,
- The Manager,
 M/s Guest House, Sri Nanak Continental,
 2222 Hardhyan Singh Road, Karol Bagh, New Delhi- 110005

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

Name & address of the building: M/s Guest House, Sri Nanak Continental, 2222 Hardhyan Singh Road,

Karol Bagh, New Delhi- 110005

Type of Occupancy Residential (Guest House) 3. Type of Case Renewal

4. Details of Previous NOC F.6/DFS/MS/GH/2013/SZ/482 dated 25.6.2013

5. Fire Safety directives letter No N/A 6. Date of inspection 28.11.2016

7. Name of Inspecting Office D.O. M.K. Chattopadhyay & A.D.O. Sandeep Duggal

8. Name and designation of officers

From the building side Sh. Sandeep Khandelwal (Owner)

9. Year of Construction Before 1994

10. Applicant's letter No. Nil dated 21.10.2016

The said guest house is comprised of basement (one office & Hall), ground floor (Reception & shops), first floor (09 Guest rooms, 01 office & 01 store room), second floor (08 guest rooms) & third floor having (09 guest rooms 01 office & 01 store

S. No.	otal 26 guest rooms) & a staff kitchen with temporar Minimum Standards on fire prevention	Requirement as pe	Provided at	Remarks
	and fire safety U/R 33	FSC dt. 25.6.2013	site	
1.	Access to building		Site	MR/NMR
	Road width	06 mtrs.	12 mtrs	MR
	Gate width	N/A	180 cms	N/A
	 Width of internal road 	N/A	N/A	N/A N/A
2.	Number, Width, Type & Arrangement	of Exits		IV/A
	a. Number of staircases			
	Upper Floors			
	Basements	01	01	MR, being old cas
	b. Width of staircases	01	01	MR, being old cas
	Upper Floor	U1	_	
	Basements	-	100	- 1
		Old case	100 cms	MR, being old case
	c. Protection of exits	Old case	120 cms	MR, being old case
	• Fire check door		8	
	Pressurization	N/A	N/A	N/A
		N/A	N/A	N/A
	d. No. of continuous staircases to			11/11
	terrace	Paguirad	0.1	MD
	e. Width of Corridor	Required	01	MR
	f. Door Size	125 cms	165 & 125 cms	MR
•	Composition 4 ii	Old case	83 cms	MR being old case
•	Compartmentation			
	Fire check door	N/A	N/A	N/A
	Sealing of electrical shafts Fire Rating of shaft door	N/A	N/A	N/A
	Fire Rating of shaft doorWater Curtain	N/A	N/A	-
	Fire Dampers	N/A		N/A
	The Bampers	N/A	N/A	N/A
	Smoke Management System	11//1	N/A	N/A
	Basements	Required	F 1 . C	
		Required	Exhaust fans	MR
	Upper floors	Required	are provided Natural ventilation	
		Required	provided	MR
4	Fire Extinguishers			
	Total numbers	03 no's at each floor	Provided	MR
	• Types	WCO ₂ / CO ₂ /ABC type	Provided	MR
	• 18 marking	ISI marked	Provided	MR
	First-Aid Hose Reels		-1011404	IVIIX
	Total numbers on each floor	01 no./floor	Provided	MO
	Length of hose reel hose	30 m	Tiovided	MR

7.	Automatic fire detection and alarming s	system		
	Type of detectors	N/A	N/A	N/A
	 Location of Main Panel 	N/A	N/A	N/A
2	 Location of Repeater Panel 	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
e este	Hooters' Location	N/A	N/A	N/A
8.	MOEFA	Required	Provided	
				MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	Basement	Required	Provided	MR
	Ground Floor	N/A	N/A	N/A
11	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	Size of riser/down-comer	N/A	N/A	N/A
	 Number of hydrants per floor 	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants			-
	Total number of hydrants	N/A	N/A	N/A
·	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements		1771	11//11
18	Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	> Head of Main pump	N/A	N/A	N/A
,	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out putJockey pump head	N/A	N/A	N/A
	> Standby Pump out put	N/A		
	Standby Pump Head		N/A	N/A
	> Auto Starting/Manual	N/A	N/A	N/A
	Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
	Pump House AccessTerrace level	N/A	N/A	N/A
	Discharge of pump	450 LPM	Provided	MR
	Head of the pump	30 mtrs	Provided	MR
*	Power Supply	Required	Provided	MR
	Auto Starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A N/A		
	> Access to tank	N/A N/A	N/A	N/A
	Overhead Tank capacity	COS NOT THE COST	N/A	N/A
15.	Evit Signage	Old case	5000 ltrs provided	MR being old case
16.	Exit Signage. Provision of Lifts.	Required	Provided	MR
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A N/A
	Fireman's Grounding Switch		Provided	
	Lift Signage	Required Required		MR
BYIN T	believed Periodical Provided	Required	Provided	MR
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area.	4, 150, 51	OLT WAY-151 A	· · · · · · · · · · · · · · · · · · ·
N. Z. C. C. C. William				

:

D/32

19.	Fire Control Room			
	 Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans 	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were checked and found functional at the time of inspection and the shortcomings communicated vide letter no. F.6/DFS/MS/GH/2016/1772 dated 21.7.2016 in respect of above said guest house has been complied.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/GH/2013/SZ/482 dated 25.6.2013, renewal under rule 37 of the Delhi Fire Service rules 2010 is recommended.

Signature of Inspecting Officer

Name: - M.K. Chattopadhyay

Designation: - Divisional Officer

Signature of Inspecting Officer

Name:- Sandeep Duggal

Designation:- Asstt. Divisional Officer

Dy. C.F.O (South Zone)

Diany to 25

Cho (Sh

FTB: WE

m-scell