GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

Fax No. 011-23412593, Ph. 011-23412225

No. F6/DFS/MS/EH/SZ/2016 1837

Dated: 26/12/2016

FIRE SAFETY CERTIFICATE

Certified that M/s Mocha (A Unit of Impresario Entertainment & Hospitality Pvt. Ltd.) located at Shop No. 167, Ground Floor, DLF Promenade Mall, Vasant Kunj, New Delhi, building comprised of 2 tier basement, lower ground, upper ground, first floor and projection room. The restaurant running at ground floor (lower ground floor as per Mall Fire NOC) was granted FSC by this department vide letter No. F.6/DFS/MS/ EH/2012/4262 Dated 14/11/2012. The premises was re-inspected by the officer concerned of this department on 08.12.2016 in the presence of Mr. Vikash Chandra (Manager) of the restaurant and observed that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fir for occupancy class Group-D "Assembly Building" (Restaurant) with effect from 26/12/2016 for a period of Three years in accordance with rule 36 unless renewed under rile 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 16 at New Delhi by

Vipin Kental
Chief Fire Officer

Copy to: -

- 1. M/s Mocha (A Unit of Impresario Entertainment & Hospitality Pvt. Ltd.), Shop No. 167, Ground Floor, DLF Promenade Mall, Vasant Kunj, New Delhi -110070
- 2. The Dy. Health Officer, South Zone, S.D.M.C. Health Depart, Green park, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety and means of escape facilities shall be maintained in good working condition at all time. Any lapse rendering the fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
- Building Sanctioning authority may verify any deviation with regard to construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null & void.
- 3. The staff shall be trained for operating fire fighting system and mock evacuation drill be conducted at regular interval and record be maintained.
- 4. The basement shall be used strictly as per the provisions of Building Bye Laws.
- 5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in.
- 6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

1	INSPECTION REPORT Name & Address of the Building M/s MOCHA (A Unit of Impresari						
1	Name & Address of the Building						
			Ltd.), Shop No. 167, Grou				
	T		Mall, Vasant Kunj, New				
2	Type of Occupancy	Assembly Building "Group-D" Restaurant					
3	Building Comprised of		, lower ground, Upper g	ground, fire			
		floor and projecti	ion room.				
4	Type of Case	Renewal F.6/DFS/MS/EH/2012/4262 Dated 14/11/2012					
5	Details of Previous NOC		/2012/4262 Dated 14/11/2	2012			
6	Fire Safety Directives Letter No	Nil					
7	Date of Inspection	08.12.2016					
8	Name of the Inspecting Officers	ADO R.N. Singh					
9	Name & Designation of Officers Mr. Vikash Chandra (Manager)						
15	from the building side						
10	Year of construction	2008 Restaurant is running at ground floor					
11	Applicant letter No.	Nil dated 21/11/2	2016				
S. No	Minimum standards on Fire Prevention	Old NOC	Provided at Site	Remarks			
	and Fire Safety U/R 33	14/11/2012	· · · · · · · · · · · · · · · · · · ·	MR/NMI			
		Requirements	-				
1	Access to Building.	FSC No. F.6/DF	S/MS/2014/SZ/881 date	d. 17/07/14			
	Road width	Required	As Above	MR			
	Gate width	N/A	As Above	N/A			
	Width of internal road	N/A	As Above	N/A			
2	Number, width, type and arrangements of	exits [Provide	ed & Maintained by DLF	Malll			
	a. Number of Staircase		ou to Indianate by Daily				
	Upper floors	Required	As Above	MR			
	Basement floor	N/A	As Above	N/A			
	b. Width of Staircase	Provided & Maintained by DLF Mall					
				N/A			
	Upper floors	Required N/A	As Above As Above	N/A			
	Basement floor						
	c. Protection of exits	Provided & Maintained by DLF Mall					
	Fire check door	N/A	As Above	N/A			
	Pressurization	N/A	As Above	N/A			
	d. No. of continuous staircase to terrace	Required	As Above	MR			
	e. Width of corridor	Required	As Above	N/A			
	f. Door size	2 mtr	2m & 1.5m (final exit)	MR			
3	Compartmentation.	Provided & Maintained by DLF Mall					
	Fire check door.	N/A	As Above	N/A			
	 Sealing of electrical shafts. 	N/A	As Above	N/A			
	 Fire rating of shaft door. 	N/A	As Above	N/A			
	Water curtain	N/A	As Above	N/A			
	Fire dampers.	N/A	As Above	N/A			
4.	Smoke Management system.	Provided & Maintained by DLF Mall					
	Basement	30 a/c per hour	As Above	N/A			
	Upper floors	12 a/c per hour	Exhaust fans provided	MR			
5.	Fire Extinguishers.	1					
٥.	Total numbers	04 No's	04 Nos.	MR			
		ABC/Co2	ABC-04	MR			
	• Types	ISI Marked	Provided	MR			
-	ISI Marking First Aid Hose Pools						
6.	First Aid Hose Reels.	Provided & Maintained by DLF Mall					
	Total numbers on each floor.	One (Near to Restaurant) As Above		MR			
	• Length of hose-reel hose.	30 mtr 05 mm	As Above	MR			
	Nozzle Diameter	U) mm	As Above	MR			

M/s Mocha at DFL Promenade Mall, Vasant Kunj



7	Automatic Fire Detection and Alarming s		led &Maintained by DL	
	Type of detectors	Required	As Above	MR
	 Location of Main Panel 	N/A	As Above	N/A
	 Location of Repeater Panel 	N/A	As Above	N/A
	 Alternate source of power 	Required	As Above	MR
	Hooter's location	N/A	As Above	N/A
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	As Above	N/A
10.	Automatic Sprinkler System		d & Maintained by DLF	Mall
	Basement	N/A	As Above	N/A
	 Upper floors 	Required	As Above	MR
	 Sprinkler above false ceiling 	N/A As Above		N/A
11.	Internal Hydrants.	Provided & Maintained by DLF M		Mall
	 Size of Riser/Down-comer 	100 mm (Near to F	Restaurant) As Above	MR
	 Number of Hydrant per floor 	One (Near to R	destaurant) As Above	MR
	Hose box.	One (Near to Restaurant) As Above		MR
12.	Yard Hydrants.	Provide	d & Maintained by DLF	Mall
	Total number of hydrants.	N/A	As Above	N/A
	• 2. Hose box.	N/A	As Above	N/A
13.	Pumping arrangements.	Provided & Maintained by DLF Mall		
	Ground Level	3		
	Discharge of main pump.	N/A	As Above	N/A
	Head of main pump.	N/A	As Above	N/A
	Number of main pumps.	N/A	As Above	N/A
	Jockey Pump output.	N/A	As Above	N/A
	Jockey Pump head.	N/A	As Above	N/A
	Standby Pump output.	N/A	As Above	N/A
	Standby Pump head.	N/A		
	Auto Starting / Manual Stopping.	N/A	As Above	N/A N/A
	Terrace Level	Provided & Maintained by DLF Ma		
	Discharge of pump.	Required	As Above	MR
	Head of pump.	Required	As Above	MR
	Power supply.	Required	As Above	MR
	> Auto starting of pump.	Required	As Above	MR
14.	Captive water storage for Fire Fighting.	Provided & Maintained by DLF M		
	Underground tank capacity.	N/A	As Above	N/A
	Draw-off connection.	N/A	As Above	N/A
	Fire Service Inlet.	N/A	As Above	N/A
	Access to tank.	N/A	As Above	N/A
	Overhead tank capacity.	Required	· As Above	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.	Provided & Maintained by DLF Mall		
	Pressurization of lift shaft.	N/A	N/A	N/A
	 Pressurization of lift lobby. 	N/A	N/A	N/A
	Communication in lift car.	N/A	N/A	N/A
	• Fireman's switch.	N/A	N/A	N/A
	 Lift signage. 	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided	MR
18.	Refuge Area	- Aleganica	Tioridou	IVIIC
	Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
newal			DFL Promenade Mall, V	

Renewal

M/s Mocha at DFL Promenade Mall, Vasant Kunj



19.	Fire Control Room.	Provided & Maintained by DLF Mall		
	Detector System Panel.	N/A	N/A	N/A
	Flow Switch Panel.	N/A	N/A	N/A
	PA system Panel.	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for the	N/A	N/A	N/A
	Protection of special Risk, if any:			

The Fire protection systems provided in the building were randomly checked and found functional at the time of inspection. The Mall building has been granted FSC vide letter No. F.6/DFS/MS/2014/SZ/881 dated. 17/07/14

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/EH/2012/4262 Dated 14/11/2012, renewal under rule 37 of the Delhi Fire Service rules, 2010

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name : R.N. Singh

Designation: ADO

Renewal

M/s Mocha at DFL Promenade Mall, Vasant Kunj

Div. Officer (SD)