GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

No. F.6/DFS/MS/Mall/SZ/2018/ 33

Dated: 0 9 (01 (7

FIRE SAFETY CERTIFICATE

Certified that the Ambiance Mall, located at Plot No.2, Nelson Mandela Road, Vasant Kunj, New Delhi comprises of three tier Basement, Ground floor and 3 Upper Floors was granted FSC by this department vide letter No. F6/DFS/MS/2013/SZ/1140 dated 30/10/2013. The premises was reinspected by the officer concerned of this department on 27/12/2016 in the presence of Mr. I. P. Singh (Chief Security Officer) and found that the said Mall building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Mixed Occupancy (Mercantile & Assembly)" with effect from - 10-3-1-0+1-2016 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued on....0.9.1.1.1...at New Delhi by.

(Vipin Kental) Chief Fire Officer Tel: 011-23412225

Copy to:-

1. The Joint Director (Bldg.), C & I, DDA, Vikas Sadan, INA, New Delhi

2. Sh. Vinod Garg (Authorized Signatory), Ambiance Mall, located at Plot No.2, Nelson Mandela Road, Vasant Kunj, New Delhi

Conditions for the validity of fire safety certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization of unauthorized construction, if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

-N124-Ambiance Mall, Plot No.2, Nelson Mandela Road, Vasant Kunj, New Delhi INSPECTION REPORT 1. Name & address of the building: Ambiance Mall, Plot No.2, Nelson Mandela Road, Vasant Kunj, New Delhi : Mixed Occupancy (Mercantile & Assembly) 2. Type of Occupancy 3. Type of Case : Renewal : F6/DFS/MS/2013/SZ/1140dated 30/10/2013 4. Details of Previous NOC : F6/DFS/MS/BP/3070 dated 20/12/2004 &F6/MS/DFS/BP/2005/1692 dated 12/08/2005 5. Fire Safety directives letter No : 27/12/2016 6. Date of inspection 7. Name of Inspecting Officer : A.K. Malik 8. Name and designation of officers From the building side : Mr. I. P. Singh : 2008 [3 tiers Basement + Ground + 3 Upper Floor] 9. Year of Construction : Nil dated 14/10/16 outdoor diary no 10996, dated 25/10/16 10. Applicant's letter No. Provided at Remarks Minimum Standards on fire prevention and BBL/NBC S. MR/NMR Requirement site fire safety U/R 33 No. Access to building 1. MR Provided 9m Road width MR Provided 5_m Gate width MR Provided Width of internal road 6_m Number, Width, Type & Arrangement of Exits 2. a. Number of staircases MR(old case) 17 Nos 20 Nos Upper Floors Provided MR 25 Nos Basements b. Width of staircases MR(old case) 1.38-1.5m 1.5m Upper Floor MR(old case) 1.38-1.5m NA Basements c. Protection of exits MR Provided Required Fire check door MR Provided Required Pressurization MR d. No. of continuous staircases to terrace Provided 10 Nos MR Old Case Width of Corridor Old Case Provided (final exit) MR Door Size 1.5m Compartmentation 3. FCD/Fire Curtain MR Required Fire check door provided MR Provided Required Sealing of electrical shafts MR Required Provided Fire Rating of shaft door MR Provided Required Water Curtain MR Provided Required Fire Dampers Smoke Management System 4. M. V. Provided MR 30 ACPH Basements M. V. Provided MR 12 ACPH Upper floors Fire Extinguishers 5. MR 345 Nos 240 No's Total numbers ABC/W.CO₂/CO₂ MR ISI marked

-210/60/75 Nos

Yes

Provided

Provided

Provided

Five

30m

5mm

MR

MR

MR

MR

Types

 IS marking First-Aid Hose Reels

Total numbers on each floor

Length of hose reel hose

Nozzle diameter

6.

7.	Automatic fire detection and alarming system			100
	Type of detectors	Required	Provided	MR O
	 Location of Main Panel 	Required	Provided	MR
	 Location of Repeater Panel 	Required	Provided	MR
	 Alternate source of power 	Required	Provided	MR
	Hooters' Location	Required	Provided	MR
3.	MOEFA	Required	Provided	MR
).	Public Address System	Required	Provided	MR
0.	Automatic Sprinkler System			
	Basement	Required	Provided	MR
	Ground Floor	Required	Provided	MR
	 Sprinkler above false ceiling 	Required	Provided	MR
11.	Internal Hydrants			
	Size of riser/down-comer	150mm	Provided	MR
	Number of hydrants per floor	5 Nos	Provided	MR
	Hose Box	5 Nos	Provided	MR
12.	Yard Hydrants			
A 2010	Total number of hydrants	7 Nos	Provided	MR
	Hose Box	7 Nos	Provided	MR
13.	Pumping Arrangements			
13.	Ground Level			
	Discharge of main Pump	4500 LPM	Provided	MR
	> Head of Main pump	70m	Provided	MR
	Number of main pumps	2 Nos	Provided	MR
	> Jockey Pump out put	180 LPM	Provided	MR
	> Jockey pump head	70m	Provided	MR
	> Standby Pump out put	4500 LPM	2 No's Provided	MR
	Standby Pump Head	70m	Provided	MR
	> Auto Starting/Manual Stopping	Required	Provided	MR
	> Pump House Access	Required	Provided	MR
	Terrace level	1	1 1 24	
	Discharge of pump	NA	NA	NA
	➤ Head of the pump	NA	NA	NA
	> Power Supply	NA	NA	NA
	> Auto Starting of pump	NA	NA	NA
1.4	Captive Water Storage for fire fighting			-
14.		5,00,000 Lts	Provided	MR
	 Underground tank capacity Draw-off connection 	NA	Provided	MR
	Fire service inlet	NA	Provided	MR
	> Access to tank	NA	Provided	MR
	Overhead Tank capacity	30,000 Lts.	20,000 Lts.	MR(old
		50,000 Lts.	20,000 Lts.	case)
4=	F '4 6'	Required	Provided	MR
15.		Required	Tiovided	IVIIC
16.		D! 1	Provided	MR
	Pressurization of Lift Shaft Chick tables	Required		
	Pressurization of Lift lobby Communication In lift Can	Required	Provided	MR
	Communication In lift Car Fireman's Grounding Switch	Required	Provided	MR
	Fireman's Grounding Switch	Required	Provided	MR

ール | 2-6 -Ambiance Mall, Plot No.2, Nelson Mandela Road, Vasant Kunj, New Delhi

0	Lift Signage	Required	Provided	MR		
17.	Standby power supply	Required	Provided	MR		
18.	Refuge Area.	1				
	Total AreaLocation	NA	NA	NA		
		NA	NA	NA		
19.	Fire Control Room					
	Detector System Panel	Required	Provided	MR		
	 Flow Switch Panel PA System Panel Batter backup Building Floor Plans 	Required	Provided	MR		
		Required	Provided	MR		
		Required	Provided	MR		
		Required	Provided	MR		
20.	Special Fire Protection System for Protection of special Risks, if any:	Required	CO ₂ flooding system provided	MR		

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection. The shortcomings communicated vide letter no. F6/DFS/MS/GH/2016/SZ/2357 dated 04/10/16 may be considered as complied in view of recommendation of FPW at N/22 and representation of applicant at C/76. Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Accordingly DFA is put up for approval.

Signature of Inspecting Officer

Name: A.K. Malik Designation: DO (SD)

9/1/17 Dy. (

Dy. CFO (SZ)

of Fire Officer ath Zone

Receipt.....

Dispatch.....

CFO (\$2)

FTM

M-SCOU 2/1

Siz F.T. is head up for Ss-please.

Cfo(cz)

9/11/7

11 16