GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

Fax No. 011-23412593, Ph. 011-23412225

No. F6/DFS/MS/GH/SZ/2016/ 1845

Dated: .. 28/12/16

FIRE SAFETY CERTIFICATE

Issued on 28/12/16 at New Delhi by

Vipin Kental Chief Fire Officer

Copy to: -

- 1. Chauhan Guest House, 4A & 4B, Nangli Rajapur, East Nizamuddin, New Delhi-110013
- 2. The Joint Commissioner of Police (Lic.), 1st Floor, PS Defence Colony, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety and means of escape facilities shall be maintained in good working condition at all time. Any lapse rendering the fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
- Building Sanctioning authority may verify any deviation with regard to construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null & void.
- 3. The staff shall be trained for operating fire fighting system and mock evacuation drill be conducted at regular interval and record be maintained.
- 4. The basement shall be used strictly as per the provisions of Building Bye Laws.
- 5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in.
- 6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

	INSPECTIO	NREPURI	I 1A & AD Nangli E	Paianur	
1	F	Chauhan Guest House, 4A & 4B, Nangli Rajapur East Nizamuddin, New Delhi-110013			
2	Type of Occupancy F	Residential & Lodging, Group-A (Guest House)			
3	Building Comprised of	Ground plus three upper floors			
4	Tyma of Case	Renewal			
5	Details of Previous NOC	F.6/DFS/MS/GH	I/2013/SZ/1156 dated 31/	10/2013	
6	Fire Safety Directives Letter No	Vil			
7	Date of Inspection	14.12.2016			
8	Name of the Inspecting Officers	ADO R.N. Singl		*	
9	Name & Designation of Officers from the building side	Mr. Abhimanyu Roy (Manager)			
10	Year of construction	Ground floor (Rec.+ Shop + 04 G/Rooms), 1st Floor (06 G/Rooms) 2nd Floor (06 G/Rooms) 3rd floor (06 rooms for private use)			
11	Applicant letter No.	Nil Dated 11.11	.2016		
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC 15/11/2010	Provided at Site	Remarks MR/NMR	
	×	Requirement			
1	Access to Building.			MD	
7	Road width.	6 mtr	More than 6 mtr	MR N/A	
	Gate width	N/A	N/A	N/A	
	Width of internal road	N/A	N/A	N/A	
2	Number, width, type and arrangements of	exits.			
	a. Number of Staircase				
	Upper floors	Two	Two	MR	
	Basement floor	N/A	N/A	N/A	
	b. Width of Staircase				
	Upper floors.	Required	0.90 mtr each	MR old case	
	Basement floor.	N/A	N/A	N/A	
	D 11 C 14				
	Fire check door	N/A	N/A	N/A	
		N/A	N/A	N/A	
	0 1 · 1- 1- 1- 1- 1- 1- 1- 1- 1- 1- 1- 1- 1-	One	Two	MR	
		N/A	N/A	N/A	
	e. Width of corridor	1 m	1.5 m (Final exit)	MR	
	f. Door size	1 111	110 111 (2 222)		
3	Compartmentation.	N/A	N/A	N/A	
	• Fire check door.	N/A	N/A	N/A	
	Sealing of electrical shafts. Fig. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.	N/A	N/A	N/A	
9	Fire rating of shaft door.	N/A	N/A	N/A	
	Water curtain.	N/A	N/A	N/A	
	Fire dampers.	11/11	17/12		
4.	Smoke Management system.	NI/A	N/A	N/A	
-	Basement	N/A	N/A	N/A	
	Upper floors	N/A	11/11	14/11	
5.	Fire Extinguishers.	00 NI-2-	09 No's	MR	
6.	Total numbers	09 No's			
	• Types	ABC/Co2	ABC- 06 & WCo2-03	MR	
	ISI Marking	ISI Marked	Provided	IVIK	
	First Aid Hose Reels.	IA .		l v m	
	Total numbers on each floor.	Hose reel	One	MR	
	7 .1 .01		30 m	MR	
	• Length of hose-reel nose.		05 mm	MR	

Renewal

Chauhan Guest House, 4A & 4B, Nangli Rajapur ND-13



7	Automatic Fire Detection and Alarming			1
	Type of detectors	N/A	N/A	N/A
	 Location of Main Panel 	N/A	N/A	N/A
	 Location of Repeater Panel 	N/A	N/A	N/A
	 Alternate source of power 	N/A	N/A	N/A
	 Hooter's location 	N/A	N/A	N/A
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System	*	= = = = = = = = = = = = = = = = = = = =	
	Basement	N/A	N/A	N/A
	 Upper floors 	N/A	N/A	N/A
	 Sprinkler above false ceiling 	N/A	N/A	N/A
11.	Internal Hydrants.	=		
	Size of Riser / Down-comer	N/A	N/A	N/A
	 Number of Hydrant per floor 	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
12.	Yard Hydrants.			
	Total number of hydrants.	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
13.	Pumping arrangements.	1	177.	IVA
	Ground Level	я		
	Discharge of main pump.	N/A	N/A	N/A
	Head of main pump.	N/A	N/A	N/A N/A
	Number of main pumps.	N/A	N/A	N/A N/A
	Jockey Pump output.	N/A	N/A N/A	N/A N/A
	> Jockey Pump head.	N/A	N/A N/A	N/A N/A
	Standby Pump output.	N/A	N/A N/A	N/A N/A
	Standby Pump head.	N/A	N/A N/A	N/A N/A
	Auto Starting/Manual Stopping.	N/A	N/A N/A	N/A N/A
	> Pump House Access	N/A	N/A N/A	N/A N/A
	Terrace Level	IVA	11/11	IN/A
	Discharge of pump.	Required	450 LPM	MR
	Head of pump.	Required	40 mtr	MR
	> Power supply.	Required	Provided (Inverter)	MR
	Auto starting of pump.	Required	Provided (mverter)	MR
14.	Captive water storage for Fire Fighting.		Tiorided	IVIN
	Underground tank capacity.	N/A	N/A	N/A
	 Draw-off connection. 	N/A	N/A	N/A
	Fire Service Inlet.	N/A	N/A	N/A
	 Access to tank. 	N/A	N/A	N/A
	Overhead tank capacity.	2,500 Ltr.	2,500 Ltr	MR
15.	Exit Signage.	Required	Provided	
16.	Provision of Lifts.	required	Flovided	MR
	Pressurization of lift shaft.	N/A	N/A	N/A
	 Pressurization of lift lobby. 	N/A	N/A N/A	N/A N/A
	 Communication in lift car. 	N/A	N/A N/A	N/A N/A
	• Fireman's switch.	N/A	N/A N/A	
		N/A N/A	N/A N/A	N/A
17	Lift signage. Standby Parent Servels		CONTRACTOR	N/A
17	Standby Power Supply	Required	Provided (Inverter)	MR
18.	Refuge Area	121/4	D.T./A	227
	Total area	N/A	N/A	N/A
	 Location 	N/A	N/A	N/A

Renewal

Chauhan Guest House, 4A & 4B, Nangli Rajapur ND-13

fy.

9.	Fire Control Room.	>T/A	N/A	N/A
	Detector System Panel.	N/A		N/A
	• Flow Switch Panel.	N/A	N/A	
		N/A	N/A	N/A
	 PA system Panel. 	N/A	N/A	N/A
	Battery backup		N/A	N/A
	Building floor plan	N/A	- 11	NI/A
20.	Special Fire Protection System for the Protection of special Risk, if any.	N/A	One ABC type fire extinguisher provided near elect. panel	N/A

The Fire Protection system provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/GH/2013/SZ/1156 dated 31/10/2013 renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer : R.N. Singh Name

Designation: ADO

Renewal

Chauhan Guest House, 4A & 4B, Nangli Rajapur ND-13

Div. Officer (SD)

478/chs2 Dy c20(52)/andeans
22/12/26/12. Cfo(52)/ M. Skell