GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110 001

No. P6/088/ ms/ Hospital/2017/52/59

Dated: 13/01/17

FIRE SAFETY CERTIFICATE

Issued on.....2017 at New Delhi by.

(Vipin Kental)
Chief Fire Officer
T.No.011-23412225

Copy to:- Sh. Deepak Kumar, Dy. Chief Security Officer, AIIMS Complex, Ansari Nagar, New Delhi.

Conditions for the validity of fire safety certificate are under:-

All the means of escape shall be kept free of all type of obstruction all the time.
 All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.

5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

7. The owner/occupier shall apply for renewal of this Fire Safety Certificate on form J, six month prior to its expiry.

		OF LOTION TILL OIL	and the state of the state of			
1	Name & address of the building	M/S Nurses Hostel building, AIIMS Complex, Masjid Moth, New				
		Delhi-110029.				
2	Type of Occupancy		sidential Building "A" (Hostel)			
3	Building comprised of	ing comprised of Ground plus seven upper floors.				
3	Type of case	Renewal.				
4	Details of previous NOC	No.F6/DFS/MS/92/Hos	pital/675, Dated 09.04.19	92.		
5	Fire safety directives letter No	lo.F6/MS/DFS/88/643, Dated 12.05.1988.				
6	Date of inspection	03.01.2017.	4-1			
7	Name of the inspecting Officers :	ADO Vedpal				
8	Name and designation of officers	Sh.Deepak Kumar Secu	urity Officer of the Hospita	al.		
	from the building side					
9	Year of construction	1990				
10	Applicant's letter No.	Security/Fire/Inspection/2016, Dated 08.12.2016				
S. NO.	Minimum Standards on fire	Requirements/	Provided at site	Remarks		
	prevention and fire safety U/R	Existing Fire		MR / NMR		
1-17	33	Protection System				
1	Access to building					
	1) Road width	9m	9m	MR		
	2) Gate width	5m	5m	MR		
1	3) Width of internal road	6m	6m	MR		
2	Number, width Type & arrangement	ent of exits				
×-, -	a. Number of staircases			×		
	1. Upper floors	05nos.	05nos.	MR		
	2. Basements	N/A	N/A	N/A		
3- 11-	b. Width of staircase					
	1. Upper floors	1.2m/90cm	1.6m,1.14m,1m, 96cm			
	T. Opper Hoors	1.2111/000111	& 94cm	MR(old case)		
-	2. basements	N/A	N/A	N/A		
	c. Protection of exits			1,7//		
	1. Fire check door	N/A	N/A	N/A		
	2. Pressurization	N/A	N/A	N/A		
	d. No. of continuous staircase		01no.	MR		
	to terrace	o mo.	01110.	IVII		
		N/A	N/A	N/A		
1	f. Door size	1m	1m	MR		
3	Compartmentation.	IIII		IVIT		
	1. Fire check door	N/A	N/A	N/A		
	2. Sealing of electrical shafts	Required	Provided	MR		
	3. Fire Rating of shaft door	N/A	N/A	N/A		
	4. water curtain	N/A	N/A	N/A		
	5. Fire dampers	N/A	N/A	N/A		
4	Smoke Management system.					
	Basement	30 a/c per hour	N/A	N/A		
		12 a/c per hour	Natural Ventilation	MD		
-	Upper floors		Tratulal Velitilation	MR		
5	Fire Extinguishers Total numbers	22 Nos	50 Nos.	MR		
	Types	32 Nos. ABC, CO2 & WCO2	ABC, CO2 & WCO2	MR		
	ISI marking	ISI	Provided Provided	MR		
6	First-Aid Hose Reels.		T. TOVIGOU	TANIX		
	Total numbers on each floor	04nos.	04nos.	MR		
	Length of Hose reel hose	30 Mtr	30m	MR		
4 2	Nozzle Diameter	5mm	5mm	MR		
7	Automatic fire detection and alar		1	1		
	Type of detectors	Heat	Heat	MR ,		
	location of Main Panel	Ground Floor	Ground Floor	MR		
	location of Repeater panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	hooter's location	All Areas	All Areas	MR		
8	MOEFA	Required	Provided	MR		
9	Public Address System.	Required	Provided	MR		
10	Automatic Sprinkler System.	NI/A	NI/A	INI/A		
-	basement	N/A	N/A	N/A		
	upper floors	N/A	N/A	N/A		
N. Carlotte	sprinkler above false ceiling	N/A	NI/A	NIA		

11	Internal Hydrants			-
	Size of riser/down-corner	150mm	150mm	MR
	Number of Hydrants per floor	04nos.	04nos.	MR
	hose Box	04nos.	04nos.	MR
12	Yard Hydrants.			
	total number of hydrants	08nos.	08nos.	MR
	house box	08nos.	08nos.	MR
13	Pumping arrangements	UGWST & Fire Pump house is common for Docters hostel & Nurses hostel		
	1. Ground level	Required	Provided	MR
	a. Discharge of main Pump	2400LPM	2400LPM	MR
	b.Head of main pump	80m	80m	MR
	c.Number of main pumps	01no.	01no.	MR
	d.jockey pump out put	180LPM	180LPM	MR
	e.jockey pump head	80m	80m	MR
	f. Standby Pump output	2400LPM	2400LPM	MR
	g.Stanby Pump head	80m	80m	MR
	h.Auto Starting/Manual stopping	Required	Provided	MR
	pump house access 2.Terrace level	Required	Provided	MR
		NI/A	TN1/0	Dico
	a. Discharge of pump	N/A N/A	N/A	N/A
	b. head of the pump	N/A N/A	N/A	N/A
	c. Power supply d. Auto starting of pump	N/A	N/A N/A	N/A N/A
14	Captive water storage for fire		ump house is common for Doc	
17	fighting	Nurses hostel	drip flouse is common for Boo	iers noster o
	Underground tank capacity	2,00,000 ltr	2.00.000 Ltr Dravidad	MD
	a. Draw-off connection	Required	2,00,000 Ltr Provided Provided	MR MR
	b. fire service inlet	Required	Provided	MR
	c.Access to tank	Required	Provided	MR
	Over head tank Capacity	20000Liters	20000Liters	MR
15	Exit Signage.	Required	Provided	MR
		rtequired	Trovided	IVIIX
16	Provision of lifts.			
	a. Pressurization of lift shaft	N/A	N/A	N/A
	b. pressurization of lift lobby	N/A	N/A	N/A
	c. communication in lift car	Required	Provided	MR
	d. Fireman's grounding switch	Required	Provided	MR
	e. Lift signage	Required	Provided	MR
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	total area	N/A	N/A	N/A
	location	N/A	N/A	N/A
19	Fire control room			
19	a. Detector system Panel	N/A	N/A	N/A
19		N/A	N/A	N/A
19	b. Flow switch Panel		1.1/4	
19	c. PA system Panel	N/A	N/A	N/A
19	The state of the s	N/A N/A N/A	N/A N/A N/A	N/A N/A

The fire protection systems provided in the building were checked and found functional at the time of inspection. In view of the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules the NOC issued vide letter No.F.6/DFS/MS/92/(Hospital)/675, dated 09.04.1992 renewal under rule 37 of the Delhi Fire Service Rule 2010 is recommended. Shortcomings communicated vide letter dated 19.01.16 have been complied at serial numbers 6,9,11,12,13 & 15.

Accordingly DFA is put up for your approval and signature please.

Signature of the inspecting officer

Name Vedpal

Designation : Assistant Divisional Officer

In meal

oth.