GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2017/ 7 3

Dated: (8/01/16

FIRE SAFETY CERTIFICATE

Certified that M/s Hotel Pawan Plaza Guest house located at 7A/9, WEA Channa Market, Karol Bagh, New Delhi comprised of ground plus three upper floors using ground floor as reception & shops, first, second and third floor each having 06 guest rooms respectively (total 18 guest rooms) and one staff room with pantry on terrace floor was granted FSC by this department vide letter No. F6/DFS/MS/GH/2011/1869 dated 05/08/2011. The premises was reinspected by the officer concerned of this department on 29/12/16 in presence of Mr. Rahul, manager of the guest house and found that the said guest house have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) with effect from 18/11/16 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

Issued -- 18/1/16-----at New Delhi by.

(VIPEN KENTAL)

Chief Fire Officer

Copy to:-

1. The Manager, M/s Pawan Plaza Guest house, 7A/9, WEA Channa Market, Karol Bagh, 16 New Delhi-05.

2. The Joint C.P.(Lic.), Police Station, Defence Colony, 1st floor, New Delhi

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained firefighting staffs should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. The basement shall be used as per the provisions of BBL.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building : M/s. Hotel Pawan Plaza Guest House, 7A/9, Channa Market,

Karol Bagh, New Delhi-110005.

2. Type of Occupancy : Lodging House

3. Type of Case : Renewal

4. Details of previous NOC : F6/DFS/MS/GH/2011/1869 dated 05/08/2011

5. Fire Safety directives letter No : N/A

6. Date of inspection : 02-01-2017

7. +

8. Name of the Inspecting Officers: M.K. Chattopadhyay, Divisional Officer (South West)

9. Name and designation of officers

Smoke Management System.

from the building side : Mr. Rahul, Manager

9. Year of Construction : 2011

10. Applicant's letter No. : nil dated 04.12.2016

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Existing fire safety requirements as per le dated 07-04-2008		Remarks MR/NMR				
1	Access to building							
	Road width	06 mts						
	Gate width	05 mts	Directly accessible fro	m MR				
	Width of internal road	N/A	N/A	N/A				
2	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases	-	•	-				
	Upper Floors	01	Provided (01)	MR				
	Basements	N/A	N/A	N/A				
	b. Width of staircases	-	• • • • • • • • • • • • • • • • • • •	-				
	Upper Floors	1.25 mts	1.40-1.06 mts	MR being old cas				
	Basements	N/A	N/A	N/A				
	c. Protection of exits	-	<u> </u>	-				
	Fire check door	N/A	N/A	N/A				
	Pressurization	N/A	N/A	N/A				
	e. No. of continuous staircases to terraceg. Width of Corridorh. Door Size	01	01	MR				
		1.25 mts	2.05-1.33 mts	MR				
		1.0 mt	Provided (1.0 mt.)	MR				
3	Compartmentation.							
	Fire check door	N/A	N/A	N/A				
	Sealing of electrical shafts	N/A	N/A	N/A				
	Fire Rating of shaft doorWater Curtain	N/A	N/A	N/A				
		N/A	N/A	N/A				
	Fire Dampers	N/A	N/A	N/A				

	Upper floors	12 a/c per hour	Natural ventilation provided	MR		
5	Fire Extinguishers					
	Total numbers	12	Provided	MR		
	• Types	CO ₂ , ABC type	Provided	MR		
****	IS marking	ISI marked	Provided	MR		
6	First-Aid Hose Reels.					
	Total numbers on each floor	01	Provided	MR		
	• Length of hose reel hose	30 m	Provided	MR		
	Nozzle diameter	5 mm	Provided	MR		
7	Automatic fire detection and alarming system.					
	Type of detectors	Required	Provided	MR		
	Location of Main Panel	Required	Provided	MR		
	Location of Repeater Panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
×	Hooters' Location	N/A	N/A	N/A		
8.	MOEFA	Required	Provided	MR		
9	Public Address System.	Required	Provided	MR		
10	Automatic Sprinkler System.					
	• Basement	N/A	N/A	N/A		
	Upper Floor	N/A	N/A	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants					
	Size of riser/down-comer	N/A	N/A	N/A		
	Number of hydrants per floor	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
12	Yard Hydrants.					
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13	Pumping Arrangements.			*		
	Ground Level					
	Discharge of main Pump	N/A	N/A	N/A		
a 2	➤ Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	> Jockey Pump out put	N/A	N/A	N/A		
	Jockey pump headStandby Pump out put	N/A	N/A	N/A		
	Standby Pump out putStandby Pump Head	N/A	N/A	N/A		
	Auto Starting/ Manual stopping	N/A	N/A	N/A		
	116	N/A	N/A	N/A		

	rump House Access	1 1/2 2				
5	Terrace level					
	Discharge of pump	450 LPM	Provided	MR		
	Head of the pumpPower Supply	35 mts	Provided	MR		
	Auto Starting of pump	Required	Provided	MR		
		Required	Provided	MR		
14	Captive Water Storage for fire fighting	g.				
,	Underground tank capacity	N/A	N/A	N/A		
	> Draw-off connection	N/A	N/A	N/A		
	Fire service inlet	N/A	N/A	N/A		
	> Access to tank	N/A	N/A	N/A		
	Overhead Tank capacity	10,000 lts	Provided	MR		
15	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.					
10	Pressurization of Lift Shaft	N/A	N/A	N/A		
	 Pressurization of Lift lobby 	N/A	N/A	N/A		
	Communication In lift Car	Required	Provided	MR		
	Fireman's Grounding Switch	Required	Provided	MR		
	Lift Signage	Required	Provided	MR		
17	Standby power supply	Required	Provided	MR		
18	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
01/17	PA System Panel	N/A	N/A	N/A		
936	Batter backup	N/A	N/A	N/A		
Fire C	132	N/A	N/A	N/A		
20	Building Floor Plans Special Fire Protection Systems for Protection of special Risks, if any:	Required	Two ABC type fire extinguisher provided near elect. panel	MR		

The fire protection systems provided in the building were checked and found functional at the time of inspection

All the shortcomings pointed out by this department vide letters dated 07.12.2016 and 06.09.2016 have been complied with by the owner of the guest house.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F6/DFS/MS/GH/2011/1869 dated 05/08/2011, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

523 CR32

1 mg

M.K.CHATTOPADHYAY Div. Officer (SW)