GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI-110001

No.: F6/MS/DFS/EH/ 2/7/1402/7/

Dated:-17/01/17

FIRE SAFETY CERTIFICATE

> (Vipin Kental) Chief Fire Of icer Delhi Fire Service

Copy to:-

- 1. The Dy. Health Officer, East Delhi Municipal Corporation, Health Department, Karkardooma South Zone, Shahdara, Delhi
- 2. M/s True Blue Restro Bar Pvt. Ltd., Star City Mall, Mayur Vihar, Phase – I, New Delhi – 110095.

CONDITIONS:

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the ime and any lapse rendering non-functional of fire safety measures, management shal be responsible.

4. All comments/ directions of the Licensing Department shall always be permitted and

followed.

5. Basements shall be used as per BBL.

6. Any deviation, with regards to construction deviation, ventilation, occupancy, struc ural stability, electric installation etc. may be got verified from the concerned authorities.

7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

8. This Fire Safety Certificate may not be treated in any case for regularization of

unauthorized construction/ unauthorized use of land if any.

INSPECTION REPORT

1. Name & address of the building : Platinum Lounge Restaurant at G – 17, Star City Mall, Plot No. 70

01 - A, Distt. Center, Mayur Vihar - I, Delhi.

2. Type of Occupancy : Assembly 3. Type of Case

4. Details of previous NOC : F6/DFS/MS/EH/2013/NDZ/981 Dated 27/09/2013

5. Fire Safety directives letter No : F6/DFS/MS/BP/2004/1969 Dated 30/08/2004

: Renewal

Date of inspection : 17/11/2016

Name of the Inspecting Officers: DOSK Dua

8. Name and designation of officers

from the building side : Sh. Dharambir Singh

Year of Construction : 2004

10. Applicant's letter No.

S. No.	Mir	nimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR		
1	Access to building						
	•	Road width	12 Mtrs.	13 Mtrs.	MR		
	•	Gate width	4.5 Mtrs.	6.0 Mtrs.	MR		
	•	Width of internal road	6.0 Mtrs.	6.0 Mtrs.			
2	Numb	er, Width, Type & Arrangement of I	277. 249.000.000.000	0.0 Mus.	MR		
		nber of staircases					
		Upper Floors	N/A	DT/A			
		Basements	N/A	N/A N/A	N/A		
	b. Wid	th of staircases	IVA	IN/A	N/A		
	•	Upper Floors	N/A	N/A	NI/A		
		Basements	N/A	N/A	N/A		
	c. Prote	ection of exits	IVA	N/A	N/A		
	•	Fire check door	N/A	N/A	NT/A		
		Pressurization		IN/A	N/A		
	e. No.	of continuous staircases to terrace	N/A	N/A	N/A		
		th of Corridor	N/A	N/A	N/A		
	h. Door		2.5 Mtr.	2.5 Mtr.	MR		
	Compa	artmentation.	2.0 Mtr.	2.0 Mtr.,	MR		
	•	Fire check door	N/A	N/A	NT/A		
		Sealing of electrical shafts	Required	Sealed Sealed	N/A		
		Fire Rating of shaft door	N/A		MR		
		Water Curtain	-	N/A	N/A		
		Fire Dampers	N/A	N/A	N/A		
		1 no Dampers	N/A	N/A	N/A		
	Smoke Management System.						
		Basements	N/A	N/A	N/A		
	•	Upper floors	Required	Provided	MR		
	Fine Fr	tinguishove					

	Total numbers	02 nos.	04 Nos.	MR			
	• Types	ABC & Co2	ABC & Co2	MR			
	IS marking		Provided	MR			
6	First-Aid Hose Reels.	ISI marked	ISI marked				
contraction of the contraction o		OI NO.		MR			
	Length of hose reel hose	30 m	30 m	MR			
	Nozzle diameter	05 mm	05 mm	MR			
7	Automatic fire detection and alarming system.						
	Type of detectors	Heat	Provided	MR (Old case)			
	Location of Main Panel	Control Room in	Provided	MR			
	Location of Repeater Panel	Basement Security Room	Provided	MR			
	Alternate source of power	•					
	Hooters' Location	Battery/ DG Set	Provided	MR			
		Different Location	Provided	MR			
8	MOEFA	Required	Provided	MR			
9	Public Address System.	Required	Provided	MR			
	•	110quilou	1 TOVICO	IVII			
10	Automatic Sprinkler System.			A			
	Basement	N/A	N/A	N/A			
	Upper Floor	Required	Provided	MR			
	Sprinkler above false ceiling	Required	Provided	MR			
11	Internal Hydrants						
Menor and an anti-charge state of the state	Size of riser/down-comer	100 mm	100 mm	MR			
	Number of hydrants per floor	01 Nos.	01 Nos.	MR			
	Hose Box	02 Nos.	02 Nos.	MR			
12	Yard Hydrants.						
	Total number of hydrants	N/A	01 Nos.	MR (Old case)			
	Hose Box	N/A	01 Nos.	MR (Old case)			
13	Pumping Arrangements.						
	Ground Level	N/A	N/A	N/A			
	 Discharge of main Pump 	N/A	N/A	N/A			
	> Head of Main pump	N/A	N/A	N/A			
	Number of main pumps	N/A .	N/A	N/A			
	Jockey Pump out put	N/A	NI/A	NT/A			
	Jockey pump head	N/A	N/A N/A	N/A N/A			
	Standby Pump out put	N/A	N/A				
	Standby Pump Head	N/A	N/A	N/A N/A			
	Auto Starting/ Manual stopping	N/A	N/A	N/A			
	Pump House Access	N/A	N/A	N/A N/A			
	Terrace level						
	Discharge of pumpHead of the pump	4500 LPM	4500 LPM	MR (Old case)			
	Number of main pumps	50 Mtrs.	50 Mtrs.	MR (Old case)			
	Jockey Pump out put	02 Nos.	02 Nos.	MR (Old case)			
	Jockey rump out put	450 LPM	450 LPM	MR (Old case)			

			Premiun	, Loringe Restaura	nt, StarCity Mal		
U		> Jockey pump head	50 Mtrs.	50 Mtrs.	MR (Old case)		
	diameter and the second	> Standby Pump out put	4500 LPM	4500 LPM	MR (Old case)		
		> Standby Pump Head	50 Mtrs.	50 Mtrs.	MR (Old case)		
		> Power Supply	Required	Provided	MR		
		> Auto Starting of pump	Required	Provided	MR		
14	Captive Water Storage for fire fighting.						
	•	Underground tank capacity	2,00,000 Ltrs.	Provided	MR		
	>	Draw-off connection	Required	Provided	MR		
	>	Fire service inlet	Required	Provided	MR		
	>	Access to tank	N/A	N/A	N/A		
	•	Overhead Tank capacity	25,000 Ltrs.	2,50,000 Ltrs.	MR		
15	Exit S	ignage.	Required	Provided	MR		
16	Provision of Lifts.						
	•	Pressurization of Lift Shaft	N/A	N/A	N/A		
	•	Pressurization of Lift lobby	N/A	N/A	N/A		
	•	Communication In lift Car	N/A	N/A	N/A		
	•	Fireman's Grounding Switch	N/A	N/A	N/A		
	•	Lift Signage	N/A	N/A	N/A		
17	Stand	by power supply	N/A	N/A	N/A		
18	Refuge Area.						
	>	Total Area	N/A	N/A	N/A		
	>	Location	N/A	N/A	N/A		
19	Fire Control Room						
		Detector System Panel	N/A	N/A	N/A		
	-	Flow Switch Panel	N/A	N/A	N/A		
		PA System Panel	N/A	N/A	N/A		
		Batter backup	N/A	N/A	N/A		
		Building Floor Plans	N/A	N/A	N/A		
20		Il Fire Protection Systems for tion of special Risks, if any:	Required	HT & LT panel protected with local CO2 applications	MR		

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules. The Fire Safety Certificate issued vide letter no. F6/DFS/MS/EH/2013/NDZ/981 Dated 27/09/2013 renewal under rule 35 of the Delhi Fire Service Rule 2010 is recommended.

Signature of the Inspecting Officer

Name : S. K. DUA

Designation : DO(ED)