GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

Fax No. 011-23412593, Ph. 011-23412225

No. F6/DFS/MS/GH/2017/SZ/ 67

Dated: .1.4 / .1/1/7.

FIRE SAFETY CERTIFICATE

Certified that the T.E. New Delhi Guest House located at A-3, Pamposh Enclave, Greater Kailash-I, New Delhi-110048, comprised of Basement, Stilt, Ground + 3 upper floors. Basement- Office & Vacant, Stilt floor- Parking, Ground floor- Reception, waiting lounge, kitchen & Restaurant, 1st floor, 2nd floor & 3rd floor- having 08 guest rooms on each floor (Total 24 Guest Rooms) was granted Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/GH/2013/SZ/1361 dated 30/12/2013. The premises was re-inspected by the officer concerned of this department on 15.12.2016 in the presence of Mr. Lalit Kumar (Accountant) of the guest house and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fir for occupancy class "Residential Lodging Building, Group-A" with effect from 16.11/1/7 for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 16/1/17 at New Delhi by

Vipin Kental
Chief Fire Officer

Copy to: -

ole

- 1. The Joint Commissioner of Police (Lic.), 1st Floor, PS Defence Colony, New Delhi
- 2. The DHO, Central Zone, South MCD (Health Department), Lajpat Nagar, ND-24
- 3. M/s T.E. New Delhi Guest House, A-3, Pamposh Enclave, Greater Kailash, ND-110048

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety and means of escape facilities shall be maintained in good working condition at all time. Any lapse rendering the fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
- 2. Building Sanctioning authority may verify any deviation with regard to construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null & void.
- 3. The staff shall be trained for operating fire fighting system and mock evacuation drill be conducted at regular interval and record be maintained.
- 4. The basement shall be used strictly as per the provisions of Building Bye Laws.
- 5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in.
- 6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

1		-					
1	NT_	INSPECT			<u> </u>		
1	Nar	ne & Address of the Building	T.E. NE	W DEI	LHI GUEST HOUSE (A	A Unit of TE	
			Hospitality Estate Limited), Plot No. A-3, Pamposh				
			Enclave	Enclave, Greater Kailash-1, New Delhi-110048			
2	Тур	e of Occupancy	Residential & Lodging, Group-A (Guest House)				
3		lding Comprised of	Basement, Stilt, Ground + 3 upper floors				
4		e of Case	Renewal				
5		ails of Previous NOC	F.6/DFS	F.6/DFS/MS/GH/2013/SZ/1361 dated 30/12/2013			
6	Fire	Safety Directives Letter No	Nil				
7		e of Inspection	15.12.2016				
8	Nan	ne of the Inspecting Officers	ADO R.N. Singh				
9	Nam	ne & Designation of Officers					
	from the building side		Mr. Lalit Kumar (Accountant)				
10	Year of construction		Nil	(Rec.	nent (Office/Vacant), Stilt (Parking), Gd. floo waiting lounge, kitchen and Restt.), 1 st , 2nd of		
				3" Flo	Floor (08 guest rooms on each floor) Total-		
11	App	licant letter No.	Nil Data	guest r	ooms		
S. No		imum standards on Fire Prevention	Nil Date			•	
	and	Fire Safety U/R 33	1	Old NOC Provided at Site Ot. 15/11/2010		Remarks	
		The Salety Of R 33	1			MR/NMF	
1	Acce	ess to Building.	Require	ement	8		
		. Road width.	Require	d	0		
	2		N/A	u	9 mtr	MR	
	3	. Width of internal road	N/A		N/A	N/A	
2			f ovita		N/A	N/A	
	Number, width, type and arrangements of exits. a. Number of Staircase						
	•		Required	1	2 2 1		
		Basement floor	Required		2 No's	MR	
	b. V	Vidth of Staircase	Require	1	2 No's	MR	
	•		Doguin	1	1 20 0 0 7		
		Basement floor.	Required		1.28 m & 0.78 m	MR old case	
	c. P	rotection of exits	Required	1	1.28 m & 0.70 m	MR old case	
*	0	Fire check door	-				
		Pressurization	Required	<u> </u>	Provided	MR	
			N/A		N/A	N/A	
	d. N	o. of continuous staircase to terrace	Required		2 No's	MR	
		dth of corridor	N/A		N/A	N/A	
3		oor size	N/A		1.10 m (Final exit)	N/A	
3		Partmentation. Fire check door.	T				
	1. 2.		N/A		N/A	N/A	
* -	3.	Sealing of electrical shafts.	N/A		N/A	N/A	
,	3. 4.	and rating of shall door.	N/A		N/A	N/A	
	5.	Fire dampers.	N/A		N/A	N/A	
4.			N/A		N/A	N/A	
4.		e Management system.					
	1. 2.	Basement Unpar floors	30 ACPH		Exhaust fans provided	MR	
5.		Upper floors	N/A		Natural Ventilation	N/A	
J.		xtinguishers.					
	1. 2.	Total numbers	10 No's		10 No's	MR	
	3.	Types ISI Marking	Portable F		ABC- 06 & Co2-04	MR	
6.		ISI Marking	Extinguis	her	Provided	MR	
U.		id Hose Reels.				•	
-	1.	Total numbers on each floor.	Hose reel		One	MR	
	2.	Length of hose-reel hose.		-	30 m	MR	
	3.	Nozzle Diameter			05 mm	MR	
newal		TFN	lew Delhi (TH at A	-3 Pampagh Englave	IVIIV	

Renewal

7	Automatic Fire Detection and Alarming system.						
	Type of detectors	N/A	N/A	N/A			
	2. Location of Main Panel	N/A	N/A	N/A			
	Location of Repeater Panel	N/A	N/A	N/A			
	4. Alternate source of power	N/A	N/A	N/A			
	5. Hooter's location	Required	Provided	MR			
8.	MOEFA	Required	Provided	MR			
9.	Public Address System	Required	Provided	MR			
10.	Automatic Sprinkler System		0	e			
	1. Basement	Required	Provided	MR			
	2. Upper floors	N/A	N/A	N/A			
	Sprinkler above false ceiling	N/A	N/A	N/A			
11.	Internal Hydrants.						
	Size of Riser / Down-comer	Required	100 mm	MR			
	2. Number of Hydrant per floor	Required	One	MR			
	3. Hose box.	Required	One	MR			
12.	Yard Hydrants.		· · · · · · · · · · · · · · · · · · ·				
	Total number of hydrants.	N/A	N/A	N/A			
	2. Hose box.	N/A	N/A	N/A			
13.	Pumping arrangements.						
	a) Ground Level						
	Discharge of main pump.	N/A	N/A	N/A			
	Head of main pump.	N/A	N/A	N/A			
	Number of main pumps.	N/A	N/A	N/A			
	Jockey Pump output.	N/A	N/A	N/A			
	Jockey Pump head.	N/A	N/A	N/A			
	Standby Pump output.	N/A	N/A	N/A			
	Standby Pump head.	N/A	N/A	N/A			
	Auto Starting/Manual Stopping.	N/A	N/A	N/A			
	> Pump House Access	N/A	N/A	N/A			
	b) Terrace Level	14/11	11/11	1 1/11			
	Discharge of pump.	Required	900LPM & 180 LPM	MR			
	Head of pump.	Required	40 mtr & 35 Mtr	MR			
	Power supply.	Required	Provided	MR			
	Auto starting of pump.	Required	Provided	MR			
14.	Captive water storage for Fire Fighting.		Hovided	1411			
17.	Underground tank capacity.	N/A	N/A	N/A			
	 Draw-off connection. 	N/A	N/A	N/A			
	• Fire Service Inlet.	N/A	N/A	N/A			
	Access to tank.	N/A	N/A	N/A			
	Access to tank.Overhead tank capacity.	Required	10,000 Ltr.	MR			
15		Required	Provided	MR			
15. 16.	Exit Signage. Provision of Lifts.	Required	FIUVIUCU	IVIK			
10.		N/A	N/A	N/A			
		N/A	N/A N/A	N/A N/A			
	Pressurization of lift lobby.	N/A N/A	N/A N/A	N/A N/A			
	Communication in lift car.	N/A	N/A N/A	N/A N/A			
	• Fireman's switch.	N/A N/A	N/A N/A	N/A N/A			
	• Lift signage.	A STATE OF THE STA					
17	Standby Power Supply	Required	Provided	MR			
18.	Refuge Area	11 27/1		T > 7 ' '			
	Total area	N/A	N/A	N/A			
	 Location 	N/A	N/A	N/A			

Renewal

TE New Delhi GH at A-3, Pamposh Enclave, GK-1, ND-48

19.	Fire Control Room.						
	Detector System Panel.	N/A	N/A	N/A			
	Flow Switch Panel.	N/A	N/A	N/A			
	PA system Panel.	N/A	N/A	N/A			
	Battery backup	N/A	N/A	N/A			
	Building floor plan	N/A	N/A	N/A			
20	Special Fire Protection System for t	N/A					

The Fire Protection system provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/GH/2013/SZ/1361 dated 30/12/2013 renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name

: R.N. Singh

Designation: ADO

Renewal

TE New Delhi GH at A-3, Pamposh Enclave, GK-1, ND-48

Div. Officer (SD)

sz Dycho (52)

-41117/1

22/12

FTB

Cfo(571

m. s/cell Will