## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2017/SZ

Dated: 02/02/17

## FIRE SAFETY CERTIFICATE

Certified that the Krishna Model Secondary School, Old Roshan Pura Extn., Najafgarh, New Delhi-110043, comprised of ground floor plus three upper floors owned/occupied by the Krishna Model Secondary School was inspected by the officer concerned of this department on 19.01.2017 in the presence of Sh. Bhim Singh Yadav (Society Manager) and found that the Krishna Model Secondary School have complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the school building/premises is fit for occupancy class "Educational" for a period of three years, subject to compliance of the conditions printed as under.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to:-

- 1. The Manager, Krishna Model Secondary School, Old Roshan Pura Extn., Najafgarh, New Delhi-110043.
- Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Ground plus three upper floors **INSPECTION REPORT** 1. Name & address of the building: Krishna Model Secondary School, Old Roshan Pura Extn., Najafgarh, New Delhi-110043. 2. Type of Occupancy : Educational 3. Type of Case : New 4. Details of Previous NOC : N/A 5. Fire Safety directives letter No : Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 6. Date of inspection : 19.01.2017 7. Name of Inspecting Officer : A.D.O. Sandeep Duggal 8. Name and designation of officers From the building side : Sh. Bhim Singh Yadav (Society Manager) 9. Year of Construction : Before 2009 10. Applicant's letter No. : Nil dated 16.11.2016 Minimum Standards on fire prevention and S. No. NBC/BBL/ Dir. Of Provided at Remarks fire safety U/R 33 Edu. Circular dt. site MR/NMR 01.03.2011 Requirement 1. Access to building Road width Accessible 06 mtrs 06 mtrs M/R Gate width 4.5 mtrs 4.5 mtrs MR N/A Width of internal road N/A N/A 2. Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors 01 No 02 No's M/R Basements N/A N/A N/A b. Width of staircases Upper Floor 150 cms or less upto 133 cms & 142 M/R Basements 75 cms & 75 cms cms c. Protection of exits N/A N/A N/A Fire check door Pressurization N/A N/A N/A N/A N/A N/A d. No. of continuous staircases to terrace Required One M/R Width of Corridor 150 cms 200 cms M/R Door Size 100 cms 105 cms M/R 3. Compartmentation Fire check door N/A N/A N/A Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A Fire Dampers N/A N/A N/A N/A 4. Smoke Management System Basements N/A N/A N/A Upper floors Required Natural M/R ventilation 5. Fire Extinguishers Total numbers 03 no's/floor Provided M/R Types ABC/CO<sub>2</sub> type Provided M/R IS marking ISI marked Provided M/R First-Aid Hose Reels 6. Total numbers on each floor 01 no. per floor Provided M/R Length of hose reel hose 30 M Provided M/R Nozzle diameter 5 mm Provided

MAD

7.	Automatic fire detection and alarming system			
	Type of detectors	N/A	N/A	N/A
	<ul> <li>Location of Main Panel</li> </ul>	N/A		
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
	· ·		N/A	N/A
8.	MOEFA	N/A	N/A ·	N/A
9.	Public Address System	N/A	Provided	N/A
10.	Automatic Sprinkler System	14/11	Tiovided	IN/A
	Basement	N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A		
1.	Internal Hydrants	IN/A	N/A	N/A
1.	· · · · · · · · · · · · · · · · · · ·	27/4	27/4	
	Size of riser/down-comer	N/A	N/A	N/A
	<ul> <li>Number of hydrants per floor</li> </ul>	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
2.	Yard Hydrants			
	<ul> <li>Total number of hydrants</li> </ul>	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
3.	<b>Pumping Arrangements</b>		- 3/4.4	1 1/1 1
	Ground Level			
	<ul><li>Discharge of main Pump</li></ul>	NT/A	27/4	27/1
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
		N/A	N/A	N/A
	Tooliey tamp out put	N/A	N/A	N/A
	> Jockey pump head	N/A		
	> Standby Pump out put		N/A	N/A
	> Standby Pump Head	N/A	N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A	N/A
20		N/A	N/A	N/A
	Pump House Access	N/A	N/A	N/A
	Terrace level			1 1/2 1
		450 I D. 6	450 % 100 I DV	
•	Discharge of pump	450 LPM	450 & 180 LPM provided	MR
	Head of the pump	30 mtr	Provided	MR
	Power Supply	Required	Provided	MR
	Auto Starting of pump	Required	Provided	MR
14.	Contino West St. C. C. C.	Required	1 TOVIDEU.	IVIK
+.	Captive Water Storage for fire fighting			9 2
	<ul> <li>Underground tank capacity</li> </ul>	N/A	N/A	N/A
	Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity			
		10,000 ltrs	Provided	MR
5.	Evit Signage	Required	Provided	MR
). j.	Exit Signage. Provision of Lifts.			No Lift
- 12		<b>N</b> T/4	37/4	
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	<ul> <li>Fireman's Grounding Switch</li> </ul>	N/A	N/A	N/A
	Lift Signage			
7	St. II	N/A	N/A	N/A
7.	Standby power supply	N/A	N/A	N/A
8.	Refuge Area.			
	> Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
	N I DO NOT THE REAL PROPERTY OF THE PARTY OF	IV/A	N/A	N/A

19.	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	<ul> <li>Flow Switch Panel</li> <li>PA System Panel</li> <li>Battery backup</li> </ul>	N/A	N/A	N/A		
		N/A	N/A	N/A		
	<ul><li>Battery backup</li><li>Building Floor Plans</li></ul>	N/A	N/A	N/A		
		N/A	N/A	N/A		
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Note:- As per letter submitted by the Manager (placed at C-8) they have removed the doors alongwith frame from class rooms and whenever they will fit the doors the minimum width of the door will be 100 cms.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation: - Asstt. Divisional Officer

D.O. (South West)

M.SCELL LE FT. Letter in put up y