GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADOUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110 001.**

No.F.6/DFS/MS/School/2017/SZ

Dated: 02/02/17

FIRE SAFETY CERTIFICATE

Certified that the Rashtra Shakti Vidyalaya, Gandhi Nidhi, Hastsal, Uttam Nagar, New Delhi-110059, comprised of ground floor plus two upper floors, owned/occupied by Rashtra Shakti Vidyalaya was issued FSC by this department vide letter F.6/DFS/MS/2011/285 dated 14.02.2011. The School building was re-inspected by the officer concerned of this department on 10.01.2017 in the presence of Smt. Shashi Tyagi (Principal) and found that the Rashtra Shakti Vidyalaya have deemed complied the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class "Educational" for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on at New Delhi.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to:-

- The Principal, Rashtra Shakti Vidyalaya, Gandhi Nidhi, Hastsal, Uttam Nagar, New Delhi-110059
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

School building is comprised of ground plus two upper floors.

INSPECTION REPORT

1. Name & address of the building: Rashtra Shakti Vidyalaya, Gandhi Nidhi, Hastsal, Uttam Nagar, New

Type of Occupancy : Educational

3. Type of Case : Renewal

4. Details of Previous NOC : F.6/DFS/MS/2011/225 (285) dated 14.02.2011

5. Fire Safety directives letter No : N/A
6. Date of inspection : 10.01.2017

7. Name of Inspecting Officer : A.D.O. Sandeep Duggal

8. Name and designation of officers

From the building side : Smt. Shashi Tyagi (Principal)

9. Year of Construction : Before 2010

10. Applicant's letter No. : RSV/FIRE-DEPT./2016/595 dated 02.12.2016

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as per FSC dt. 14.02.2011	Provided at site	Remarks MR/NMR
ι.	Access to building			
a	Road width	Accessible 06 mtrs	08 mtrs	M/R
	Gate width	4.5 mtrs	4.5 mtrs	M/R
	 Width of internal road 	N/A	N/A	N/A
2.	Number, Width, Type & Arrangement of Exit	S		,
V	a. Number of staircases			
	 Upper Floors 	03 No.'s	03 No.'s	M/R
	Basements	N/A	N/A	N/A
	b. Width of staircases			
	Upper Floor	150 cms/additional staircase of 75 cms	150, 153 &	M/R
	Basements	if less than 150 cms	123 cms	
	D. daddan of a lite	N/A	N/A	N/A
	c. Protection of exits			
	Fire check door Proposition The constitution The constitut	N/A	N/A	N/A
	Pressurization	N/A	N/A	N/A
	d. No. of continuous staircases to		,	
	terrace	Required	One	M/R
	e. Width of Corridor	150 cms	240 cms	M/R
	f. Door Size	100 cms	100 cms	M/R
3.	Compartmentation			
	Fire check door	N/A	N/A	N/A
	Sealing of electrical shafts	N/A	N/A	N/A
	Fire Rating of shaft door	N/A	N/A	N/A
	Water Curtain			N/A
	Fire Dampers	N/A N/A	N/A N/A	N/A N/A
	C. I. Managament Systems	IN/A	IN/A	IVA
4.	Smoke Management System	NT/A	N/A	N/A
	Basements	N/A	IN/A	IN/A
	Upper floors	Required	Natural ventilation provided	M/R
5.	Fire Extinguishers			
	Total numbers	14 no's	Provided	MR
	• Types	ABC/CO ₂ type	Provided	MR
	IS marking	ISI marked	Provided	MR
6.	First-Aid Hose Reels			
	Total numbers on each floor	02 no.'s per floor	Provided	MR
	1 Ol 11	30 mtrs	Provided	MR

7. Aut	amatic fire detection and alarming and			
Aut	 omatic fire detection and alarming system Type of detectors 	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	1	
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location		N/A	N/A
		N/A	N/A	N/A
	EFA	N/A	N/A	N/A
	lic Address System	N/A	Provided	N/A
0. Aut	omatic Sprinkler System	27/4	27/4	> T / A
	• Basement	N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
1. Inte	rnal Hydrants	27/	100	27/4
	 Size of riser/down-comer 	N/A	100 mm	N/A
	 Number of hydrants per floor 	N/A	One	N/A
2	Hose Box	N/A	One ·	N/A
2. Yar	d Hydrants			
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
3. Pun	nping Arrangements			
	Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps			N/A
	Jockey Pump out put	N/A	N/A	
	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A N/A	N/A N/A	N/A
*	Pump House Access	IN/A	IN/A	IVA
8	Terrace level			1.00
	Discharge of pump	450 LPM	Provided	MR
	Head of the pump	& 180 LPM	D '11	MD
	Power Supply	40 mtrs	Provided	MR
-	Auto Starting of pump	Required	Provided	MR
		N/A	N/A	N/A
4. Cap	tive Water Storage for fire fighting			
	 Underground tank capacity 	N/A	N/A	N/A
	Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	Provided	N/A
	Access to tank	N/A	N/A	N/A
	 Overhead Tank capacity 			
		10000 ltrs	Provided	MR
5. Exit	t Signage.	Required	Provided	MR
6. Pro	vision of Lifts.			No T:64
20	Duranication - £1 !A CL - A	N/A	N/A	No Lift N/A
	Pressurization of Lift Shaft Pressurization of Lift Shaft		231 40001 122	
	Pressurization of Lift lobby Communication In lift Com	N/A	N/A	N/A
	Communication In lift Car Figure 2.2 Constant Societals	N/A	N/A	N/A
	• Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17. Sta	ndby power supply	N/A	N/A	N/A
	2 311			
18. Ref	uge Area.			
	> Total Area	N/A	N/A	N/A

19.	Fire Control Room					
	Detector System PanelFlow Switch Panel	N/A	N/A	N/A		
		N/A	N/A	N/A		
	PA System PanelBattery backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
		N/A	N/A	N/A		
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection and the shortcomings communicated vide letter no. F.6/DFS/MS/2014/School/1081 dated 16.05.2014 has been complied.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the Fire Safety Certificate issued vide letter number F.6/DFS/MS/2011/225 (285) dated 14.02.2011 renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting Officer

Name:- Sandeep Duggal

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

12/1/12

505/DOCSW) 17-01-2017 549/CAOS2

DCFO (SZ)

18/1 F760.

GOST M.SCEU LE