## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No. F6/DFS/MS/2017/NDZ/ 25/

Dated: 22/2/17

## FIRE SAFETY CERTIFICATE

Gharoli, Mayur Vihar-III, School, Public Indian Anglo that the Certified Delhi-96 owned/occupied by Anglo Indian Public School comprised of ground plus three upper floors was granted fire safety certificate vide letter no. F6/MS/DFS/School/2013/NDZ/1271 dated-02/12/13. The school building was inspected by the officer concerned of this department on 08/02/17 in the presence of Sh.Jagpal Singh (Manager) and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with the rules and that the building is fit for occupancy Group B "Educational Building" with effect from .22/2-/17..... for a period of three years, subject to conditions printed overleaf.

Issued on ..... 22/2/17..... at New Delhi by

(Vipin Kental)
Chief Fire Officer

To,

The Manager,
Anglo Indian Public School,
Gharoli,Mayur Vihar -III,Delhi -96.

Copy to:-

1.The Dy. Director of Education, D-Block, Anand Vihar Delhi-92.

## CONDITIONS:

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, six months prior to its expiry.

1. Name & address of the building : Anglo Indian Public School at Gharoli, Mayur

Vihar-III, Delhi-96.

2. Building is comprised of : Ground +3, upper floor.

3. Type of Occupancy : Educational

4. Type of Case : Renewal

5. Details of Previous NOC letter : F.6/DFS/MS/08/2013 dated 02.12.2013

6. Fire Safety direction letter No : Director of Education

7. Date of Inspection : 08/02/17

8. Name of the Inspecting officers : ADO R.K. Yadav

9. Name and designation of Officer

from the building side : Sh.Jagpal Singh (Manager)

10. Year of Construction :1983

11. Applicant's letter No : AIPS/1554/16 dated 28/11/2016

NO	Minimum Standards on fire	Old Circular	Provided at Site	Remark	
NO	prevention and fire safety U/R33	Requirement	Trovided at oile	Ttomant	
1	Access to building				
	Road width	06 Mtrs.	1 length hose	MR	
	1 Toda Watii		form main road	7	
1	Gate width	N/A	N/A	N/A	
	Width of internal road	N/A	N/A	N/A	
2	Number, Width, Type and Arrangeme	ent of Exits			
	a. Number of Staircases				
	Upper Floor	02 Nos	02 Nos.	MR	
	Basement	N/A	N/A	N/A	
	B. Width of Staircases				
	Upper Floor	1.5 M or less	1.10 M & .60m	MR *	
French	Basement	N/A	N/A	N/A	
	c. Protection of exits	N/A	N/A	N/A	
	<ul><li>Fire check door</li><li>Pressurization</li></ul>	N/A	N/A	N/A	
	e. No. of continuous staircases to	N/A	N/A	N/A	
	terrace	1no.	1 No.	MR	
13.5	g. Width of Corridor	1.0 M	1.0 M	MR	
	h. Door Size	1.0 Mtrs	1.0 Mtrs	MR	
3	Compartmentation.		4		
	Fire check door	N/A	N/A	N/A	
	<ul> <li>Sealing of electrical shafts</li> </ul>	Required	Sealed	MR	
7	Fire rating of shaft door	N/A	N/A	N/A	
	Water curtain	N/A	N/A	N/A	
1 - 74	Fire Dampers	N/A	N/A	N/A	
4	Smoke Management System.	14//			
7	Basement	N/A	N/A	N/A	
	Upper floor	N/A	N/A	N/A	
F	3880.1100.	IN/A	IN/A	IN/A	
5.	Total numbers	08 Nos.	Provided	MR	
	Total numbers	ABC & Co2	Provided	MR	
	• Types	ISI marked	Provided	MR	
	IS marking	ISI IIIaikeu	Trovided	IVIIX	

	-	M	11-	-
--	---	---	-----	---

6	First-aid-Hose Reels.					
0		The state of the s		140		
	Total numbers of each floor	1no.	Provided	MR		
	<ul> <li>Length of hose reel hose</li> </ul>	30 M	Provided	MR		
	Nozzle diameter	5 mm	Provided	MR		
7	Automatic fire detection and alarming system.					
	Type of detectors	N/A	N/A	N/A		
	Location of main panel	N/A	N/A	N/A		
	<ul> <li>Location of repeater panel</li> </ul>	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooter's location	N/A	N/A	N/A		
8	MOEFA	Required	Provided	MR		
9	Public address System.	N/A	N/A	N/A		
10	Automatic Sprinkler System.					
	Basement	N/A	N/A	N/A		
	upper floor	N/A	N/A	N/A		
	sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants			V. A. J. H. T. T. L.		
	size of riser/down-comer	100 MM	Provided	MR		
	Number of hydrants per	1No.	Provided	MR		
-	floor					
	Hose Box	1No.	Provided	MR		
12	Yard Hydrants.			*		
12	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13	Pumping Arrangements.	N/A	N/A	N/A		
10	Ground Level	N/A	N/A	N/A		
	> Discharge of main Pump	N/A	N/A	N/A		
ek.	Head of Main Pump	N/A	N/A	N/A		
	> Number of main pumps	N/A	N/A	N/A		
	> Jockey pump out put	180 LPM	Provided	MR		
	> Jockey pump head	40 M	40 M	MR		
	> Standby pump out put	N/A	N/A	N/A		
	> Standby pump Head	N/A	N/A	N/A		
	Auto Starting /Manual	N/A	N/A	N/A		
	stopping	N/A	N/A	N/A		
- 107	> Pump House Access	IV/A	IV/A	IN/A		
	Terrace Level     Discharge of nump	450 LPM	Provided	MR		
	> Discharge of pump	450 LPM	40 LPM	MR		
	> Head of the Pump		Provided	MR		
- 4. 1	> Power supply	Required				
	Auto Starting of pump	Required	Provided	MR		
14	Captive Water Storage for Fire Fighting.	N/A	N/A	N/A		
	Underground tank capacity	N/A	N/A	N/A		
	> Draw-off connection	N/A	N/A	N/A		
	> Fire service inlet	N/A	N/A	N/A		
	> Access to tank	N/A	N/A	N/A		
	Overhead Tank capacity	5,000 Ltrs.	Provided	MR		
15	Exit Signage.	Required	Provided	MR		
	<b>V V</b>					

16	Provision of Lifts.	12 -		
10		NI/A	NI/A	NI/A
- 12	Pressurization of Lift Shaft	N/A	N/A	N/A
	<ul> <li>Pressurization of Lift lobby</li> </ul>	N/A	N/A	N/A
	<ul> <li>Communication in lift car</li> </ul>	N/A	N/A	N/A
- Harris	<ul> <li>Firemen's grounding switch</li> </ul>	N/A	N/A	N/A
	Lift Signage	» N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.	N/A	N/A	N/A
	Total area	N/A	N/A	N/A
	<ul> <li>Location</li> </ul>	N/A	N/A	N/A
19	Fire Control Room	N/A	N/A	N/A
	<ul> <li>Detector system panel</li> </ul>	N/A	N/A	N/A
~	<ul> <li>Flow switch panel</li> </ul>	N/A	N/A	N/A
	PA system panel	N/A	N/A	N/A
+	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A

The building was issued shortcomings vide letter no. F6/DFS/MS/School/2016/1951 dated 11/08/16. The same were checked and found functional at the time of inspection. Keeping in view the substantial compliance of the minimum standards on fire prevention and fire sefety required under the rules it is recommended to renew Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Signature of the Inspecting Officer

Name : R. K. Yadav

Designation: ADO(LN)

DO(ED)

DeFo(ND)