GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/EFS/MS/GH/2017/ NO 2/29/

Dated: 02/03/17

FIRE SAFETY CERTIFICATE

Certified that the Pakija Guest House located at 1141, Haveli Sadar Sadoor, Matia Mahal, Jama Masjid, Delhi-110006. comprised of Ground + 4 Upper Floors, Ground floor – commercial (other's property), 1st floor – reception + 04 guest rooms 2nd to 4th floor 03 guest rooms at each floor total 13 guest rooms was granted FSC by this department vide letter No.F6/DFS/MS/GH/2014/NDZ/433 dated 03/04/14. The premises was re-inspected by the officer concerned of this department on 11/02/17 in the presence of Mr. Feroz (Manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of class Residential Group –A-1 for total 13 guest rooms only as above with effect from – Political for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010. mentioned below.

Issued on ...ond.6.3./17..... at New Delhi by.

(Vipin Kental)
Chief Fire Officer
Delhi Fire Service
Ph: - 011-23412225

Copy to:-

- 1. The Joint. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi
- The Licensee,
 Pakija Guest House,
 1141, Haveli Sadar Sadoor, Matia Mahal, Jama Masjid, Delhi-110006...

Conditions:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. The means of escape shall be kept unobstructed / unlocked & remain available for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT

1.Name & address of the building:-

2. Type of occupancy:-

Pakija Guest House,1141,Haveli Sadar Sadoor, Matia Mahal,Jama Masjid,Delhi.

Residential Group A-1 Ground + 4 upper

Floor (13 guest rooms) ground floor –

commercial (other's properties), 1st floor – reception + 04 guest rooms,2nd to 4th floor 03 guest rooms at

each floor. Renewal

3. Type of case:-

4. Details of previous FSC:-

F6/DFS/MS/GH/2014/NDZ/433 dated

03/04/14

N/A

5. Fire safety directives No.-

6. Date of inspection:-

tion:- 11/02/17

7. Name of the inspecting officer:-

8. Name & designation of officer From the building side:-

D.O. Gurmukh Singh.

9. Year of construction:-

Mr. Feroz (Manager). 2006.

10. Applicant's letter No:-

06/Joint.C.P./Lic.(H) dated 02/01 17.

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety measures	Provided at site	Remarks MR/NMR	
1.	Access to Building	Ť			
	1) Road width	N/A	4 mtr.	MR	
	2) Gate width	N/A	N/A	N/A	
	3)Width of internal road	N/A	N/A	N/A	
2.	Number, Width Type & Arrangement of Exits				
T.L.	A. Number of staircases				
	1. Upper floors	01 No.	01 No.	MR	
	2. Basements	N/A	N/A	N/A	
	B. Width of staircase				
	1. Upper floors	80 cms.	90 cms.	MR	
	2. Basements	N/A	N/A	N/A	
	C. Protection of exits				
	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A	
	D. No. of continuous	N/A	N/A	N/A	
	staircase to terrace				
	E. Width of corridor	N/A	N/A	N/A	
	F. Door size	1 mtr.	1 mtr.	MR	
3.	Compartmentation				
	1) Fire check door	N/A	N/A	N/A	
	2) Sealing of electrical shafts	N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A	
	5) Fire Dampers	N/A	N/A	N/A	

4.	Smoke Management System			The state of the s
7.	1) Basements	N/A		
	2) Upper floors	30 ACPH 12 ACPH	N/A Natural	MR
5.	Fire Extinguishers	12 ACITI	Ivaturar	IVIIC
3.	1) Total numbers	08 Nos.	08 Nos.	MR
		ABC & CO2	ABC & CO2	MR
	2) Types	Required Required	Provided Provided	MR
6.	3) ISI marking First-Aid Hose Reel	Required	Flovided	IVIIC
0.		N/A	N/A	N/A
	1)Total number at each floor	IN/A	IN/A	IN/A
	2) Length of hose reel hose	N/A	N/A	N/A
	3) Nozzle diameter	N/A	N/A	N/A
7.	Automatic Fire Detection & A		14/21	11/11
7.	1) Type of detectors	N/A	N/A	N/A
(3)	2) Location of main panel	N/A	N/A N/A	N/A
	3) Location of repeater panel	N/A	N/A N/A	N/A
		N/A	N/A N/A	N/A N/A
	4) Alternate source of power		N/A N/A	N/A
0	5) Hooter's Location	N/A		N/A N/A
8.	MOEFA	N/A	N/A	
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			NT/A
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling			V 1/2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
11.	Internal Hydrants	15.77	37/1	77/4
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor	F-, 1, 1 H 117		
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants			
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
7-4-1	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump			
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump		N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output		N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	N/A
	stopping	1111		
	2) Terrace level			
	a) Discharge of pump	N/A	N/A	N/A
	b) Head of pump	N/A	N/A	N/A
	o) Head of pump	11/11	11/11	11/23

	c) Power supply	N/A	N/A	N/A		
	d) Auto starting of pump	N/A	N/A	N/A		
4.	Captive Water Storage for Fire Fighting					
	Under ground tank capacity	N/A	N/A	N/A		
	a) Draw-off connection	N/A	N/A	N/A		
	b) Fire service inlet	N/A	N/A	N/A		
	c) Access to tank	N/A	N/A	N/A		
	d) Over head tank capacity	N/A	N/A	N/A		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts.	STALL STALLS				
	a) Pressurization of lift	N/A	N/A	N/A		
	b) Pressurization of lift lobby	N/A	N/A	N/A		
	c) Communication in lift car	N/A	N/A	N/A		
	d) Fireman's switch	N/A	N/A	N/A		
	e) Lift signage	N/A	N/A	N/A		
17.	Stand by Power Supply	Required	Provided	MR		
18.	Refuge Area	N/A	N/A	N/A		
	Total area location.	N/A	.N/A	N/A		
19.	Fire Control Room	N/A	N/A	N/A		
	a) Detector system panel	N/A	N/A	N/A		
	b) Flow switch panel	N/A	N/A	N/A		
	c) PA system panel	N/A	N/A	N/A		
	d) Battery backup	N/A	N/A	N/A		
	e) Building floor plan	N/A	N/A	N/A		
20.	Special Fire Protection Syste any:	m for Protection	of special Risk, if	N/A		

The fire protection system provided in the guest house were tested, checked at random and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F6/DF\$/MS/GH/2014/NDZ/433 dated .03/04/2014, renewal under Rule 35 of the Delhi Fire Service rules 2010, is recommended.

> Gurmukh Singh Divisional Officer

Divisional Officer

Divisional Officer

The C.F. M. Scell Ffor

W. Scell M. Signalius please

F. 7 letter is put up for signalius please