

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI

HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

Fax No. 011-23412593, Ph. 011-23412225

No. F6/DFS/MS/EH/2017/SZ/ 284

Dated: 01/03/17

FIRE SAFETY CERTIFICATE

Certified that M/s **Punjabi BY Nature** (A Unit of A.R. Fisheries Pvt. Ltd.) located at **T-305, 3rd floor, Ambience Mall, Plot No-2, Nelson Mandela Marg, Vasant Kunj, New Delhi**, is running at third floor of a building comprised of three basements, ground plus three upper floors was granted FSC by this department vide letter No. F.6/DFS/MS/EH/2013/SZ/1230 dated 27/11/2013. The premises was re-inspected by the officer concerned of this department on 27.01.2017 in the presence of Mr. Tarak Majumdar (Manager) of the restaurant and observed that the said building have deemed complied with the Fire Prevention and Fire Safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fir for occupancy class-D "**Assembly Building**" (Restaurant) as above with effect from 01/03/17 for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 01/03/17 at New Delhi by


(Vipin Kental)
Chief Fire Officer

Copy to: -

1. M/s Punjabi by Nature Restaurant (A unit of A.R. Fisheries Pvt. Ltd.)
T-305, 3rd floor, Ambience Mall, Vasant Kunj, New Delhi-100070
2. The Joint C.P. (Lic.), First Floor, PS Defence Colony, New Delhi-110049
3. The DHO (Central Zone), South MCD, Health Deptt, Jal Vihar, Lajpat Nagar, ND-24

Conditions for the validity of Fire Safety Certificate

1. All the fire safety and means of escape facilities shall be maintained in good working condition at all time. Any lapse rendering the fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
2. Building Sanctioning authority may verify any deviation with regard to construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null & void.
3. The staff shall be trained for operating fire fighting system and mock evacuation drill be conducted at regular interval and record be maintained.
4. The basement shall be used strictly as per the provisions of Building Bye Laws.
5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in.
6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

1	Name & Address of the Building	M/s Punjabi By Nature (A unit of A.R. Fisheries Pvt. Ltd), T-305, 3 rd Floor, Ambience Mall, Vasant Kunj, New Delhi-110070		
2	Type of Occupancy	Assembly Building "Group-D" Restaurant		
3	Building Comprised of	03 tier basement, ground + 03 upper floors		
4	Type of Case	Renewal		
5	Details of Previous NOC	F.6/DFS/MS/EH/2013/SZ/1230 Dated 27/11/2013		
6	Fire Safety Directives Letter No	Nil		
7	Date of Inspection	19.11.2016		
8	Name of the Inspecting Officers	ADO R.N. Singh		
9	Name & Designation of Officers from the building side	Mr. Tarak Majumdar (Manager)		
10	Year of construction	2010 Restt running at 3 rd Floor of the building		
11	Applicant letter No.	CIN U74899 DL1987PTC029264 dated 25/10/2016		
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC 27/11/2013 Requirements	Provided at Site	Remarks MR/NMR
1	Access to Building.			
	• Road width	Required	09 mtr	MR
	• Gate width	N/A	N/A	N/A
	• Width of internal road	N/A	N/A	N/A
2	Number, width, type and arrangements of exits.			
	a. Number of Staircase			
	• Upper floors	Two	Two near restaurant	MR
	• Basement floor	N/A	N/A	N/A
	b. Width of Staircase			
	• Upper floors	1.50	1.40 m & 1.50 m	MR (old case0
	• Basement floor	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	Required	Provided by Ambience Mall	MR
	• Pressurization	Required	Provided by Ambience Mall	MR
	d. No. of continuous staircase to terrace	Required	Provided by Ambience Mall	MR
	e. Width of corridor	Required	Provided by Ambience Mall	MR
	f. Door size	2.0 m	2.0 m & 1.10 m (Final Exit)	MR
3	Compartmentation.			
	• Fire check door.	N/A	N/A	N/A
	• Sealing of electrical shafts.	N/A	N/A	N/A
	• Fire rating of shaft door.	N/A	N/A	N/A
	• Water curtain	N/A	N/A	N/A
	• Fire dampers.	N/A	N/A	N/A
4.	Smoke Management system.	Provided & Maintained by Ambience Mall		
	• Basement	30 a/c per hour	Provided By Mall	MR
	• Upper floors	12 a/c per hour	Provided By Mall	MR
5.	Fire Extinguishers.			
	• Total numbers	ISI marked	10 Nos.	MR
	• Types		ABC-06/ W.Co2-04	MR
	• ISI Marking		Provided	MR
6.	First Aid Hose Reels.			
	• Total numbers on each floor.	Required	Provided by Ambience Mall	MR
	• Length of hose-reel hose.	30 mtr	Provided by Ambience Mall	MR
	• Nozzle Diameter	05 mtr	Provided by Ambience Mall	MR

7	Automatic Fire Detection and Alarming system.			
	• Type of detectors	Required	Provided by Ambience Mall	MR
	• Location of Main Panel	Required	Provided by Ambience Mall	MR
	• Location of Repeater Panel	Required	Provided by Ambience Mall	MR
	• Alternate source of power	Required	Provided by Ambience Mall	MR
	• Hooter's location	Required	Provided by Ambience Mall	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			Provided & Maintained by Ambience Mall
	• Basement	Required	Provided by Ambience Mall	MR
	• Upper floors	Required	Provided by Ambience Mall	MR
	• Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants.			Provided & Maintained by Ambience Mall
	• Size of Riser/Down-comer	Required	Provided by Ambience Mall	MR
	• Number of Hydrant per floor	Required	Provided by Ambience Mall	MR
	• Hose box.	Required	Provided by Ambience Mall	MR
12.	Yard Hydrants.			Provided & Maintained by Ambience Mall
	• Total number of hydrants.	N/A	N/A	N/A
	• 2. Hose box.	N/A	N/A	N/A
13.	Pumping arrangements.			Provided & Maintained by Ambience Mall
	• Ground Level	Provided & Maintained by Ambience Mall		
	➤ Discharge of main pump.	N/A	N/A	N/A
	➤ Head of main pump.	N/A	N/A	N/A
	➤ Number of main pumps.	N/A	N/A	N/A
	➤ Jockey Pump output.	N/A	N/A	N/A
	➤ Jockey Pump head.	N/A	N/A	N/A
	➤ Standby Pump output.	N/A	N/A	N/A
	➤ Standby Pump head.	N/A	N/A	N/A
	➤ Auto Starting / Manual Stopping.	N/A	N/A	N/A
	➤ Access to pump house	N/A	N/A	N/A
	• Terrace Level	Provided & Maintained by Ambience Mall		
	➤ Discharge of pump.	Required	Provided by Ambience Mall	MR
	➤ Head of pump.	Required	Provided by Ambience Mall	MR
	➤ Power supply.	Required	Provided by Ambience Mall	MR
	➤ Auto starting of pump.	Required	Provided by Ambience Mall	MR
14.	Captive water storage for Fire Fighting.			Provided & Maintained by Ambience Mall
	• Underground tank capacity.	Required	Provided by Ambience Mall	MR
	➤ Draw-off connection.	Required	Provided by Ambience Mall	MR
	➤ Fire Service Inlet.	Required	Provided by Ambience Mall	MR
	➤ Access to tank.	Required	Provided by Ambience Mall	MR
	• Overhead tank capacity.	Required	Provided by Ambience Mall	MR
15.	Exit Signage.	Required	Provided by Ambience Mall	MR
16.	Provision of Lifts.			Provided & Maintained by Ambience Mall
	• Pressurization of lift shaft.	N/A	N/A	N/A
	• Pressurization of lift lobby.	N/A	N/A	N/A
	• Communication in lift car.	N/A	N/A	N/A
	• Fireman's switch.	N/A	N/A	N/A
	• Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided (DG Set)	MR
18.	Refuge Area			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A

19.	Fire Control Room.	Provided & Maintained by Ambience Mall			
		• Detector System Panel.	N/A	As above	N/A
		• Flow Switch Panel.	N/A	As above	N/A
		• PA system Panel.	N/A	As above	N/A
		• Battery backup	N/A	As above	N/A
• Building floor plan	N/A	As above	N/A		
20.	Special Fire Protection System for the Protection of special Risk, if any :	N/A	As above	N/A	

The Fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/EH/2013/SZ/1230 Dated 27/11/2013, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

R.N. Singh
6/2/17

Signature of the Inspecting Officer
Name : R.N. Singh
Designation: ADO

Renewal

Punjabi by Nature Restt, T-305, 3rd floor, Ambience Mall, Vasant Kunj

Div. Officer (SD)

Put up with a copy of Ambience Mall FSC.

ADG
RNS

Sir.

Anilash
10/2/17

FSC of Ambience mall placed on 11/14/17

DO/DO
Anilash
17/2/17

R.N. Singh
14/2