GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2017/SZ

262

Dated: 23/2/17

FIRE SAFETY CERTIFICATE

Certified that the Mahashai Chunilal Saraswati Bal Mandir Senior Secondary School, L-Block, Hari Nagar, New Delhi-110064 comprised of ground floor plus two upper floors owned/occupied by Mahashai Chunilal Saraswati Bal Mandir Senior Secondary School was issued Fire Safety Certificate by this department vide letter F.6/DFS/MS/School/2013/711 dated 14.8.2013. The School building was reinspected by the officer concerned of this department on 10.02.2017 in the presence of Sh. Vasudev (Security Guard) and found that Mahashai Chunilal Saraswati Bal Mandir Senior Secondary School have deemed complied the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (Except room no. 52 & 53) is fit for occupancy class "Educational" for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to:-

- The Manager, Mahashai Chunilal Saraswati Bal Mandir Senior Secondary School, L- Block, Hari Nagar, New Delhi-110064
- Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

school building is comprised of ground plus two upper floors. INSPECTION REPORT 1. Name & address of the building: Mahashai Chunilal Saraswati Bal Mandir Senior Secondary School, L-Block, Hari Nagar, New Delhi-110064. Type of Occupancy Educational Type of Case Renewal 4. Details of Previous NOC F.6/DFS/MS/School/2013/711 dated 14.8.2013 5. Fire Safety directives letter No N/A 6. Date of inspection 10.02.2017 7. Name of Inspecting Officer A.D.O. Sandeep Duggal 8. Name and designation of officers From the building side Sh. Vasudev (Security Guard) 9. Year of Construction Before 2000 10. Applicant's letter No. Sbm/HN/1088/12/2016 dated 09.12.2016 Minimum Standards on fire prevention and S. No. Requirement Provided at fire safety U/R 33 Remarks as per FSC dt. site MR/NMR 14.8.2013 1. Access to building Road width Accessible 06 mtrs 6.4 mtrs M/R Gate width Old case 4.4, 4.35 & 1.73 mtrs MR, being old case Width of internal road N/A N/A N/A 2. Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors 03 No.'s 03 No.'s Basements M/R b. Width of staircases N/A N/A N/A Upper Floor Basements 150 cms/additional 130, 125 & M/R c. Protection of exits staircase of 75 cms 122 cms if less than 150 cms Fire check door N/A N/A Pressurization N/A d. No. of continuous staircases to N/A N/A N/A terrace N/A N/A N/A e. Width of Corridor N/A Door Size N/A N/A 150 cms. 263 & 239 cms M/R Old case 98 & 98 cms MR, being old (Double door) 3. case Compartmentation Fire check door N/A N/A N/A Sealing of electrical shafts N/A N/A Fire Rating of shaft door N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A N/A N/A 4. Smoke Management System N/A Basements N/A N/A N/A Upper floors Required Natural ventilation M/R provided 5. Fire Extinguishers Total numbers 22 no's Provided MR Types ABC/CO₂ type Provided MR IS marking Provided ISI marked MR 6. First-Aid Hose Reels Total numbers on each floor 02 no.'s/ floor Provided MR Length of hose reel hose 30 mtrs Provided MR Nozzle diameter

7.	Automatic fire detection and alarming system					
58	Type of detectors	N/A	N/A	N/A		
	Location of Main Panel	N/A	N/A	N/A		
	 Location of Repeater Panel 	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooters' Location	N/A	N/A	N/A		
8.	MOEFA	N/A	Provided	N/A		
9.	Public Address System	N/A	Provided	N/A		
10.	Automatic Sprinkler System					
	Basement	N/A	N/A	N/A		
	Ground Floor	N/A	N/A	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11.	Internal Hydrants					
	Size of riser/down-comer	N/A	N/A	N/A		
	Number of hydrants per floor	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
12.	Yard Hydrants			-		
	 Total number of hydrants 	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13.	Pumping Arrangements					
	Ground Level					
	Discharge of main Pump	N/A	N/A	N/A		
. ,	> Head of Main pump	N/A	N/A	N/A		
	Number of main pumpsJockey Pump out put	N/A	N/A	N/A		
	> Jockey pump head	N/A	N/A	N/A		
	Standby Pump out put	N/A	N/A	N/A		
	Standby Pump Head	N/A	N/A	N/A		
	Auto Starting/Manual Stopping					
		N/A	N/A	N/A		
		N/A	N/A	N/A		
	Pump House Access	N/A	N/A	N/A		
	Terrace level					
	Discharge of pump	450 LPM	360 LPM (02 no.'s) Provided	MR		
	Head of the pump	40 mtrs	Provided	MR		
	Power Supply	Required	Provided	MR		
	> Auto Starting of pump	N/A	N/A	N/A		
				. P		
14.	Captive Water Storage for fire fighting					
	Underground tank capacity	N/A	N/A	N/A		
	> Draw-off connection	N/A	N/A	N/A		
	Fire service inlet	N/A	Provided	N/A		
	Access to tank	N/A	N/A	N/A		
	Overhead Tank capacity	10000 ltrs	20,000 ltrs	MR		
		100001113		11111		
			Provided			
15.	Exit Signage.	Required	Provided Provided	MR		
		Required	Provided			
	Provision of Lifts.		Provided No Li	ft		
	Provision of Lifts. • Pressurization of Lift Shaft	N/A	Provided No Li N/A	ft N/A		
	Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby	N/A N/A	Provided No Li N/A N/A	ft N/A N/A		
	Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car	N/A N/A N/A	Provided No Li N/A N/A N/A	ft N/A N/A N/A		
	Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch	N/A N/A	Provided No Li N/A N/A	ft N/A N/A		
	Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car	N/A N/A N/A	Provided No Li N/A N/A N/A	ft N/A N/A N/A		
16.	Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch	N/A N/A N/A N/A	Provided No Li N/A N/A N/A N/A N/A	ft N/A N/A N/A N/A		
17.	Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage Standby power supply	N/A N/A N/A N/A N/A	Provided No Li N/A N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A N/A		
15. 16. 17.	Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage	N/A N/A N/A N/A N/A	Provided No Li N/A N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A N/A		

2/14

19.	Fire Control Room			
	 Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection and shortcomings communicated vide letter no. F.6/DFS/MS/School/2016/SZ dated 04.11.2016 has been complied.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number <u>F.6/DFS/MS/School/2013/711</u> dated <u>14.8.2013</u> renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Note:- As per letter submitted by the Principal (placed at C-18) Class room no. 50 & 53 will not be used for teaching purpose as both rooms does not meet the travel distance.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation: - Asstt. Divisional Officer

Divisional Officer (South West)

DCFD(SZ)

13/2/2017

629 CFO SE

1412/17 1412/17 122/35 degree

(57) PTh