GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2017/ 315

Dated: 03 /03 /17

FIRE SAFETY CERTIFICATE

Certified that M/s Megha Palace guest house located at 39/3, Bara Bazaar Marg, Old Rajinder Nagar, New Delhi- 60 comprised of lower ground floor (reception, office & 01 guest room), upper ground floor (04 guest rooms), first floor (04 guest rooms), second floor (02 guest rooms) and total 11 guest rooms. 02 rooms at half portion of second floor & 04 rooms at third floor are used as personal/residential purpose by the owner) and fourth floor (sealed with pucca brick wall by the owner) was issued FSC by this department vide letter no. F.6/DFS/MS/GH/SZ/2013/1249 dated 28.11.2013. The guest house was re-inspected by the officer concerned of this department on 20.02.2017 in presence of Mr. Shekhar Chand, manager and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class residential (Guest house) w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on <u>03/9/17</u> at New Delhi.

(VIPIN KENTAL) CHIEF FIRE OFFICER

9c day

Copy to: -

- 1. The Joint C.P..C.P (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.
- The Manager,
 M/s Megha Palace guest house,
 39/3, Bara Bazaar Marg, Old Rajinder Nagar,
 New Delhi- 110060.

Following fire safety directives must be adhered to: a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management. b. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency. risk and responsibility of the management.

- c. Any loss of life or property due to non-functional fire safety measures shall be at the
- d. Building Sanctioning authority may verify any deviation with regard to the construction / occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- e. Basement shall be used as per the building bye laws.
- The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- g. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on website www.dfs.delhigovt.nic.in
- h. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' (sub rule (1) of rule 37) along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building : M/s Megha Palace guest house, 39/3, Old Rajinder Nagar, Bara bazaar Marg, New Delhi-60.

2. Type of Occupancy : Lodging House

3. Type of Case : Renewal

4. Details of previous NOC : F.6/DFS/MS/GH/SZ/2013/1249 dated 28.11.2013

5. Fire Safety directives letter No : N/A.

6. Date of inspection : 20.02.2017

7. Name of the Inspecting Officers: M.K. Chattopadhyay, Divisional Officer (South West)

8. Name and designation of officers

from the building side : Mr. Shekhar Chand, manager

9. Year of Construction : 1999-2000

10. Applicant's letter No. : 3948/Joint C.P./Lic(H) dated New Delhi the 15.11.2016

The said guest house is comprised of lower ground, upper ground and four upper floors. FSC was granted for lower ground, upper ground, first and half portion of second floor. Half of second floor and third floor is used as residential purpose by owner. Fourth floor is sealed by pucca brick wall.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as per letter dated- 28.11.2013	Provided at site	Remarks MR/NMR		
1	Access to building					
	Road width	06 mts	06 mts	MR		
	Gate width	05 mts	Directly accessible	MR		
	Width of internal road	N/A	N/A	N/A		
2	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases	-	-	- :		
	Upper Floors	01	01	MR being old case		
	Basements	-	-	-		
	b. Width of staircases	-		-		
	Upper Floors	Old case	0.90 mt.	MR being old case		
	Basements		-			
	c. Protection of exits	-	=	-		
	Fire check door	N/A	N/A	N/A		
	Pressurization	N/A	N/A	N/A		
	e. No. of continuous staircases to terrace	01	01	MR		
	g. Width of Corridor	1.0 mt.	1.40 mts.	MR		
	h. Door Size	1.0 mt.	0.80 mt.	MR being old case		
3	Compartmentation.					
-	Fire check door	N/A	N/A	N/A		
	Sealing of electrical shafts	N/A	N/A	N/A		
	Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
4	Smoke Management System.					
	Basements	30 a/c per hour	N/A	N/A		

5 Fire Extinguishers							
	Total numbers	12	Provided	MR			
	• Types	CO ₂ , ABC type	Provided	MR			
	IS marking	ISI marked	Provided	MR			
6	First-Aid Hose Reels.						
	Total numbers on each floor	Not required	Provided				
	• Length of hose reel hose	30 m	Provided				
	Nozzle diameter	5 mm	Provided				
7	Automatic fire detection and alarming system.						
	Type of detectors	N/A	N/A	N/A			
	 Location of Main Panel 	N/A	N/A	N/A			
	Location of Repeater Panel	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooters' Location	N/A	N/A	N/A			
8	MOEFA	N/A	Provided				
9	Public Address System.	N/A	Provided				
10	The read of the re						
	• Basement	N/A	» N/A	N/A			
	Upper Floor	N/A	N/A	N/A			
	Sprinkler above false ceiling	N/A	N/A	N/A			
11	Internal Hydrants			1 1 1 2			
	Size of riser/down-comer	N/A	N/A	N/A			
	Number of hydrants per floor	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
12	Vand Hydranta	11/11	14/71				
12	Yard Hydrants.Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A N/A		N/A N/A			
13	Pumping Arrangements.	IV/A	N/A	IV/A			
ň.	Ground Level			-			
	Discharge of main Pump	N/A	N/A	N/A			
	> Head of Main pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	Jockey Pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	Standby Pump out putStandby Pump Head	N/A N/A	N/A N/A	N/A			
	Standby Pump HeadAuto Starting/ Manual	N/A	N/A	N/A			
	stopping standar	N/A	N/A	N/A			
	> Pump House Access	N/A	N/A	N/A			

		2 rectains of pump		Provided					
C		Head of the pump	N/A	30 mts	7 3				
		Power Supply	Required	Provided	MR				
		 Auto Starting of pump 	N/A	N/A	N/A				
14	Capti	aptive Water Storage for fire fighting.							
	•	Underground tank capacity	N/A	N/A	N/A				
	>	Draw-off connection	N/A	N/A	N/A				
	>	Fire service inlet	N/A	N/A	N/A				
	>	Access to tank	N/A	N/A	N/A				
	•	Overhead Tank capacity	N/A	3000 lts					
15	Exit S	gnage.	Required	Provided	MR				
16	Provis	ovision of Lifts.							
112	•	Pressurization of Lift Shaft	N/A	N/A	N/A				
	•	Pressurization of Lift lobby	N/A	N/A	N/A				
	•	Communication In lift Car	Required	Provided	MR				
		Fireman's Grounding Switch	N/A (Old Lift)	N/A	N/A				
	•	Lift Signage	Required	Provided	MR				
17	Standb	y power supply	Required	Provided	MR				
18									
	>	Total Area	N/A	N/A	N/A				
	>	Location	N/A	N/A	N/A				
19	Fire Control Room								
	•	Detector System Panel	N/A	N/A	N/A				
_	•	Flow Switch Panel	N/A	N/A	N/A				
	•	PA System Panel	N/A	N/A	N/A				
	•	Batter backup	N/A	N/A	N/A				
	•	Building Floor Plans	N/A	N/A	N/A				
20		Fire Protection Systems for on of special Risks, if any:	Required	Two ABC type fire extinguisher found provided near elect. panel	MR				
	The fire protection systems were '111' at 11'								

The fire protection systems provided in the building were checked and found functional at the time of inspection.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/GH/SZ/2013/1249 dated 28.11.2013, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

dans

M.K. CHATTOPADHYAY
Divisional Officer (South West)