GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2017/SZ / 4 4 6

Dated: 24/3/17

FIRE SAFETY CERTIFICATE

Certified that the **Govt. Co-ed. Sarvodaya Vidyalaya**, Dichaon Kalan, New Delhi-110043 comprised of Ground floor plus one upper floor having total 20 rooms (Including Class Rooms, Offices, Labs, Staff Room & Store etc.) owned/occupied by Govt. of NCT of Delhi was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2014/SZ/353 dated 21.03.2014. The School was re-inspected by the officer concerned of this department on 04.03.2017 in the presence of Sh. Harkesh (Vice-Principal) and found that Govt. Co-Ed. Sarvodaya Vidyalaya have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on at New Delhi.

(VIPIN KENTAL)
CHIEF FIRE OFFICER

Copy to:-

- The Principal, Govt. Co-ed. Sarvodaya Vidyalaya, Dichaon Kalan, New Delhi-110043
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The exits shall be unlocked & unobstructed for unhindered evacuation of occupants in case of any emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Alfall		INSPECTION	REPORT			
2. 3. 4.	Type Type Deta	of Occupancy : Educational of Case : Renewal ils of Previous NOC : F.6/DFS/MS/So	urvodaya Vidyalaya chool/2014/SZ/353 /Estate/CC/Fire Safety	dated 21.03.2014		
6	Date	of inspection : 04.03.2017				
7.	Nam	e of Inspecting Officer : A.D.O. Sandeep	p Duggal			
		e and designation of officers the building side : Sh. Harkesh (V	ice-Principal)			
9.	Year	of Construction : 2013-14				
	Appl	icant's letter No. : SV/DK/2017/9	922 dated 09.02.201	7 Provided at	Remarks	
S. No.		nimum Standards on fire prevention and safety U/R 33	Requirement as per FSC dt. 21.03.2014	site	MR/NMR	
1.	Ac	cess to building	1,000			
		Road width	Accessible 06 mtrs	06 mtrs	MR	
		Gate width	4.5 mtrs N/A	5.8 mtrs. N/A	MR N/A	
		• Width of internal road	N/A	N/A	IV/A	
2.	Nu	mber, Width, Type & Arrangement of Exits				
	a.	Number of staircases	02.71	02.21-2	MR	
		Upper Floors Programmer Programmer	03 No.'s	03 No.'s	MR N/A	
	h	Basements Width of staircases	N/A	N/A	IN/A	
	U.	Upper Floor	150 cms	158, 158 &	MR	
		Basements	130 cms	158 cms	IVIIC	
			N/A	N/A	N/A	
		Protection of exits				
		• Fire check door	N/A	N/A	N/A	
		Pressurization	N/A	N/A	N/A	
				3		
	d.	No. of continuous staircases to terrace	N/A	One	N/A	
	e.	Width of Corridor	150 cms	177 cms	MR	
	f.	Door Size	100 cms	102cms. (Double door)	MR	
3.	Co	mpartmentation				
		Fire check door	N/A	N/A	N/A	
		Sealing of electrical shafts	N/A	N/A	N/A	
		Fire Rating of shaft door	N/A	N/A	N/A	
		Water Curtain	N/A	N/A	N/A	
		Fire Dampers	N/A	N/A	N/A	
4.	Sr	noke Management System				
		Basements	N/A	N/A	N/A	
		Upper floors	Required	Natural Ventilation provided	MR	
5.	Fi	ire Extinguishers	1 1 1 -	*		
*		Total numbers	08 No's	Provided	MR	
		• Types	ABC/CO ₂ type	Provided	MR	
		IS marking	ISI marked	ISI marked	MR	
		V AND Hora Pola	181 marked			
6.	F	• Total numbers on each floor	N/A	N/A	N/A	
		• Length of hose reel hose	N/A	N/A	N/A	
WATER TO			N/A	NI/A	NI/A	

7.	Automatic fire detection and alarming system			
	Type of detectors	N/A	N/A	N/A
	 Location of Main Panel 	N/A	N/A	N/A
	 Location of Repeater Panel 	N/A	N/A.	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	. N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System		*	
	Basement	N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants	NI/A	NI/A	NI/A
	Size of riser/down-comer	N/A N/A	N/A N/A	N/A N/A
	Number of hydrants per floor	N/A N/A	N/A	N/A
10	Hose Box Verd Hardware	IN/A	IN/A	IV/A
12.	Yard Hydrants	N/A	N/A	N/A
	Total number of hydrantsHose Box	N/A N/A	N/A N/A	N/A N/A
13.		1N/ A	IN/A	IVA
13.	• Ground Level	THE HEAD LANGE		
	Ground LevelDischarge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
5.23	Number of main pumps			
	Jockey Pump out put	N/A	N/A	N/A
12 3	> Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump HeadAuto Starting/Manual Stopping	N/A	N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A	N/A
757.17		N/A	N/A	N/A
	Dung Hayaa Aaaaa	N/A	N/A	N/A
	Pump House AccessTerrace level	1 1 1 1 1 1 1		
	Terrace levelDischarge of pump	N/A	N/A.	N/A
	> Head of the pump	N/A	N/A	N/A
	Power Supply	N/A	N/A	N/A
	> Auto Starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for fire fighting			2
	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	> Fire service inlet	N/A	N/A	N/A
121	> Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
15.	Exit Signage.	N/A	N/A	N/A
16.	Provision of Lifts.		× "	(No Lift)
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	• Lift Signage			
		N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
18.	Refuge Area.			
	> Total Area	N/A	N/A	N/A

19.	Fire Control Room			
	Detector System Panel	N/A	N/A	N/A
	• Flow Switch Panel .	N/A	N/A.	N/A
	PA System Panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number <u>F.6/DFS/MS/School/2014/SZ/353</u> dated <u>21.03.2014</u> renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation: - Asstt. Divisional Officer

167/DOCSID)

09.03.2017

Divisional Officer (South West)

DCFO(SZ)

712/6-52

2568

xagrif 14/3

Cho of

FTM

m scell

15/3.