GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2017/SZ/ 444

Dated: 24/3/17

FIRE SAFETY CERTIFICATE

Certified that the **S.D.M.C Primary Girls Partibha School**, Jharoda Kalan, New Delhi-110072 comprised of ground plus one upper floor, having total 19 rooms (Including Class Rooms, Office, Comp. Room, Sci. Lab, Sports Room, Store & Hall etc.) owned/occupied by S.D.M.C was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2013/SZ/698 dated 13.08.2013. The school building was reinspected by the officer concerned of this department on 04.03.2017 in the presence of Smt. Kanta Kumari (Incharge) and found that the S.D.M.C Primary Girls Partibha School have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on 24/3/17 at New Delhi.

(VIPIN KENTAL)
CHIEF FIRE OFFICER

Copy to:-

- The Principal,
 S.D.M.C Primary Girls Partibha School,
 Jharoda Kalan, New Delhi-110072
- 2. Director of Education, S.D.M.C, Civic Centre, Minto Road, New Delhi-110001.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Comprised of Ground plus one upper floor INSPECTION REPORT S.D.M.C Primary Girls Partibha School, Jharoda Kalan, New Delhi-72 Name & address of the building Educational Type of Occupancy 2. Renewal 3. Type of Case 4. Details of Previous NOC F.6/DFS/MS/School/2013/SZ/698 dated 13.08.2013 5. Fire Safety directives letter No Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 04.03.2017 6. Date of inspection A.D.O. Sandeep Duggal 7. Name of Inspecting Officer 8. Name and designation of officers Smt. Kanta Kumari (In-charge) From the building side 9. Year of Construction Before 2011 Nil dated 07.02.2017 10. Applicant's letter No. Provided at Requirement Remarks Minimum Standards on fire prevention and S. No. MR/NMR as per FSC dt. site fire safety U/R 33 13.08.2013 1. Access to building Accessible 06 mtrs MR 10 mtrs Road width N/A N/A N/A Gate width N/A N/A N/A Width of internal road Number, Width, Type & Arrangement of Exits 2. a. Number of staircases Upper Floors 01 no. MR 01 no. Basements N/A N/A N/A b. Width of staircases Upper Floor 150 cms 155 cms MR Basements N/A N/A N/A Protection of exits N/A N/A N/A Fire check door N/A N/A N/A Pressurization N/A N/A One d. No. of continuous staircases to MR 220 cms 150 cms terrace 110 cms MR Width of Corridor 100 cms Door Size 3. Compartmentation N/A N/A N/A Fire check door Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A Smoke Management System 4. N/A N/A N/A Basements Natural Ventilation MR Required Upper floors provided 5. Fire Extinguishers MR Provided 05 No's Total numbers ABC/CO₂ type MR Provided Types ISI marked MR IS marking ISI marked First-Aid Hose Reels 6. N/A N/A N/A Total numbers on each floor

7.	Automatic fire detection and alarming system			
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	 Location of Repeater Panel 	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	. N/A	Provided	N/A
10.	Automatic Sprinkler System			
10.	Basement	N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	Size of riser/down-comer	N/A	N/A	N/A
	 Number of hydrants per floor 	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants			
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			N. TENEZA
	Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	> Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put		and the second second	N/A
	> Jockey pump head	N/A	N/A	
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump HeadAuto Starting/Manual Stopping	N/A	N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
	Down House Access	N/A	N/A	N/A
	Pump House AccessTerrace level			
	Discharge of pump.	N/A	N/A	N/A
1	Head of the pump	N/A	N/A	N/A
	> Power Supply	N/A	N/A	N/A
	➤ Auto Starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	> Access to tank	N/A	N/A	N/A
	 Overhead Tank capacity 		N/A	N/A
1.5	D 14 C	N/A N/A	N/A N/A	N/A N/A
15.	Exit Signage.	IN/A	IN/A	IVA
16.	Provision of Lifts.		*	(No Lift)
1 49	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
I kin s	• Lift Signage			
*		N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
18.	Refuge Area.			
	> Total Area	N/A	N/A	N/A
	> Location			

N/A	N/A	N/A
N/A	N/A	N/A
	N/A N/A N/A N/A	N/A N/A N/A N/A N/A N/A N/A N/A N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2013/SZ/698 dated 13.08.2013 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer Name: - Sandeep Duggal

Designation: - Asstt. Divisional Officer

161 DOCCW) 09/02/2017

Divisional Officer (South West)

F.T. Letter is put up for signature please.

Souther Scell Wills.