## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F.6 / DFS / MS / 2017 / 50 /

Dated: 03 / 04/2017

## **FIRE SAFETY CERTIFICATE**

## Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.Delhigovt.nic.in">www.dfs.Delhigovt.nic.in</a>

Issued on 0.3/64/12 at New Delhi

Chief Fire Officer Ph:-011-23414250

Copy to: -

- 1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi 110054.
- 2. The Principal, Adriel High School, Pocket-2, Sector-24, Rohini, New Delhi-110085.

## **INSPECTION REPORT**

1. Name & address of the building : Adriel High School, Pocket-2, Sector-24, Rohini, New Delhi-110085.

2. Type of Occupancy : Educational

3. Type of Case : Renewal (G+03floors-School at G+02 floors & 3<sup>rd</sup> Floor-Residence)

4. Details of previous NOC : F6/DFS/MS/2011/2171 dated 07.09.2011( G + 02 floors )

5. Fire Safety directives letter No : NBC Part-46. Date of inspection : 18/03/2017

7. Name of the Inspecting Officers : ADO (RN)

8. Name and designation of officers

from the building side : Ms. Poonam Leekha (Principal)

9. Year of Construction : 2004-2013

10. Applicant's letter No. : Nil dated 27.01.2017

Plot Area-4054.05 sqm Covered Area:2627.025 sqm

class rooms -29nos,

students---634 nos

	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR		
	Access to building					
	<ul><li>Road width</li><li>Gate width</li></ul>	06m 4.5m	06m 4.5m	MR MR		
	Width of internal road	NA	NA	NA		
	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases					
	Upper Floors	02	02	MR		
	<ul> <li>Basements</li> <li>b. Width of staircases</li> <li>Upper Floors</li> <li>Basements</li> </ul>	NA	NA	NA		
		1.50m	1.50m NA	MR NA		
	c. Protection of exits	NA	NA	INA		
	<ul><li>Fire check door</li><li>Pressurization</li></ul>	NA	NA	NA		
		NA	NA	NA		
	d. No. of continuous staircases to terrace	01	01	MR		
	e. Width of Corridor f. Door Size	NA	NA	NA		
		1 m	01m	MR		

3	Compartmentation.			21	
	Fire check door	NA	NA	NA	
	Sealing of electrical shafts	NA	NA NA	NA NA	
	Fire Rating of shaft door	NA	NA		
	Water Curtain			NA	
	Fire Dampers	NA	NA	NA	
4	Smoke Management System.	NA	NA	ŇA	
	Basements	30 a/c per hour	NA	274	
	Upper floors			NA	
		12 a/c per hour	Natural Ventilated	MR	
5	Fire Extinguishers				
	Total numbers	11nos	16 nos	MR	
	• Types	ABC/Co2	ABC16	MR	
	ISI marking	ISI Marked	Yes	MR	
5	First-Aid Hose Reels.				
	Total numbers on each floor	01	02each floor	MR	
	<ul> <li>Length of hose reel hose</li> </ul>	30m	30m	MR	
	Nozzle diameter	5mm			
7	Automatic fire detection and alarming syst	em.	5mm	MR	
	Type of detectors	NA	NA	NA	
	Location of Main Panel	NA	NA	NA	
	Location of Repeater Panel	NA	NA	NA	
	Alternate source of power	NA	NA	NA	
	Hooters' Location	NA	0.505691	- 2	
	MOEFA	NA NA	NA	NA	
	Public Address System.	Required	NA Provided	NA	
0	Automatic Sprinkler System.	Required	Provided	MR	
	Basement	NA	NA NA	271	
	Upper Floor	NA NA	NA NA	NA NA	
	Sprinkler above false ceiling	NA	NA	NA	
l	Internal Hydrants			1721	
	Size of riser/down-comer	0.1	0.1	100	
	Number of hydrants per floor	01	01	MR	
	Hose Box		01	MR	
	Yard Hydrants.	02	02	MR	
5	Total number of hydrants	NTA I	3.7	18	
	Hose Box	NA	NA S	NA	
	TUSE BOX	NA	NÁ	NA	

	Ground Level	N/A	N/A	N/A	
	<ul> <li>Discharge of main Pump</li> </ul>				
	➤ Head of Main pump	N/A	N/A N/A 220lpm	N/A N/A MR	
	➤ Number of main pumps	N/A			
	➤ Jockey Pump out put	220lpm			
	Jockey pump head	N/A	N/A	N/A	
	Standby Pump out put	N/A	N/A	N/A	
	> Standby Pump Head	N/A	N/A	N/A	
	> Auto Starting/ Manual stopping		N/A	N/A	
	> Pump House Access	N/A	N/A		
	Terrace level	900 lpm	900 lpm	MR	
	➤ Discharge of pump	40m	40 m	MR	
	➤ Head of the pump	Required	Provided	MR	
	> Power Supply		Provided	MR	
	> Auto Starting of pump	Required	Tiovided		
	Captive Water Storage for fire fighting.				
	Underground tank capacity	NA	NA	NA	
	> Draw-off connection	NA	NA	NA	
	> Fire service inlet	NA	NA	NA	
	Access to tank	NA	NA	NA	
	Overhead Tank capacity	10,000 ltrs	10000 ltr	MR	
		Required	Provided	MR	
	Exit Signage.	Required			
	Provision of Lifts.	N/A	N/A	N/A	
	Pressurization of Lift Shaft	N/A	N/A	N/A	
	Pressurization of Lift lobby	* *		N/A	
	Communication In lift Car	N/A	N/A		
	Fireman's Grounding Switch	N/A	N/A	N/A	
	Lift Signage	N/A	N/A	N/A	
,	Standby power supply	N/A	N/A	N/A	
	Refuge Area.			N/A	
	> Total Area	N/A	N/A		
	> Location	N/A	N/A	N/A	
			**>		

		N/A	N/A	N/A
Detector S	ystem Panel		N/A	N/A
Flow Swit		N/A	IN/A	27/4
PA System		N/A	N/A	N/A
Batter bac		N/A	N/A	N/A
Building	Floor Plans	N/A	N/A	N/A
	on Systems for	N/A	N/A	N/A
Special Fire Protecti Protection of special	Risks, if any:			

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. 2710 dated 29.12.2015.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in director of education Circular dated 01.03.2011, it is recommended to renewal of fire safety certificate issued vide this department letter of even no. 2171 dated 07.09.2011 ground + two floors.

24.3.17 Dy cro[wx) 29/5/1/2 260 West 1/2/17 Signature of the Inspecting Officer Name: Rajesh Kumar Designation: ADO/RN