

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

Fax No. 011-23412593, Ph. 011-23412225

No. F6/DFS/MS/EH/2017/SZ/ 504

Dated: 03/04/17

FIRE SAFETY CERTIFICATE

Certified that the **Buzz Restaurant** (A Unit of Gururaj Hospitality Services) located at **Shop No. 31-34, Ground Floor, MGF Metropolitan Mall, Saket, New Delhi-110017**, building comprised of 02 basements, ground + 02 upper floors with restaurant running at ground floor only was granted FSC by this department vide letter No. F.6/DFS/MS/EH/2013/SZ/1207 dated 14/11/2013. The premises was re-inspected by the officer concerned of this department on 03.03.2017 in the presence of Mr. Rakesh Kumar (Manager) of the restaurant and observed that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class-D "**Assembly Building**" (Restaurant) as above with effect from 03/4/17 for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 03/4/17 at New Delhi by

31/3
(Vipin Kental)
Chief Fire Officer

Copy to: -

1. The Joint C.P. (Lic.), First Floor, PS Defence Colony, New Delhi-110049
2. The DHO (South Zone), South MCD, Health Deptt, Green Park, New Delhi-110016
3. Authorised Signatory, M/s Buzz Restaurant (A Unit of Gururaj Hospitality Services), Shop No. 31-34, Ground Floor, MGF Metropolitan Mall, Saket, New Delhi-110017

Conditions for the validity of Fire Safety Certificate

1. All the fire safety and means of escape facilities shall be maintained in good working condition at all time. Any lapse rendering the fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
2. Building Sanctioning authority may verify any deviation with regard to construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null & void.
3. The staff shall be trained for operating fire fighting system and mock evacuation drill be conducted at regular interval and record be maintained.
4. The basement shall be used strictly as per the provisions of Building Bye Laws.
5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in.
6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

| INSPECTION REPORT | | | | |
|-------------------|---|--|----------------------------|----------------|
| 1 | Name & Address of the Building | Buzz Restaurant (A Unit of Gururaj Hospitality Services), Shop No. 31-34, Ground Floor, MGF Metropolitan Mall, Saket, New Delhi-110017 | | |
| 2 | Type of Occupancy | Assembly Building "Group-D" Restaurant | | |
| 3 | Building Comprised of | Two tier basement, ground + 7 upper floors. | | |
| 4 | Type of Case | Renewal | | |
| 5 | Details of Previous NOC | F.6/DFS/MS/EH/2013/SZ/1207 Dated 14/11/2013 | | |
| 6 | Fire Safety Directives Letter No | N/A | | |
| 7 | Date of Inspection | 03.03.2017 | | |
| 8 | Name of the Inspecting Officers | ADO R.N. Singh | | |
| 9 | Name & Designation of Officers from the building side | Mr. Rakesh Kumar (Manager) | | |
| 10 | Year of construction | Restt running at Ground Floor of the building | | |
| 11 | Applicant letter No. | Nil dated Nil, ODD No. 1165 dated 02.02.2017 | | |
| S. No | Minimum standards on Fire Prevention and Fire Safety U/R 33 | Old NOC 08/09/2010 Requirements | Provided at Site | Remarks MR/NMR |
| 1 | Access to Building. | | | |
| | • Road width | Required | 9 mtr | MR |
| | • Gate width | N/A | Provided by Mall | N/A |
| | • Width of internal road | N/A | Provided by Mall | N/A |
| 2 | Number, width, type & arrangement of exits | | | |
| | a. Number of Staircase | Provided & Maintained by MGF Metropolitan Mall | | |
| | • Upper floors | Located at GF | N/A | N/A |
| | • Basement floor | N/A | N/A | N/A |
| | b. Width of Staircase | Provided & Maintained by MGF Metropolitan Mall | | |
| | • Upper floors | Located at GF | N/A | N/A |
| | • Basement floor | N/A | N/A | N/A |
| | c. Protection of exits | Provided & Maintained by MGF Metropolitan Mall | | |
| | • Fire check door | N/A | N/A | N/A |
| | • Pressurization | N/A | N/A | N/A |
| | d. No. of continuous staircase to terrace | N/A | N/A | N/A |
| | e. Width of corridor | N/A | N/A | N/A |
| | f. Door size | Required | 1.34m & 1.06m (final exit) | MR |
| 3 | Compartmentation. | Provided & Maintained by MGF Metropolitan Mall | | |
| | • Fire check door. | N/A | As above | N/A |
| | • Sealing of electrical shafts. | N/A | As above | N/A |
| | • Fire rating of shaft door. | N/A | As above | N/A |
| | • Water curtain | N/A | As above | N/A |
| | • Fire dampers. | N/A | As above | N/A |
| 4. | Smoke Management system. | Provided & Maintained by MGF Metropolitan Mall | | |
| | • Basement | N/A | As above | N/A |
| | • Upper floors | N/A | As above | N/A |
| 5. | Fire Extinguishers. | | | |
| | • Total numbers | ISI marked | 06 No's | MR |
| | • Types | | ABC-04, Co2-02 | MR |
| | • ISI Marking | | Provided | MR |
| 6. | First Aid Hose Reels. | Provided & Maintained by MGF Metropolitan Mall | | |
| | • Total numbers on each floor. | Hose-reel | 02 provided in Restt. | MR |
| | • Length of hose-reel hose. | | 30 m | MR |
| | • Nozzle Diameter | | 05 mm | MR |

Renewal

Buzz Restt, Shop No. 31-34, GF, MGF Metropolitan Mall, Saket

| | | | | |
|-----|---|--|----------|-----|
| 7 | Automatic fire detection & alarming system | Provided & Maintained by MGF Metropolitan Mall | | |
| | • Type of detectors | N/A | As above | N/A |
| | • Location of Main Panel | N/A | As above | N/A |
| | • Location of Repeater Panel | N/A | As above | N/A |
| | • Alternate source of power | N/A | As above | N/A |
| | • Hooter's location | N/A | As above | N/A |
| 8. | MOEFA | Required | Provided | MR |
| 9. | Public Address System | N/A | N/A | N/A |
| 10. | Automatic Sprinkler System | Provided & Maintained by MGF Metropolitan Mall | | |
| | • Basement | N/A | As above | N/A |
| | • Upper floors | N/A | As above | N/A |
| | • Sprinkler above false ceiling | N/A | N/A | N/A |
| 11. | Internal Hydrants. | Provided & Maintained by MGF Metropolitan Mall | | |
| | • Size of Riser/Down-comer | N/A | As above | N/A |
| | • Number of Hydrant per floor | N/A | As above | N/A |
| | • Hose box. | N/A | As above | N/A |
| 12. | Yard Hydrants. | Provided & Maintained by MGF Metropolitan Mall | | |
| | • Total number of hydrants. | N/A | As above | N/A |
| | • 2. Hose box. | N/A | As above | N/A |
| 13. | Pumping arrangements. | | | |
| | • Ground Level | Provided & Maintained by MGF Metropolitan Mall | | |
| | ➤ Discharge of main pump. | N/A | As above | N/A |
| | ➤ Head of main pump. | N/A | As above | N/A |
| | ➤ Number of main pumps. | N/A | As above | N/A |
| | ➤ Jockey Pump output. | N/A | As above | N/A |
| | ➤ Jockey Pump head. | N/A | As above | N/A |
| | ➤ Standby Pump output. | N/A | As above | N/A |
| | ➤ Standby Pump head. | N/A | As above | N/A |
| | ➤ Auto Starting / Manual Stopping. | N/A | As above | N/A |
| | ➤ Access to pump house | N/A | As above | N/A |
| | • Terrace Level | Provided & Maintained by MGF Metropolitan Mall | | |
| | ➤ Discharge of pump. | 450 LPM | As above | MR |
| | ➤ Head of pump. | 40 m | As above | MR |
| | ➤ Power supply. | Required | As above | MR |
| | ➤ Auto starting of pump. | Required | As above | MR |
| 14. | Captive water storage for Fire Fighting. | Provided & Maintained by MGF Metropolitan Mall | | |
| | • Underground tank capacity. | N/A | As above | N/A |
| | ➤ Draw-off connection. | N/A | As above | N/A |
| | ➤ Fire Service Inlet. | N/A | As above | N/A |
| | ➤ Access to tank. | N/A | As above | N/A |
| | • Overhead tank capacity. | 5,000 Ltr | As above | MR |
| 15. | Exit Signage. | Required | Provided | MR |
| 16. | Provision of Lifts. | Provided & Maintained by MGF Metropolitan Mall | | |
| | • Pressurization of lift shaft. | N/A | As above | N/A |
| | • Pressurization of lift lobby. | N/A | As above | N/A |
| | • Communication in lift car. | N/A | As above | N/A |
| | • Fireman's switch. | N/A | As above | N/A |
| | • Lift signage. | N/A | As above | N/A |
| 17 | Standby Power Supply | Required | Provided | MR |
| 18. | Refuge Area | | | |
| | • Total area | N/A | N/A | N/A |
| | • Location | N/A | N/A | N/A |

Renewal

Buzz Restt, Shop No. 31-34, GF, MGF Metropolitan Mall, Saket

| 19. | Fire Control Room. | Provided & Maintained by MGF Metropolitan Mall | | |
|--|---|---|----------|----------|
| | | <ul style="list-style-type: none"> • Detector System Panel. • Flow Switch Panel. • PA system Panel. • Battery backup • Building floor plan | N/A | As above |
| | | N/A | As above | N/A |
| | | N/A | As above | N/A |
| | | N/A | As above | N/A |
| | | N/A | As above | N/A |
| 20. | Special Fire Protection System for the Protection of special Risk, if any : | | | N/A |
| <p>Previously the restaurant was granted FSC in the name of Buzz Restaurant (A Unit of RG Entertainment Pvt. Ltd.) by this department vide letter dated 14/11/2013 and NOC for change in name of Buzz Restaurant (A Unit of RG Entertainment Pvt. Ltd) to Buzz Restaurant (A Unit of Gururaj Hospitality Services) was granted by this department vide letter No. F.6/DFS/MS/EH/2016/1742 dated 19/07/2016.</p> <p>The Fire protection systems provided in the building were randomly checked and found functional at the time of inspection.</p> <p>Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F6/DFS/MS/EH2013/SZ/1207 Dated 14/11/2013, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.</p> <p>Accordingly, DFA is put up for approval and signature please.</p> | | | | |
| <p><i>[Signature]</i> 10/3/17</p> <p>Signature of the Inspecting Officer Name : R.N. Singh Designation: ADO</p> | | | | |

Renewal

Buzz Restt, Shop No. 31-34, GF, MGF Metropolitan Mall, Saket

Div. Officer (SD)

[Signature]
14/3/17

[Signature]

[Signature]
15/3

Chb (S2) PA but up. file of metropolitan mall saket.

[Signature]

[Signature]
16/3

[Signature]
24/3

[Signature]
17

