

FIRE SAFETY CERTIFICATE

Certified that M/s **Chilis Grill & Bar Restaurant** (A Unit of Paramount Restaurants Pvt. Ltd) at **Shop No 161, Ground Floor, DLF Place, Saket, New Delhi**, running at ground floor of the building comprised of three tier basement, ground plus seven upper floors was granted FSC by this department vide letter No. F.6/DFS/MS/EH/2014/SZ/280 dated 28/02/2014. The premises was re-inspected by the officer concerned of this department on 15.03.2017 in the presence of Mr. Rakesh (Manager) of the restaurant and observed that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class-D "**Assembly Building**" (Restaurant) as above with effect from 31/3/17 for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 31/3/17 at New Delhi by


Vipin Kental
Chief Fire Officer

Copy to:-

1. The Manager, M/s Chilis Grill & Bar Restaurant at Shop No. 161, Ground Floor, DLF Place, Saket, New Delhi-100070
2. The joint C.P. (Lic.), First Floor, PS Defence Colony, New Delhi-110049
3. The DHO (South Zone), South MCD, Health Deptt. Green Park, New Delhi-16

Conditions for the validity of Fire Safety Certificate

1. All the fire safety and means of escape facilities shall be maintained in good working condition at all time. Any lapse rendering the fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
2. Building Sanctioning authority may verify any deviation with regard to construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null & void.
3. The staff shall be trained for operating fire fighting system and mock evacuation drill be conducted at regular interval and record be maintained.
4. The basement shall be used strictly as per the provisions of Building Bye Laws.
5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in.
6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT


| S. No | Minimum standards on Fire Prevention and Fire Safety U/R 33 | Old NOC 28/02/2014 Requirements | Provided at Site | Remarks MR/NMR |
|-------|---|--|------------------|----------------|
| 1 | Access to Building. | F.6/DFS/MS/Mall/2015/SZ/1954 Dated 30/10/2015 | | |
| | • Road width | Required | As above | MR |
| | • Gate width | N/A | N/A | N/A |
| | • Width of internal road | N/A | N/A | N/A |
| 2 | Number, width, type & arrangement of exits. | Provided & Maintained by DLF Place Mall | | |
| | a. Number of Staircase | | | |
| | • Upper floors | N/A | As above | N/A |
| | • Basement floor | N/A | As above | N/A |
| | b. Width of Staircase | Provided & Maintained by DLF Place Mall | | |
| | • Upper floors | N/A | As above | N/A |
| | • Basement floor | N/A | As above | N/A |
| | c. Protection of exits | Provided & Maintained by DLF Place Mall | | |
| | • Fire check door | N/A | As above | MR |
| | • Pressurization | N/A | As above | N/A |
| | d. No. of continuous staircase to terrace | Required | As above | N/A |
| | e. Width of corridor | N/A | N/A | N/A |
| | f. Door size | Required | 2.0m & 1.31m | MR |
| 3 | Compartmentation. | Provided & Maintained by DLF Place Mall | | |
| | • Fire check door. | N/A | As above | N/A |
| | • Sealing of electrical shafts. | N/A | As above | N/A |
| | • Fire rating of shaft door. | N/A | N/A | N/A |
| | • Water curtain | N/A | N/A | N/A |
| | • Fire dampers. | N/A | N/A | N/A |
| 4. | Smoke Management system. | Provided & Maintained by DLF Place Mall | | |
| | • Basement | N/A | As above | N/A |
| | • Upper floors | Required | As above | MR |
| 5. | Fire Extinguishers. | | | |
| | • Total numbers | ISI marked | 07 No's | MR |
| | • Types | | ABC-05, .Co2-02 | MR |
| | • ISI Marking | | Provided | MR |
| 6. | First Aid Hose Reels. | Provided & Maintained by DLF Place Mall | | |
| | • Total numbers on each floor. | Hose-reel | One in Restt. | MR |
| | • Length of hose-reel hose. | | 30 m | MR |
| | • Nozzle Diameter | | 5 mm | MR |

Renewal

M/s Chilis Grill & Bar Restaurant, DLF Place, Saket

| | | | | |
|-----|--|--|-------------------|-----|
| 7 | Automatic fire detection & alarming system. | Provided & Maintained by DLF Place Mall | | |
| | • Type of detectors | Required | Smoke & Heat | MR |
| | • Location of Main Panel | Required | As above | MR |
| | • Location of Repeater Panel | N/A | N/A | N/A |
| | • Alternate source of power | Required | As above | MR |
| | • Hooter's location | Required | As above | MR |
| 8. | MOEFA | Required | As above | MR |
| 9. | Public Address System | Required | As above | MR |
| 10. | Automatic Sprinkler System | Provided & Maintained by DLF Place Mall | | |
| | • Basement | Required | As above | MR |
| | • Upper floors | Required | As above | MR |
| | • Sprinkler above false ceiling | N/A | N/A | N/A |
| 11. | Internal Hydrants. | Provided & Maintained by DLF Place Mall | | |
| | • Size of Riser/Down-comer | Required | As above | MR |
| | • Number of Hydrant per floor | Required | As above | MR |
| | • Hose box. | Required | As above | MR |
| 12. | Yard Hydrants. | Provided & Maintained by DLF Place Mall | | |
| | • Total number of hydrants. | N/A | As above | N/A |
| | • Hose box. | N/A | As above | N/A |
| 13. | Pumping arrangements. | Provided & Maintained by DLF Place Mall | | |
| | • Ground Level | Provided & Maintained by DLF Place Mall | | |
| | ➤ Discharge of main pump. | N/A | As above | N/A |
| | ➤ Head of main pump. | N/A | As above | N/A |
| | ➤ Number of main pumps. | N/A | As above | N/A |
| | ➤ Jockey Pump output. | N/A | As above | N/A |
| | ➤ Jockey Pump head. | N/A | As above | N/A |
| | ➤ Standby Pump output. | N/A | As above | N/A |
| | ➤ Standby Pump head. | N/A | As above | N/A |
| | ➤ Auto Starting / Manual Stopping. | N/A | As above | N/A |
| | ➤ Access to pump house | N/A | As above | N/A |
| | • Terrace Level | Provided & Maintained by DLF Place Mall | | |
| | ➤ Discharge of pump. | 450 LPM | As above | MR |
| | ➤ Head of pump. | 40 m | As above | MR |
| | ➤ Power supply. | Required | As above | MR |
| | ➤ Auto starting of pump. | Required | As above | MR |
| 14. | Captive water storage for Fire Fighting. | Provided & Maintained by DLF Place Mall | | |
| | • Underground tank capacity. | N/A | As above | N/A |
| | ➤ Draw-off connection. | N/A | As above | N/A |
| | ➤ Fire Service Inlet. | N/A | As above | N/A |
| | ➤ Access to tank. | N/A | As above | N/A |
| | • Overhead tank capacity. | 5,000 Ltr | As above | MR |
| 15. | Exit Signage. | Required | Provided | MR |
| 16. | Provision of Lifts. | Provided & Maintained by DLF Place Mall | | |
| | • Pressurization of lift shaft. | N/A | N/A | N/A |
| | • Pressurization of lift lobby. | N/A | N/A | N/A |
| | • Communication in lift car. | N/A | N/A | N/A |
| | • Fireman's switch. | N/A | N/A | N/A |
| | • Lift signage. | N/A | N/A | N/A |
| 17 | Standby Power Supply | Required | Provided (DG Set) | MR |
| 18. | Refuge Area | Provided & Maintained by DLF Place Mall | | |
| | • Total area | N/A | N/A | N/A |
| | • Location | N/A | N/A | N/A |


N/6

| 19. | Fire Control Room. | Provided & Maintained by DLF Place Mall | | |
|---|---|---|----------|-----|
| | <ul style="list-style-type: none"> • Detector System Panel. • Flow Switch Panel. • PA system Panel. • Battery backup • Building floor plan | N/A | As above | N/A |
| | | N/A | As above | N/A |
| | | N/A | As above | N/A |
| | | N/A | As above | N/A |
| | | N/A | As above | N/A |
| | | N/A | As above | N/A |
| 20. | Special Fire Protection System for the Protection of special Risk, if any : | N/A | As above | N/A |
| <p>The Fire protection systems provided in the building were test checked and found functional at the time of inspection.</p> <p>Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/EH/2014/SZ/282 Dated 28/02/2014, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.</p> <p>Accordingly, DFA is put up for approval and signature please.</p> <div style="text-align: right; margin-top: 20px;">  Signature of the Inspecting Officer Name : R.N. Singh Designation: ADO </div> | | | | |

Renewal

M/s Chilis Grill & Bar Restaurant, DLF Place, Saket

Div. Officer (SD)


17/3/17