GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/DFS/ans/ school/2017/ ND2/483

Dated: 31/3/17

FIRE SAFETY CERTIFICATE

Certified that the EDMC Primary School at Ghonda, Delhi 110053 comprised of ground plus one upper floor owned/occupied by EDMC Primary School was issued FSC vide letter no. F6/DFS/MS/School/2013/NDZ/1316 dated 13/12/13 The school building was reinspected by the officer concerned of this department on 10/03/17 in the presence of Mr. Anil Bansal, Principal of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with Circular Letter no. F16/Estate/CC/FireSafety/2011/3298to3398 dated-01/03/11 issued by Director of Education and found that the school building is fit for occupancy class "B" 'Educational Building' for ground floor with effect from .31 3. 17.... for a period of three years, subject to conditions, printed overleaf.

Issued on 31.3 1.7 at New Delhi by

(Vipin Kental) Chief Fire Officer

To.

The Principal, EDMC Primary School, Ghonda (2nd Shift) Delhi 110053,

Copy:-

- The Principal, EDMC Primary School, Ghonda (1st Shift) Delhi 110053.
- The Director of Education, EDMC, Udyog Sadan, Plot No.419, FIE, Patparganj Industrial Area, Delhi-110092

CONDITIONS

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Deihi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

1. Name & address of the building : EDMC Primary School, Ghonda, Delhi-110053

2. Building is comprised of Ground plus first floor only

3. Type of Occupancy : Educational

4. Type of Case : Renewal

5. Details of Previous NOC letter : F6/DFS/MS/School/2013//NDZ/1316

Dated 13/02/13

6. Fire Safety directive letter no : F16/Estate/CC/FireSafety/2011/3298to3398

dated-01/03/11 issued by Director of Education

7. Date of Inspection : 10/03/17

8. Name of the Inspecting officers : ADO V. B. Yadav

9. Name and designation of Officer

from the building side : Mr. Anil Bansal (Principal)

10. Year of Construction : 1994

11. Applicant's letter No : Letter No.-Nil, Dated-14/02/17

| Sr. No. | Minimum Standards on Fire Prevention and Fire Safety U/R33 | Circular Requirement | Provided at Site | Remarks MR/NMR | | | |
|-------------------------------------|---|-------------------------|---|--|--|--|--|
| 01 | Access to Building | | | | | | |
| digentrality abanque (1 initial), p | Road width O6 mtr. 04 mtr. MR/old | | | | | | |
| | Gâte width | OO ma. | V4 1110 . | accepted | | | |
| | Width of internal road | NA | N/A | N/A | | | |
| | VVidti of international | N/A | N/A | N/A | | | |
| 02 | Number, Width, Type and Arrangement of Exits | | | | | | |
| aliyohquanda dali lida shiyota | a. Number of Staircases | | n van der | to make the self-part of the property of the control of the contro | | | |
| | Upper floor | 01 nos. | 01 nos. | MR | | | |
| | Basement | N/A | N/A | N/A | | | |
| | b. Width of Staircases | | | | | | |
| | Upper floor | 1.50 mtr. | 1.50 mtr. | MR | | | |
| | Basement | N/A | NA | N/A | | | |
| | c. Protection of Exits | | | | | | |
| | Fire check door | N/A | N/A | N/A | | | |
| | Pressurization | N/A | N/A | N/A | | | |
| | d. No. of Continuous Staircases to Terrace | N/A | N/A | N/A | | | |
| | e. Width of Corridor | 1.50 mtr. | 1.50 mtr. | MR | | | |
| | f. Door Size | O1 mtr. | 01 mtr. | MR | | | |
| 03 | Compartmentation. | | | | | | |
| | Fire check door | N/A | N/A , | N/A | | | |
| | Sealing of electrical shafts | N/A | N/A | N/A | | | |
| | Fire rating of shaft door | N/A | N/A | N/A | | | |
| | Water curtain | N/A | N/A | N/A | | | |
| | Fire dampers | N/A | N/A | N/A | | | |
|)4 | Smoke Management System. | | | | | | |
| and and the second second | Basement | N/A | N/A | N/A | | | |
| | Upper floor | N/A | N/A | N/A | | | |
| 05. | Fire Extinguishers | | | | | | |
| nakkinigijah,ni menjudian d | Total numbers | 04 nos. | 04 nos. | MR | | | |
| | • types | ABC /CO ₂ | ABC /CO ₂ | MR | | | |
| | IS marking | ISI marked | ISI marked | MR | | | |

| - | Total numbers on each floor | N/A | N/A | N/A | | | |
|--|---|--|--|--|--|--|--|
| (hadjaldissipa | Length of hose reel hose | N/A | N/A | N/A | | | |
| Paragraphic linear paragraphic | Nozzle diameter | N/A | N/A | N/A | | | |
| or representation was | Automatic Fire Detection and Alarming System | | ab diges conglition, generals nelsecurers into the service requirem is assert to be hyperbolished to have a touche or fine a | ant a ware de et de la maio et en la capación de la | | | |
| and a second color | Type of detectors | N/A | N/A | . N/A | | | |
| Apple de la company | Location of main panel | WA | N/A | N/A | | | |
| Special same | Location of repeater panel | N/A | N/A | N/A | | | |
| September 100 September 1 | Alternate source of power | N/A | N/A | N/A | | | |
| The state of the s | Hooter's location | N/A | N/A | N/A | | | |
| - Control of the Cont | MOEFA | N/A | N/A | N/A | | | |
| Company of the Company | Public Address System. | N/A | N/A | N/A | | | |
| - | Automatic Sprinkler System. | | | | | | |
| Wall Control | Basement | N/A | N/A | N/A | | | |
| over tal City and | upper floor | N/A | NA | N/A | | | |
| employed to the second | sprinkler above false ceiling | N/A | N/A | N/A | | | |
| - | Internal Hydrants | | | | | | |
| - | size of riser/down-comer | N/A | N/A | N/A | | | |
| colorin sales from | Number of hydrants per floor | N/A | N/A | N/A | | | |
| - Marie Contract | Hose box | N/A | N/A | N/A | | | |
| September 1 | Yard Hydrants. | | | | | | |
| A CONTRACTOR | Total number of hydrants | NA | N/A | N/A | | | |
| and the same | Hose box | N/A | N/A | N/A | | | |
| e il rapportuni propini | Pumping Arrangements. | | | | | | |
| Service Services | ➢ Ground Level | an kigan i Bangu atkan in kadi angan makanan sasangi bilaji in ani ngani hasibi ya kan atkan makanan | | | | | |
| - Contraction of | Discharge of main pump | N/A | N/A | N/A | | | |
| Seasons of | Head of Main pump | N/A | N/A | · N/A | | | |
| Cold Security | Number of main pumps | N/A | N/A | N/A | | | |
| Open Security | Jockey pump out put | N/A | N/A | N/A | | | |
| Comment (b) | Jockey pump head | N/A | N/A | N/A | | | |
| Approximate | Standby pump out put | N/A | N/A N/A | N/A N/A | | | |
| Seepage 100 | Standby pump head | N/A N/A | N/A N/A | N/A | | | |
| Open Company | Auto starting /manual stopping | N/A | N/A | N/A | | | |
| - | Pump house access Terrace Level | Parts. | | | | | |
| Annual Company of the Parket Company | | N/A | N/A | N/A | | | |
| o'm cades sun's | Discharge of pump | N/A | N/A | N/A | | | |
| maging to repair | Head of the pumpPower supply | N/A | N/A | N/A | | | |
| Self-Listensey, | Power supply Auto Starting of pump | N/A | N/A | N/A | | | |
| 1 | Captive Water Storage for Fire Fighting. | | 1 | the same of the sa | | | |
| | | N/A | N/A | N/A | | | |
| Monage and | Underground tank capacity Draw-off connection | N/A | N/A | N/A | | | |
| manual de saladades | Draw-off connection Fire service inlet | N/A | N/A | N/A | | | |
| Carriage/propriets | Access to tank | N/A | N/A | N/A | | | |
| , deli , di pix casa e | Overhead tank capacity | N/A | N/A | N/A | | | |
| - Anna | Exit Signage. | N/A | N/A | N/A | | | |

| 16 | Provision of Lifts. | | | | | | |
|--|---|-------|-----|-------|--|--|--|
| | Pressurization of lift shaft | N/A | N/A | N/A | | | |
| | Pressurization of lift lobby | N/A | N/A | N/A | | | |
| | Communication in lift car | N/A | N/A | N/A | | | |
| | Firemen's grounding switch | N/A | N/A | N/A | | | |
| | Lift signage | N/A | N/A | N/A | | | |
| 17 | Standby Power Supply | N/A | N/A | N/A | | | |
| 18 | Refuge Area. | | | | | | |
| AND THE PARTY OF T | Total area | N/A | N/A | N/A | | | |
| | Location | . N/A | N/A | N/A | | | |
| 19 | Fire Control Room | | | | | | |
| APPLICATION OF THE PARTY OF THE | Detector system panel | N/A | N/A | N/A | | | |
| | Flow switch panel | N/A | N/A | - N/A | | | |
| | PA system panel | N/A | N/A | N/A | | | |
| | Battery backup | N/A | N/A | N/A | | | |
| | Building floor plans | N/A | N/A | N/A | | | |
| 20 | Special Fire Protection Systems for Protection of Special Risks, if any: | N/A | N/A | N/A | | | |

The fire protection systems provided in the building were tested/checked at the time of inspection.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the circular no- F16/Estate/CC/FireSafety/2011/3298to3398 dt-01/03/11 issued by Director of Education, it is recommended to grant Fire Safety Certificate.

Signature of the Inspecting Officer

Name

- V. B. Yadav

Designation - A.D.O (TP)