

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

Fax No. 011-23412593, Ph. 011-23412225

No. F6/DFS/MS/EH/2017/SZ/ 478

Dated: ... 30/3/17

FIRE SAFETY CERTIFICATE

Certified that M/s **Platinum Restaurant** located at **137/9, Aruna Asaf Ali Marg, Kishangarh, New Delhi-110070**, comprised of Ground floor only with seating capacity of 98 persons was granted FSC by this department vide letter No. F.6/DFS/MS/EH/2013/SZ/1027 dated 04/10/2013. The premises was re-inspected by the officer concerned of this department on 15/03/2017 in the presence of Mr. Raj Kumar of the restaurant and observed that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class-D "**Assembly Building**" (Restaurant) as above with effect from 30/3/17 for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 30/3/17 at New Delhi by

30/3
(Vipin Kental)
Chief Fire Officer

Copy to: -

1. The Joint C.P. (Lic.), First Floor, PS Defence Colony, New Delhi-110049
2. The DHO (Central Zone), South MCD, Health Deptt, Lajpat Nagar, New Delhi-24
3. M/S Platinum Restaurant (A Unit of Plutos exim Pvt.Ltd.)
Aruna Asaf Ali Marg Kishangarh New Delhi-110070.

Conditions for the validity of Fire Safety Certificate

1. All the fire safety and means of escape facilities shall be maintained in good working condition at all time. Any lapse rendering the fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
2. Building Sanctioning authority may verify any deviation with regard to construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null & void.
3. The staff shall be trained for operating fire fighting system and mock evacuation drill be conducted at regular interval and record be maintained.
4. The basement shall be used strictly as per the provisions of Building Bye Laws.
5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in.
6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

1	Name & Address of the Building	M/s Platinum Restaurent,137/9, Aruna Asaf Ali Marg,Kishangarh, New Delhi-110070.		
2	Type of Occupancy	Group-D Assembly Building. RestaurantGround floor only		
3	Type of Case	Renewal		
4	Details of Previous NOC	No.F6/MS/DFS/EH/2013/SZ/1027 Dated 04/10/2013		
5	Fire Safety Directives Letter No	Nil		
6	Date of Inspection	15/03/2017		
7	Name of the Inspecting Officers	ADO R.N. Singh		
8	Name & Designation of Officers from the building side	Mr. Raj Kumar		
9	Year of construction	2002		
10	Applicant letter No.	Nil Dated 22/02/2017		
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	AS Per Old NOC 2013	Provided at Site	Remarks MR/NMR
1	Access to Building.			
	• Road width	12 mtr.	Provided	MR
	• Gate width	Required	Provided	M/R
	• Width of internal road	N/A	N/A	N/A
2	Number, width, type and arrangements of exits.			
	a. Number of Staircase			
	• Upper floors	N/A	N/A	N/A
	• Basement floor	N/A	N/A	N/A
	b. Width of Staircase			
	• Upper floors	N/A	N/A	N/A
	• Basement floor	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	Required	Provided	MR
	• Pressurization	N/A	N/A	N/A
	d. No. of continuous staircase to terrace	N/A	N/A	N/A
	e. Width of corridor	N/A	N/A	N/A
	f. Door size	2.0 m	Provided 03 Nos. 2mtr. 1.80 mtr. &0.75 mtr	MR
3	Compartmentation.			
	• Fire check door.	Required	Provided	M/R
	• Sealing of electrical shafts.	N/A	N/A	N/A
	• Fire rating of shaft door.	N/A	N/A	N/A
	• Water curtain	N/A	N/A	N/A
	• Fire dampers.	N/A	N/A	N/A
4.	Smoke Management system.			
	• Basement	30 a/c per hour	N/A	N/A
	• Upper floors	12 a/c per hour	Exhaust fan	MR
5.	Fire Extinguishers.			
	• Total numbers		06 Nos.	MR
	• Types	ISI marked	4 ABC & 2 Co2	MR
	• ISI Marking		Yes	MR
6.	First Aid Hose Reels.			
	• Total numbers on each floor.	01 Nos.	Provided	MR
	• Length of hose-reel hose.	30 mtr	Yes	MR
	• Nozzle Diameter	05 mtr	Yes	MR

7	Automatic Fire Detection and Alarming system.			
	• Type of detectors	N/A	N/A	N/A
	• Location of Main Panel	N/A	N/A	N/A
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	N/A	N/A	N/A
	• Hooter's location	N/A	N/A	N/A
8.	MOEFA	Required	Provided	M/R
9.	Public Address System	Required	Provided	M/R
10.	Automatic Sprinkler System			
	• Basement	N/A	N/A	N/A
	• Upper floors	Not Required	Provided	MR
	• Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants.			
	• Size of Riser/Down-comer	N/A	N/A	N/A
	• Number of Hydrant per floor	N/A	N/A	N/A
	• Hose box.	N/A	N/A	N/A
12.	Yard Hydrants.			
	• Total number of hydrants.	Not Required	Provided	M/R
	• 2. Hose box.	Not Required	Provided	M/R
13.	Pumping arrangements.			
	• Ground Level			
	➤ Discharge of main pump.	N/A	N/A	N/A
	➤ Head of main pump.	N/A	N/A	N/A
	➤ Number of main pumps.	N/A	N/A	N/A
	➤ Jockey Pump output.	N/A	N/A	N/A
	➤ Jockey Pump head.	N/A	N/A	N/A
	➤ Standby Pump output.	N/A	N/A	N/A
	➤ Standby Pump head.	N/A	N/A	N/A
	➤ Auto Starting / Manual Stopping.	N/A	N/A	N/A
	➤ Access to pump house	N/A	N/A	N/A
	• Terrace Level			
	➤ Discharge of pump.	450 LPM	840 & 600 LPM	MR
	➤ Head of pump.	Required	26 & 23 mtrs.	MR
	➤ Power supply.	Required	Provided	MR
	➤ Auto starting of pump.	Required	Provided	MR
14.	Captive water storage for Fire Fighting.			
	• Underground tank capacity.	N/A	N/A	N/A
	➤ Draw-off connection.	N/A	N/A	N/A
	➤ Fire Service Inlet.	N/A	N/A	N/A
	➤ Access to tank.	N/A	N/A	N/A
	• Overhead tank capacity.	5000 Ltr.	5000 Ltr.	M/R
15.	Exit Signage.	Required	Provided	M/R
16.	Provision of Lifts.			
	• Pressurization of lift shaft.	N/A	N/A	N/A
	• Pressurization of lift lobby.	N/A	N/A	N/A
	• Communication in lift car.	N/A	N/A	N/A
	• Fireman's switch.	N/A	N/A	N/A
	• Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Yes	Provided	MR
18.	Refuge Area			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A


N/ 7

19.	Fire Control Room.			
	• Detector System Panel.	N/A	N/A	N/A
	• Flow Switch Panel.	N/A	N/A	N/A
	• PA system Panel.	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for the Protection of special Risk, if any :	N/A	N/A	N/A


The Fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rules 35 of the Delhi Fire Service Rules 2010/-----

Accordingly, DFA is put up for approval and signature please.


Signature of the Inspecting Officer
Name : R.N. Singh
Designation: ADO

Div. Officer (SD)


20/3/17
