

No. F6/DFS/MS/EH/2017/SZ/ 505

Dated: 3/4/17

FIRE SAFETY CERTIFICATE

Certified that M/s **Chilis Restaurant** (A Unit of Paramount Restaurants Pvt. Ltd) located at **Shop No R-308, 3rd floor, Ambience Mall, Vasant Kunj, New Delhi**, running at third floor of the building comprised of three tier basement, ground plus three upper floors was granted FSC by this department vide letter No. F.6/DFS/MS/EH/2014/SZ/281 dated 28/02/2014. The premises was re-inspected by the officer concerned of this department on 15.03.2017 in the presence of Mr. Devashish (Manager) of the restaurant and observed that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class-D "**Assembly Building**" (Restaurant) as above with effect from 3/4/17 for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 3/4/17 at New Delhi by


Vipin Kental
Chief Fire Officer

Copy to: -

1. The Manager, M/s Chilis Restaurant at Shop No. R-308, 3rd floor, Ambience Mall, Vasant Kunj, New Delhi-100070
2. The joint C.P. (Lic.), First Floor, PS Defence Colony, New Delhi-110049
3. The DHO (South Zone), South MCD, Health Deptt. Green Park, New Delhi-16

Conditions for the validity of Fire Safety Certificate

1. All the fire safety and means of escape facilities shall be maintained in good working condition at all time. Any lapse rendering the fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
2. Building Sanctioning authority may verify any deviation with regard to construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null & void.
3. The staff shall be trained for operating fire fighting system and mock evacuation drill be conducted at regular interval and record be maintained.
4. The basement shall be used strictly as per the provisions of Building Bye Laws.
5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in.
6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

| | | | | |
|-------|---|---|-----------------------|----------------|
| 1 | Name & Address of the Building | M/s Chili's Restaurant at Shop No. R-308 3 rd floor, Ambience Mall, Vasant Kunj, New Delhi-110070 (A Unit of Paramount Restaurants Pvt. Ltd) | | |
| 2 | Type of Occupancy | Assembly Building "Group-D" Restaurant | | |
| 3 | Building Comprised of | Three tier Basement, Ground + 03 upper floors | | |
| 4 | Type of Case | Renewal | | |
| 5 | Details of Previous NOC | F.6/DFS/MS/EH/2014/SZ/281 Dated 28/02/2014 | | |
| 6 | Fire Safety Directives Letter No | Nil | | |
| 7 | Date of Inspection | 15.03.2017 | | |
| 8 | Name of the Inspecting Officers | ADO R.N. Singh | | |
| 9 | Name & Designation of Officers from the building side | Mr. Devashish (Manager) | | |
| 10 | Year of construction | Restt running at 3 rd floor in Ambience Mall building. | | |
| 11 | Applicant letter No. | Nil Dt. Nil ODD No-2112 Dt. 27/02/2016 | | |
| S. No | Minimum standards on Fire Prevention and Fire Safety U/R 33 | Old NOC Dt. 15/11/2010 requirements | Provided at Site | Remarks MR/NMR |
| 1 | Access to Building. | F.6/DFS/MS/Mall/SZ/2017/33 dated 09/01/2017 | | |
| | • Road width | Required | As above | MR |
| | • Gate width | N/A | N/A | N/A |
| | • Width of internal road | N/A | N/A | N/A |
| 2 | Number, width, type & arrangement of exits. | Provided & Maintained by Ambience Mall | | |
| | a. Number of Staircase | | | |
| | • Upper floors | 2 No's | 2 No's Near Restt | MR |
| | • Basement floor | N/A | N/A | N/A |
| | b. Width of Staircase | Provided & Maintained by Ambience Mall | | |
| | • Upper floors | Required | As above | MR |
| | • Basement floor | N/A | N/A | N/A |
| | c. Protection of exits | Provided & Maintained by Ambience Mall | | |
| | • Fire check door | Required | As above | MR |
| | • Pressurization | N/A | N/A | N/A |
| | d. No. of continuous staircase to terrace | Required | As above | MR |
| | e. Width of corridor | N/A | N/A | N/A |
| | f. Door size | Required | 1.50m & 1.17m | MR |
| 3 | Compartmentation. | Provided & Maintained by Ambience Mall | | |
| | • Fire check door. | N/A | As above | N/A |
| | • Sealing of electrical shafts. | N/A | As above | N/A |
| | • Fire rating of shaft door. | N/A | N/A | N/A |
| | • Water curtain | N/A | N/A | N/A |
| | • Fire dampers. | N/A | N/A | N/A |
| 4. | Smoke Management system. | Provided & Maintained by Ambience Mall | | |
| | • Basement | N/A | N/A | N/A |
| | • Upper floors | Required | Exhaust fans provided | MR |
| 5. | Fire Extinguishers. | | | |
| | • Total numbers | 06 No's | 06 No's | MR |
| | • Types | ISI marked | ABC-04, W.Co2-02 | MR |
| | • ISI Marking | | Provided | MR |
| 6. | First Aid Hose Reels. | Provided & Maintained by Ambience Mall | | |
| | • Total numbers on each floor. | Hose-reel | One in Restt. | MR |
| | • Length of hose-reel hose. | | 30m | MR |
| | • Nozzle Diameter | | 5mm | MR |

Renewal

M/s Chili's Restaurant, Ambience Mall, Vasant Kunj

| | | | | |
|-----|--|---|--------------------|-----|
| 7 | Automatic fire detection & alarming system. | Provided & Maintained by Ambience Mall | | |
| | <ul style="list-style-type: none"> Type of detectors | Required | Smoke & Heat | MR |
| | <ul style="list-style-type: none"> Location of Main Panel | Required | As above | MR |
| | <ul style="list-style-type: none"> Location of Repeater Panel | N/A | N/A | N/A |
| | <ul style="list-style-type: none"> Alternate source of power | Required | As above | MR |
| | <ul style="list-style-type: none"> Hooter's location | Required | As above | MR |
| 8. | MOEFA | Required | As above | MR |
| 9. | Public Address System | Required | As above | MR |
| 10. | Automatic Sprinkler System | Provided & Maintained by Ambience Mall | | |
| | <ul style="list-style-type: none"> Basement | Required | As above | MR |
| | <ul style="list-style-type: none"> Upper floors | Required | Provided in Restt. | MR |
| | <ul style="list-style-type: none"> Sprinkler above false ceiling | N/A | N/A | N/A |
| 11. | Internal Hydrants. | Provided & Maintained by Ambience Mall | | |
| | <ul style="list-style-type: none"> Size of Riser/Down-comer | Required | As above | MR |
| | <ul style="list-style-type: none"> Number of Hydrant per floor | Required | As above | MR |
| | <ul style="list-style-type: none"> Hose box. | Required | As above | MR |
| 12. | Yard Hydrants. | Provided & Maintained by Ambience Mall | | |
| | <ul style="list-style-type: none"> Total number of hydrants. | N/A | As above | N/A |
| | <ul style="list-style-type: none"> Hose box. | N/A | As above | N/A |
| 13. | Pumping arrangements. | Provided & Maintained by Ambience Mall | | |
| | <ul style="list-style-type: none"> Ground Level | Provided & Maintained by Ambience Mall | | |
| | <ul style="list-style-type: none"> ➤ Discharge of main pump. | N/A | As above | N/A |
| | <ul style="list-style-type: none"> ➤ Head of main pump. | N/A | As above | N/A |
| | <ul style="list-style-type: none"> ➤ Number of main pumps. | N/A | As above | N/A |
| | <ul style="list-style-type: none"> ➤ Jockey Pump output. | N/A | As above | N/A |
| | <ul style="list-style-type: none"> ➤ Jockey Pump head. | N/A | As above | N/A |
| | <ul style="list-style-type: none"> ➤ Standby Pump output. | N/A | As above | N/A |
| | <ul style="list-style-type: none"> ➤ Standby Pump head. | N/A | As above | N/A |
| | <ul style="list-style-type: none"> ➤ Auto Starting / Manual Stopping. | N/A | As above | N/A |
| | <ul style="list-style-type: none"> ➤ Access to pump house | N/A | As above | N/A |
| | <ul style="list-style-type: none"> Terrace Level | Provided & Maintained by Ambience Mall | | |
| | <ul style="list-style-type: none"> ➤ Discharge of pump. | 450 LPM | As above | MR |
| | <ul style="list-style-type: none"> ➤ Head of pump. | 40m | As above | MR |
| | <ul style="list-style-type: none"> ➤ Power supply. | Required | As above | MR |
| | <ul style="list-style-type: none"> ➤ Auto starting of pump. | Required | As above | MR |
| 14. | Captive water storage for Fire Fighting. | Provided & Maintained by Ambience Mall | | |
| | <ul style="list-style-type: none"> Underground tank capacity. | N/A | As above | N/A |
| | <ul style="list-style-type: none"> ➤ Draw-off connection. | N/A | As above | N/A |
| | <ul style="list-style-type: none"> ➤ Fire Service Inlet. | N/A | As above | N/A |
| | <ul style="list-style-type: none"> ➤ Access to tank. | N/A | As above | N/A |
| | <ul style="list-style-type: none"> Overhead tank capacity. | 5,000 Ltr | As above | MR |
| 15. | Exit Signage. | Required | Provided | MR |
| 16. | Provision of Lifts. | Provided & Maintained by Ambience Mall | | |
| | <ul style="list-style-type: none"> Pressurization of lift shaft. | N/A | N/A | N/A |
| | <ul style="list-style-type: none"> Pressurization of lift lobby. | N/A | N/A | N/A |
| | <ul style="list-style-type: none"> Communication in lift car. | N/A | N/A | N/A |
| | <ul style="list-style-type: none"> Fireman's switch. | N/A | N/A | N/A |
| | <ul style="list-style-type: none"> Lift signage. | N/A | N/A | N/A |
| 17 | Standby Power Supply | Required | Provided (DG Set) | MR |
| 18. | Refuge Area | | | |
| | <ul style="list-style-type: none"> Total area | N/A | N/A | N/A |
| | <ul style="list-style-type: none"> Location | N/A | N/A | N/A |

Renewal

M/s Chili's Restaurant, Ambience Mall, Vasant Kunj

| 19. | Fire Control Room. | Provided & Maintained by Ambience Mall | | |
|-----|---|--|----------|-----|
| | • Detector System Panel. | N/A | As above | N/A |
| | • Flow Switch Panel. | N/A | As above | N/A |
| | • PA system Panel. | N/A | As above | N/A |
| | • Battery backup | N/A | As above | N/A |
| | • Building floor plan | N/A | As above | N/A |
| 20. | Special Fire Protection System for the Protection of special Risk, if any : | N/A | As above | N/A |

The Fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/EH/2014/SZ/281 Dated 28/02/2014, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

R.N. Singh
16/03/17

Signature of the Inspecting Officer
Name : R.N. Singh
Designation: ADO

Renewal

M/s Chili's Restaurant, Ambience Mall, Vasant Kunj

Div. Officer (SD)

Anilash
17/3/17

Dy. CPO (SD) re attach. Ambience FSC.

R.N. Singh

20/3

(F.A.S.)

D.O. (SD)
Anilash
20/3/17

ADP
RMS

Sir.

FSC of Ambience mall placed on e-18 folio

00/SD
Anilash
21/3/17

R.N. Singh
21/3

