GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI-110001

No.F6/DFS/MS/GH/2017 / 102 / 540

Dated 13/09/17

FIRE SAFETY CERTIFICATE

Certified that the Check In by **ORAN**" -A Unit of Shree Ved Consultancy LLp located at 104, Babar Road New Delhi comprised of basement, ground plus three upper floors (Basement floor main hall + 04 office rooms, ground floor reception + lobby+ 08 guest rooms, Ist floor to 3rd floor 11 guest rooms at each floor total 41 guest rooms) was granted FSC by this department vide letter No. F6/MS/DFS/GH/2015/NDZ/2044 dated 13/11/15. The premises was re- inspected by the officer concerned of this department on 24/03/2017 in the presence of Sh. Rajeev Sharma and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and that the premises is fit for occupancy class Residential Group A-1 for 41 guest rooms only as above with effect from ...|3..o.5.(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o.5.)(.o

(Vipin Kental) Chief Fire Officer

Copy to:-

3.

2)Licensee, Check In by ORAN" -A Unit of Shree Ved Consultancy LLp located at 104, Babar Road New Delhi

CONDITIONS

- 1. All the means of escape shall be kept free of all the type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.3
 - All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 5. This Fire Safety Certificate can not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 6. All comments/ directions of the Licensing Department shall always be permitted and followed.
- 7. The owner /occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form' J'[sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry"
- 8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

-4/19-

INSPECTION REPORT

1.Name & address of the building:- Check In by Oran (A Unit of Shree Ved Consultancy LLP), located at 104, Babar Road,

New Delhi.

2. Type of occupancy:- Residential Group A-1 Basement, Ground +

3 Upper Floors (Total 41 Guest Rooms)

3. Type of case:- Renewal

4. Details of previous FSC :- No. F6/DFS/MS/GH/2015/NDZ/2044 dated 13/11/2015.

5. Fire safety directives No.- N/A

6. Date of inspection: 24.03.2017

7. Name of the inspecting officer:- Dy.CFO Sunil Chowdhary, D.O. Gurmukh

Singh & A.D.O. Manoj Kumar Sharma

8. Name & designation of officer From the building side:-

Mr. Rajeev Sharma

9. Year of construction:- 2010

10. Applicant's letter No:- Nil- dated 09/03/17

				Old Case	
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement	Provided at site	Remarks MR/NMR	
1.	Access to Building				
	1) Road width	N/A	6 mtrs.	MR	
	2) Gate width	N/A	N/A	N/A	
	3)Width of internal road	NA	NA	NA	
2.	Number, Width Type & Arran	gement of Exits			
	A. Number of staircases				
	1. Upper floors	02 No	02 No.	MR	
	2. Basements	02 No.	02 No.	MR	
	B. Width of staircase				
	1. Upper floors	125 cms	110 cms & 140 cms.	MR	
	2. Basements	125 cms.	110 cms& 140 cms.	MR	
	C. Protection of exits				
	1. Fire check door	Required in basement	Provided	MR	
	2. Pressurization	N/A	N/A	N/A	
	D. No. of continuous staircase to terrace	N/A	N/A	N/A	
	E. Width of corridor	N/A	N/A	N/A	
	F. Door size	1 Mtr.	1 Mtr.	MR	
3.	Compartmentation				
	1) Fire check door	Required	Provided in basement	MR	
	2) Sealing of electrical shafts	N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A	
	5) Fire Dampers	N/A	N/A	N/A	

< A/20-

4.	Smoke Management System					
	1) Basements	30 ACPH	Exhaust fan	MR		
	2) Upper floors	12 ACPH	Natural	MR		
5.	Fire Extinguishers					
J.	1) Total numbers	14 Nos.	14 Nos.	MR		
	2) Types	ABC & CO2	ABC, CO2 &	MR		
	3) ISI marking	Required	Provided	MR		
6.	First-Aid Hose Reel		*			
0.	1)Total number of each floor	01 no.	01 no.	MR		
	2) Length of hose reel hose	30 Mtr.	30 Mtr.	MR		
	3) Nozzle diameter	5 mm	5 mm	MR		
7.	Automatic Fire Detection & Alarming System					
1.	1) Type of detectors	N/A	N/A	N/A		
	2) Location of main panel	N/A	N/A	N/A		
	3) Location of repeater panel	N/A	N/A	N/A		
	4) Alternate source of power	N/A	N/A	N/A		
	5) Hooter's Location	N/A	N/A	N/A		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	Required	Provided	MR		
9.	/Intercom	required	=,20,100,00			
10.	Automatic Sprinkler System					
10.	1) Basement	Required	Provided	MR		
	2) Upper floors	N/A	N/A	N/A		
	3) Sprinkler above false	N/A	N/A	N/A		
		IV/A	11/21	17712		
11.	ceiling Internal Hydrants					
11.	1) Size of riser/down-comer	100 mm	100mm	MR		
		01 no.	01 no.	MR		
	2) Number of hydrants per floor	OT HO.	or no.	11111		
		01 nos.	01 nos.	MR		
10	3) Hose box	01 1105.	01 1103.	IVIIC		
12.	Yard Hydrants	N/A	N/A	N/A		
	1) Total number of hydrants	N/A	N/A	N/A		
	2) Hose box	IN/A	IN/A	14/11		
13.	Pumping Arrangement	DT/A	NI/A	N/A		
	1) Ground level	N/A	N/A	N/A		
	a) Discharge of main	N/A	N/A	IN/A		
	pump	DT/A	NI/A	N/A		
	b) Head of main pump	N/A	N/A			
	c) Number of main pum		N/A	N/A		
	d) Jockey pump out put	N/A	N/A	N/A		
	e) Jockey pump head	N/A	N/A	N/A		
	f) Stand by pump outpu		N/A	N/A		
	g) Stand by pump head	N/A	N/A %	N/A		
	h) Auto starting/Manual	N/A	N/A	N/A		
	stopping					
	2) Terrace level	A		3.00		
	a) Discharge of pump	900 LPM &180	900 LPM &	MR		

hai

		LPM	180LPM	
	b) Head of pump	40 Mtr.	40 Mtr.	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
14.	Captive Water Storage for Fire		Tiovided	IVIIX
	Under ground tank capacity	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	10,000 Ltr.	10,000 ltrs.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System any:	for Protection of s	special Risk, if	N/A

The fire protection system provided in the guest house were tested, checked at random and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and safety measures as required under the rules the FSC issued vide letter No.F6/DFS/MS/GH/2015/NDZ/2044 dated 13/11/2015, renewal under Rule 35 of the Delhi Fire Service rules 2010, is recommended

Sunil Chowdhary Dy. Chief Fire Officer Gurmukh Singh Divisional Officer

Manoj Kumar Sharma Assistant Divisional Officer

273/CG-MOZ C.F. J. 13/4/17

Miscell Film.
Weight

F.t. is but up for signature, bleast