GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2017/SZ / 1068

FIRE SAFETY CERTIFICATE

Dated: 26/4/17

Certified that the **Great Mary Public School**, RZ-53, Mahendra Park, Pankha Road, (Opp. A/2 Janak Puri), New Delhi-110059 comprised of ground plus one upper floor in a three storied building having total 11 rooms (Including Class Rooms, Office, Comp. Room, Hall & Store etc.) owned/occupied by Great Mary Public School was issued Fire Safety Certificate by this department vide letter No F6/DFS/MS/School/2013/SZ/1036 dated 07.10.2013. The school building was re- inspected by the officer concerned of this department on 28.03.2017 in the presence of Smt. Reena (Teacher) and found five rooms on second floor has been constructed for residential and storage purpose only. The Great Mary Public School have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises (Ground plus one upper floor only) is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

(VIPIN KENTAL)
CHIEF FIRE OFFICER

Copy to:-

- The Principal, Great Mary Public School, RZ-53, Mahendra Park, Pankha Road, (Opp. A/2 Janak Puri), New Delhi-110059
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

1.78		INSPECTION	REPORT	instanting storf			
1.	Name	& address of the building: Great Mary Publ	ic School, RZ-53, M	ahendra Park, Pan	kha Road, (Opp.		
1.	. 1 (01110		New Delhi-110059				
2.	. Type o	f Occupancy : Educational		(
	. Type o	f Case : Renewal					
4.	. Details	of Previous NOC : F6/DFS/MS/Sc	hool/2013/SZ/1036	dated 07.10.2013			
Sec. 1		fety directives letter No : Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011					
		f inspection : 28.03.2017	D 1				
7.	. Name	of Inspecting Officer : A.D.O. Sandee	p Duggal				
8.		and designation of officers	achar)				
		the building side : Smt. Reena (Te	eacher)				
			od 08 03 2017				
S. No.		ant's letter No. : GM/03/17 date nimum Standards on fire prevention and	Requirement	Provided at	Remarks		
5. INO.		safety U/R 33	as per FSC dt. 07.10.2013	site	MR/NMR		
1.	Acc	ess to building					
		Road width	Accessible	05 mtrs	M/R, being old case		
		Gate width	N/A	N/A	N/A N/A		
		Width of internal road	N/A	N/A	IV/A		
2.	Nu	mber, Width, Type & Arrangement of Exit	S				
	a.]	Number of staircases		0237) (T		
		Upper Floors	02 No.'s	02 No.'s	MR		
		• Basements	N/A	N/A	N/A		
	b.	Width of staircases		The state of the state of	* *		
		Upper Floor	150 cms/additional	112 & 97 cms	MR		
*	4.7	• Basements	staircase of 75 cms		A 1974 374		
	10		if less than 150 cms	DI/A	NI/A		
	c.	Protection of exits	N/A	N/A	N/A		
		• Fire check door					
		Pressurization	N/A	N/A	N/A		
	1	No. of continuous staireasses to	N/A	N/A	N/A		
	d.	No. of continuous staircases to terrace	1	-0E 13 11			
	e.	Width of Corridor	Required	One	MR		
	f.	Door Size	150 cms	150 & 240 cms	MR		
	1.	Door Size					
			Old case	85 cms	M/R, being old case		
3.	Co	mpartmentation					
- 4		Fire check door	N/A	N/A	N/A		
		Sealing of electrical shafts	N/A	N/A	N/A		
		Fire Rating of shaft door	N/A	N/A	N/A		
		Water Curtain	The state of the s	N/A	N/A		
		Fire Dampers	N/A N/A	N/A N/A	N/A N/A		
4.	Sn	oke Management System	N/A	IN/A	IVA		
			N/A	N/A	N/A		
	1	Basement Upper floors	Required	Natural	MR		
		Upper floors	Roquitou	ventilation			
5.	Fi	re Extinguishers					
		Total numbers	05 no's	Provided	MR		
		• Types	ABC type	Provided	MR		
		• IS marking	ISI marked	Provided	MR		
6.	Fi	rst-Aid Hose Reels					
- Alexander		Total numbers on each floor	N/A	N/A	N/A		
t and		Length of hose reel hose	N/A	N/A	N/A		
400		Nozzle diameter	N/A	N/A	N/A		

1.	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel			
		N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	Provided	N/A
10.	Automatic Sprinkler System Basement	N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants	IN/A	IN/A	IN/A
	Size of riser/down-comer	N/A	N/A	N/A
	Number of hydrants per floor	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants		141 141 141 141	
	Total number of hydrants	N/A	N/A	N/A
4 1	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			
	Ground Level	*/		
E.S. 9-8	Discharge of main Pump	N/A	N/A	N/A
	➤ Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	> Jockey Pump out put	N/A	N/A	N/A
	> Jockey pump head			
	> Standby Pump out put	N/A	N/A	N/A
	> Standby Pump Head	N/A	N/A	N/A
-	Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
	Pump House Access	N/A	N/A	N/A
	Terrace level		Secretary States	
	> Discharge of pump	N/A	N/A	N/A
	> Head of the pump	N/A	N/A	N/A
	Power SupplyAuto Starting of pump	N/A	N/A	N/A
7.5	7 Auto Starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for fire fighting			
7-1				
	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
-17-3	Fire service inlet	N/A	N/A ·	N/A
	Access to tank	N/A	N/A	-N/A
	Overhead Tank capacity	N/A	N/A	N/A
		N/A	N/A	N/A
15.	Exit Signage.			
16.	Provision of Lifts.	(No Lift)		
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car Figure 2. Convention Societals	N/A	N/A	N/A
	• Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
17.	Standby power suppry	11//1		
18.	Refuge Area			
	The band of the ba		Company of the	
	> Total Area	N/A	N/A	N/A
	> Total Area > Location	N/A N/A	N/A N/A	N/A N/A

19.	Fire Control Room	The state of the s		
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection System for Prote of special Risks, if any:	ction N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F6/DFS/MS/School/2013/SZ/1036 dated 07.10.2013 renewal in accordance with the Circular No. F. 16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Note:- As per the letter submitted by the Principal the school is running at ground floor plus one upper floor in a three storied building and five rooms on second floor is being used for residential and storage purpose only and there are less than 45 students in each class room (placed at C-19).

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation: - Asstt. Divisional Officer

D.O. (South West)

Cfo & P m. scell F7 60.

F.T. letter is put up for signature plean.