GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/EH/2017/SZ/ 1069

Dated: 26/4/17

FIRE SAFETY CERTIFICATE

Certified that the **M/s Om Sweets Pvt. Ltd.,** GL-23, Shaheed Bhagat Singh Marg, Jail Road, Hari Nagar, New Delhi-110064 the building comprised of Basement, ground floor plus three upper floors, but restaurant is running at First floor only. The restaurant was issued FSC by this department vide letter no. F.6/DFS/MS/EH/2013/SZ/937 dated 20.09.13 owned/occupied by M/s Om Sweets Pvt. Ltd. The building was re-inspected by the officers concerned of this department on 23.03.2017 in presence of Sh. Ajim Khan (Unit Manager) and found that the management have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi fire service Rules 2010 and that the building/premises (**First floor only**) is fit for occupancy class Group D "Assembly Building" w.e.f the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on 26/4/19 at New Delhi.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to: -

The Manager,
 M/s Om Sweets Pvt. Ltd., GL-23,
 Shaheed Bhagat Singh Marg, Jail Road,
 Hari Nagar, New Delhi-110064

The Dy. Health Officer,
 South Delhi Municipal Corporation,
 West Zone, Rajouri Garden, New Delhi-110027

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Building is comprised of basement, ground plus three upper floors but restaurant is running at first floor only. INSPECTION REPORT M/s Om Sweets Pvt. Ltd., GL-23, Shaheed Bhagat Singh Marg, Jail Name & address of the building: Road, Hari Nagar, New Delhi-110064 Group D (Assembly Building) 2. Type of Occupancy Renewal Type of Case 3. F.6/DFS/MS/EH/2013/SZ/937 dated 20.09.13 Details of Previous NOC 4. N/A Fire Safety directives letter No 23.03.2017 Date of inspection 6. D.O. M.K. Chattopadhyay & A.D.O. Sandeep Duggal Name of Inspecting Officer 7. Name and designation of officers : Sh. Ajim Khan (Unit Manager) From the building side 2009-10 Year of Construction : Nil dated 10.02.2017 10. Applicant's letter No. Building is comprised of basement (store), ground floor (sweet shop), First floor (restaurant), second floor (kitchen), third floor (store) & terrace (two rooms sealed). Provided at Remarks Requirement as Minimum Standards on fire prevention and fire S. MR/NMR per FSC dt. site safety U/R 33 No. 20.09.13 Access to building 1. MR 12 mtrs 09 mtrs Road width Provided MR 4.5 mtrs Gate width N/A N/A N/A Width of internal road Number, Width, Type & Arrangement of Exits 2. a. Number of staircases MR 02 No.'s 02 No.'s Upper Floors 02 No.'s MR Basements 02 No.'s b. Width of staircases 150 to 111 cms & MR Two staircases Upper Floor 85 cms MR 130 cms & 85 cms Basements Two staircases c. Protection of exits MR Provided Required Fire check door N/A N/A N/A Pressurization d. No. of continuous staircases to MR Required One terrace Width of Corridor MR 160 cms 150 cms MR 92 & 115 cms Two exits Door Size Compartmentation 3. MR Provided Required Fire check door N/A N/A Sealing of electrical shafts N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A **Smoke Management System** 4. MR Exhaust fans Required Basements are provided MR Natural Required Upper floors Ventilation Fire Extinguishers 5. MR 03 No.'s/floor Provided Total numbers ABC/CO₂ Provided MR Types ISI marked MR ISI marked IS marking First-Aid Hose Reels 6. MR Provided

	Type of detectors	Smoke	Provided	MK			
lik gradit	Location of Main Panel	Required	G. Floor	MR			
	Location of Repeater Panel	N/A	N/A	N/A			
	Alternate source of power	Required	Provided	MR			
	Hooters' Location	Required	Provided Near exit	MR			
8.	MOEFA	Required	Provided	MR			
9.	Public Address System	Required	Provided	MR			
10.	Automatic Sprinkler System						
	Basement	Required	Provided	MR			
	Ground Floor	Required	Provided	MR			
	Sprinkler above false ceiling	Required	Provided	MR			
11.	Internal Hydrants						
	Size of riser/down-comer	100 mm One	Provided Provided	MR MR			
	Number of hydrants	One	Provided	MR			
	Hose Box	Offe	Tiovided	IVIIC			
12.	Yard Hydrants	N/A	N/A	N/A			
	Total number of hydrants	N/A N/A	N/A	N/A			
1	Hose Box	IN/A	IV/A				
13.	Pumping Arrangements						
	Ground LevelDischarge of main Pump	1620 LPM	Provided	MR			
*	Head of Main pump	70 mtrs	Provided	MR			
	Number of main pumps		Provided	MR			
	> Jockey Pump out put	One	The second secon				
	Jockey pump head	180 LPM	Provided	MR			
	Standby Pump out put	40 mtrs	Provided	MR			
	Standby Pump Head	1620 LPM	Provided	MR			
	Water Curtain Pump	70 mtrs	Provided	MR			
	> Auto Starting/Manual Stopping	N/A	N/A	N/A			
	Auto Starting/Manual Stopping	Required	Provided	MR			
	A Company of the Comp	Required	Provided	MR			
	Pump House AccessTerrace level						
	Terrace levelDischarge of pump	900 LPM	Provided	MR			
	> Head of the pump	40 mtrs	Provided	MR			
	> Power Supply	Required	Provided	MR			
	> Auto Starting of pump	Required	Provided	MR			
14.	Captive Water Storage for fire fighting						
	Underground tank capacity	70000 Ltrs	Provided	MR			
2	> Draw-off connection	Required	Provided	MR			
	> Fire service inlet	Required	Provided	MR			
	> Access to tank	Required	Provided	MR			
	Overhead Tank capacity	10000 ltrs	Provided	MR			
15.	Exit Signage.	Required	Provided	MR			
16.	Provision of Lifts.	(Lift is not in use)					
	Pressurization of Lift Shaft	N/A	N/A	N/A			
: 65	Pressurization of Lift lobby	N/A	N/A	N/A			
A CHILL	Communication In lift Car	N/A	N/A	N/A			
	Fireman's Grounding Switch	N/A	N/A	N/A			
	Lift Signage	N/A	N/A	N/A			
17.	Standby power supply	Required	Provided	MR			
			- Jackson 24	Z .			
18.	Refuge Area.		NI/A	N/A			
1.	> Total Area	N/A	N/A				
	> Location	NI/A	N/A	N/A			

19.	Fire (Control Room			
	•	Detector System Panel	N/A	N/A	N/A
	•	PA System Panel	N/A	N/A	N/A
			N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A	
	4		N/A	N/A	N/A
20.		al Fire Protection System for Protection of Il Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The shortcomings issued vide letter number F.6/DFS/MS/EH/2017/SZ/305 dated 03.02.2017 has been complied.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/EH/2013/SZ/937 dated 20.09.13, renewal under rule 37 of the Delhi Fire Service rules 2010 is recommended.

Signature of Inspecting Officer Name: - M.K. Chattopadhyay Designation: - Divisional Officer

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

Dy. C.F.O.(South Zone)

FIPO?

M. Scell Very

My

F. T. letter in put up for signature, please.

Sandeeff

M. SCELL WZ574