GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/GH/2017/ NO2/373

Dated: 91/4//7

FIRE SAFETY CERTIFICATE

Certified that the The Pearl Guest House, 8721/1, Desh Bandhu Gupta Road, Pahar Ganj, New Delhi comprised of Basement, Ground, Mezzanine + 4 Upper Floors, Basement, 03 halls, Ground floor reception + Still Parking, Mezzanine floor 06 guest rooms, 1st floor to 3rd floor 08 guest rooms at each floor, 4th floor staff kitchen and sitting area total 30 guest rooms was granted FSC by this department vide letter No.F6/DFS/MS/GH/2014/NDZ/491 dated 17/04/14. The premises was re-inspected by the officer concerned of this department on 07/04/17 in the presence of Mr. Rajesh (Manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of class Residential Group -A-1' for total 30 guest rooms only as above with effect from 2/-/-4-7/-7 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi

(Vipin Kental) Chief Fire Officer Delhi Fire Service Ph: - 011-23412225

Copy to:-

1. The Joint. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi

The Licensee, The Pearl Guest House. 8721/1, Desh Bandhu Gupta Road, Pahar Gani, New Delhi.

Conditions:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. The means of escape shall be kept unobstructed / unlocked & remain available for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT

1. Name & address of the building:-

The Pearl Guest House,8721/1,Desh Bandhu

Gupta Road, Pahar Ganj, New Delhi. Residential Group A-1 bas., Ground + 4 upper

2. Type of occupancy:-

Floor (30 guest rooms) Basement – 03 halls, ground floor – reception + stilt parking, mezzanine floor – 06 guest rooms, 1st to 3rd floor 08 guest rooms at each floor & 4th floor staff kitchen & sitting area.

3. Type of case:-

Renewal.

4. Details of previous FSC:-

F6/DFS/MS/GH/2014/NDZ/491

dated 17/04/14

5. Fire safety directives No.-

N/A

6. Date of inspection:-

07/04/17

7. Name of the inspecting officer:-

D.O. Gurmukh Singh.

8. Name & designation of officer From the building side:-

Mr. Rajesh (Manager).

9. Year of construction:-

2010.

10. Applicant's letter No:-

611/ Joint. C.P/Lic. (H) dated 06/03/17

S.No.	Minimum Standards on fire	Requirement/	Provided at site	Remarks	
	Prevention and fire safety	Existing fire	*	MR/NMR	
	U/R 33	safety			
- X	١	measures			
1.	Access to Building	THE YOUR			
3×1	1) Road width	N/A	14 mtr.	N/A	
	2) Gate width	N/A	N/A	N/A	
	3)Width of internal road	N/A	N/A	N/A	
2.	Number, Width Type & Arrangement of Exits				
	A. Number of staircases		.,		
	1. Upper floors	01 No.	01 No.	MR	
	2. Basements	02 Nos.	02 Nos.	MR	
	B. Width of staircase				
	1. Upper floors	125 cms.	140 cms.	MR	
	2. Basements	125 cms.	120 & 140 cms.	MR	
	C. Protection of exits		77		
	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A	
	D. No. of continuous	N/A	N/A	N/A	
	staircase to terrace			1.17	
	E. Width of corridor	N/A	N/A	N/A	
	F. Door size	1 mtr.	1 mtr.	MR	
3.	Compartmentation				
	1) Fire check door	N/A	N/A	N/A	
	2) Sealing of electrical shafts	N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A	

	E E D	DI/A	27/4	
1	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System	00 1 00777		
	1) Basements	30 ACPH	Mechanical	MR
_	2) Upper floors	12 ACPH	Natural	MR
5.	Fire Extinguishers			
	1) Total numbers	16Nos.	20 Nos.	MR
F 14 14 14	2) Types	ABC & CO2		MR
1 1 1 1	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel	Sit Maria		
	1)Total number at each floor	01 no.	01 no.	MR
	2) Length of hose reel hose	30 mtr.	Provided	MR
	3) Nozzle diameter	5 mm.	Provided	MR
7.	Automatic Fire Detection & A			IVIIC
	1) Type of detectors	N/A	N/A	N/A
	2) Location of main panel	N/A	N/A	N/A
H.	3) Location of repeater panel	N/A	N/A	N/A
(40)	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A N/A	N/A N/A
8.	MOEFA	Required	Provided Provided	MR
9.				
10.	Public Address System	Required	provided	MR
10.	Automatic Sprinkler System 1) Basement	D	D 111	100
- Y		Required	Provided	MR
	2) Upper floors	N/A	N/A	N/A
-	3) Sprinkler above false	N/A	N/A	N/A
1.1	ceiling			
11.	Internal Hydrants	127/		
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor			
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants			
1.75	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump			
	' b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump		N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output		N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	N/A
	stopping	11//1	IVA	IV/A
	2) Terrace level			
		450 LPM	450 LPM	MR
	a) Discharge of pump	430 LPW	430 LPIVI	IVIK

	b) Head of pump	30 Mtr.	30 Mtr.	MR	
	' c) Power supply	Required	Provided	MR	
4	d) Auto starting of pump	Required	Provided	MR	
14.	Captive Water Storage for Fire Fighting				
	1) Under ground tank capacity	N/A	N/A	N/A	
	a) Draw-off connection	N/A	N/A	N/A	
	b) Fire service inlet	N/A	N/A	N/A	
	, c) Access to tank	N/A	N/A	N/A	
	d) Over head tank capacity	15,000 ltrs.	Provided	MR	
15.	Exit Signage.	Required	Provided	MR	
16.	Provision of Lifts.				
	a) Pressurization of lift shaft	N/A	N/A	N/A	
	b) Pressurization of lift lobby	N/A	N/A	N/A	
	c) Communication in lift car	N/A	N/A	N/A	
	d) Fireman's switch	N/A	N/A	N/A	
	e) Lift signage	N/A	N/A	N/A	
17.	Stand by Power Supply	Required	Provided	MR	
18.	Refuge Area	N/A	N/A	N/A	
	Total area location	N/A	N/A	N/A	
19.	Fire Control Room	N/A	N/A	N/A	
	a) Detector system panel	N/A	N/A	N/A	
	b) Flow switch panel	N/A	N/A	N/A	
	c) PA system panel	N/A	N/A	N/A	
	, d) Battery backup	N/A	N/A	N/A	
	e) Building floor plan	N/A	N/A	N/A	
20.	0. Special Fire Protection System for Protection of special Risk, if any:				

The fire protection system provided in the guest house were tested, checked at random and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F6/DFS/MS/GH/2014/NDZ/491 dated 17/04/2014, renewal under Rule 35 of the Delhi Fire Service rules 2010, is recommended.

Divisional Officer