GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001 Fax No. 011-23412593, Ph. 011-23412225

No. F6/DFS/MS/EH/2017/SZ/ 63 6

Dated: 4/5./.1.7...

FIRE SAFETY CERTIFICATE

Certified that the M/S Swagath Restaurant, (A Unit of Red Chilly Foods Pvt. Ltd.) located at M-9,1st & 2nd floor, G.K-II, New Delhi, comprised of Basement, Ground plus two upper floors (Restt. is running at 1st and 2nd floor of the building) was granted FSC by this department vide letter No.F6/DFS/MS/EH/2013/SZ/539 dated 09/07/2013. The premises was re-inspected by the officer concerned of this department on 27/04/2017 in the presence of Mr. Ghanshyam (Manager) of the restaurant and observed that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class-D "Assembly Building" (Restaurant) as above with effect from 4/1/2 for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 4/5/17 at New Delhi by

(Vipin Kental) Chief Fire Officer

014

Copy to: -

CH M

1. M/S Swagath Restaurant, located at M-9,1st & 2nd floor, G.K-II, New Delhi

2. The DHO (Central Zone), South MCD, Health Deptt, Lajpat Nagar, New Delhi-24

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety and means of escape facilities shall be maintained in good working condition at all time. Any lapse rendering the fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
- 2. Building Sanctioning authority may verify any deviation with regard to construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null & void.
- The staff shall be trained for operating fire fighting system and mock evacuation drill be conducted at regular interval and record be maintained.
- 4. The basement shall be used strictly as per the provisions of Building Bye Laws.
- 5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in.
- 6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

			1113			
-		INSPEC	TION REPORT			
	l Nan	ne & Address of the Building	Foods Pvt ltd.	M/s Swagat Restaurant 9(A Unit of Red Chilly Foods Pvt ltd.),M-9,1 st & 2 nd Floor, G.KII, New Delhi-		
2	2 Typ	e of Occupancy				
	1 21	ding comprised of	Group-D Assembly Building. (Restaurant)			
4		e of Case	Basement, Ground + 2 upper floors.			
5		ils of Previous NOC	Renewal			
6		Safety Directives Letter No	No.F6/DFS/MS/EH/2013/SZ/539 Dated 09-07-2013 Nil			
7		of Inspection	27/04/2017			
8		ne of the Inspecting Officers				
	Nam	ne & Designation of Officers	ADO R.N. Singh			
and department	from	the building side	Mr. Ghanshyam (Manager) Nil Restt running at first & second floor			
10) Year	of construction				
11		licant letter No.	g Second Hoor			
S.	Min	imum standards on Fire Prevention	Nil Dated 10/04/2017			
No		Fire Safety U/R 33	As Per Old NOC – 2013	Provided at Site	Remarks	
1		ss to Building.	NOC - 2013		MR/NMR	
			Accessible			
				9 mtr	MR	
			N/A	N/A	N/A	
2	Num	ber, width, type & arrangement of exits	N/A	N/A	N/A	
	a. N	lumber of Staircase				
	•		Tr.			
		Basement floor	Two	Two	MR	
	b. V	Vidth of Staircase	N/A	N/A	N/A	
		Upper floors	Required	0.95m & 0.67m	MR	
		Basement floor	N/A	N/A	N/A	
	c. P	rotection of exits		14/11	IN/A	
	•		N/A	DI/A	77/1	
		Pressurization	N/A	N/A	N/A	
	d. N	o. of continuous staircase to terrace		N/A	N/A	
	e. W	idth of corridor	N/A N/A	Provided one	MR	
		oor size		N/A	N/A	
3	Compartmentation.		02 no's	1 mtr & 0.93 mtr	MR	
		Fire check door.	N/A	27/4		
		Sealing of electrical shafts.	N/A	N/A	N/A	
		Fire rating of shaft door.	N/A	N/A	N/A	
		Water curtain	N/A N/A	N/A	N/A	
		Fire dampers.	N/A N/A	N/A	N/A	
4.	Smok	e Management system.	IN/A	N/A	N/A	
	•	Basement System.	20 -/- 1			
		Upper floors	30 a/c per hour	N/A	N/A	
5.	Fire F	xtinguishers.	12 a/c per hour	Provided	MR	
	•	Total numbers	8 No. 3 12			
		Types	ISI marked	08 No's	MR	
		ISI Marking	151 marked	ABC- 08	MR	
6.	First A	Aid Hose Reels.		Provided	MR	
	•		01	D		
		Total numbers on each floor.	01 no	Provided	MR	
		Length of hose-reel hose.	30 m	Provided >	MR	
	•	Nozzle Diameter	5 mm	Provided	MR	

NIIY

7	Automatic fire detection & alarming system.			
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	 Alternate source of power 	N/A	N/A	N/A
	Hooter's location	N/A	N/A	N/A
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			The second second
	Basement	N/A	N/A	N/A
	Upper floors	Required	Provided	M/R
	 Sprinkler above false ceiling 	N/A	N/A	N/A
11.	Internal Hydrants.	- 12 12 12 12 12 12 12 12 12 12 12 12 12		
	Size of Riser/Down-comer	100mm	Provided	MR
	Number of Hydrant per floor	01no	Provided	MR
	Hose box.	01no	Provided	MR
12.	Yard Hydrants.			
	Total number of hydrants.	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
13.	Pumping arrangements.	1		
	Ground Level	2		
	Discharge of main pump.	N/A	N/A	N/A
	Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.	N/A	N/A	N/A
	Jockey Pump head.	N/A	N/A	N/A
	Standby Pump output.	N/A	N/A	N/A
	Standby Pump head.	N/A	N/A	N/A
	Auto Starting / Manual Stopping.	N/A	N/A	N/A
	Terrace Level			
	Discharge of pump.	450 Lpm	450 LPM	MR
	Head of pump.	40 mtr	35 mtr	MR
	Power supply.	Required	Provided	MR
	Auto starting of pump.	N/A	N/A	N/A
14.	Captive water storage for Fire Fighting.		1 - 1 - 1	
	Underground tank capacity.	N/A	N/A	N/A
	Draw-off connection.	N/A	N/A	N/A
	> Fire Service Inlet.	N/A	N/A	N/A
	Access to tank.	N/A	N/A	N/A
	Overhead tank capacity.	5,000 Ltr	5,000 Ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	Pressurization of lift shaft.	N/A	N/A	N/A
	Pressurization of lift lobby.	N/A	N/A	N/A
	Communication in lift car.	N/A	N/A	N/A
	Fireman's switch.	N/A	N/A	N/A
	Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided	MR
18.	Refuge Area			
	Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A

NIIS Fire Control Room. N/A N/A N/A Detector System Panel. N/A N/A N/A Flow Switch Panel. N/A N/A N/A PA system Panel. N/A N/A N/A Battery backup N/A N/A N/A Building floor plan Special Fire Protection System for the Protection of special Risk, if any: N/A

The Fire protection systems provided in the building were checked randomly and found functional at the time of inspection.

The shortcoming issued by this department vide letter No. F6/DFS/MS/EH/2016/SZ/2237 dated 20/9/2016 has been rectified fully.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F6/DFS/MS/EH/ 2013/SZ/539 dated 09-07-2013, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

: R.N. Singh Designation: ADO

Div. Officer (SD)

m·s dell FT m·

cro/sf
Miscell UKTS.